Facility	Category	Finding	Recommendation	Estimated Cost	Code Reference
Aunt Julia Ann's Road - 54 Aunt Julia Ann's Road West Dennis, MA 02670	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
Aunt Julia Ann's Road - 54 Aunt Julia Ann's Road West Dennis, MA 02670	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-accessible. The parking lot can	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Aunt Julia Ann's Road - 54 Aunt Julia Ann's Road West Dennis, MA 02670	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Aunt Julia Ann's Road - 54 Aunt Julia Ann's Road West Dennis, MA 02670	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Aunt Julia Ann's Road - 54 Aunt Julia Ann's Road West Dennis, MA 02670	Fishing Piers	Pier/Platform walking surface is not compliant.	Provide compliant walking surface with recommended value at the pier/platform.		
Aunt Julia Ann's Road - 54 Aunt Julia Ann's Road West Dennis, MA 02670	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3

Aunt Julia Ann's Road - 54 Aunt Julia Ann's Road West Dennis, MA 02670	Fishing Piers	Railing height at the fishing station is not compliant.	Provide compliant railing height at the fishing station.		ADA 1005.2.1
Baker - 4, 12 & 14 Baker Way West Dennis, MA 02670	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Baker - 4, 12 & 14 Baker Way West Dennis, MA 02670	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Parking	The access aisle markings are faded, damaged, or otherwise not viewable.	Re-stripe the access aisle so as to discourage parking.	$250.00	ADA 502.3, 502.3.3

Bass River Park - 40 Old Main Street West Dennis, MA 02670	Path of Travel	There is no edge protection at the drop off.	Install edge protection on the walking surface at the required minimum height.	$1,088.00	ADA 303.5
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Path of Travel	There is no edge protection at the drop off.	Install edge protection on the walking surface at the required minimum height.	$1,088.00	ADA 303.5
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9

Bass River Park - 40 Old Main Street West Dennis, MA 02670	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Path of Travel	The surface of the primary accessible path of travel is rough and uneven, providing a hazardous surface for individuals with mobility impairments	Resurface the path of travel to provide a smooth, firm, stable and slip-resistant surface.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Path of Travel	There is no edge protection at the drop off.	Install edge protection on the walking surface at the required minimum height.	$1,088.00	ADA 303.5
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Picnic Areas	The slope of the clear floor space at the table is not compliant.	Provide compliant clear floor space at the table.	$1,840.00	ADA 305.3, 902.2
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902

Bass River Park - 40 Old Main Street West Dennis, MA 02670	Reach Ranges	Element reach depth is not compliant.	Make sure that the element is within allowed reach range with recommended reach depth.	$550.00	ADA 308
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Benches	Clear floor space slope is not compliant for the bench.	Provide compliant clear floor space at the bench.	$1,840.00	ADA 305, 903.2
Bass River Park - 40 Old Main Street West Dennis, MA 02670	Benches	No clear floor space provided at the bench.	Provide compliant clear floor space for the bench at one end.	$1,840.00	ADA 305, 903.2
Bayview Beach - 40 Bayview Road Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Bayview Beach - 40 Bayview Road Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Bayview Beach - 40 Bayview Road Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Bayview Beach - 40 Bayview Road Dennis, MA 02638	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Bayview Beach - 40 Bayview Road Dennis, MA 02638	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Bayview Beach - 40 Bayview Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903

Boundless Playground at Graded School House - 67 School Street West Dennis, MA 02670	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
Boundless Playground at Graded School House - 67 School Street West Dennis, MA 02670	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to accessible building entrances at every major junction along the	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Boundless Playground at Graded School House - 67 School Street West Dennis, MA 02670	Play Area	The ramp slope is not compliant.	Modify the run of the ramp to provide the required slope and cross slope.	$25.84	ADA 1008, 1008.2.5, 405.2
Boundless Playground at Graded School House - 67 School Street West Dennis, MA 02670	Play Area	The ramp length is not compliant.	Provide compliant ramp to the play equipment.	$824.99	ADA 1008.2
Boundless Playground at Graded School House - 67 School Street West Dennis, MA 02670	Play Area	The slope of the bottom landing is not compliant.	Modify the bottom landing to provide a compliant slope.	$25.84	ADA 1008.2, 405.2

Boundless Playground at Graded School House - 67 School Street West Dennis, MA 02670	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-accessible. The parking lot can	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Picnic Areas	There is no accessible route to the picnic tables.	Provide an accessible route to the picnic tables.	$1,440.00	ADA 205, 226, 228, 308, 309, 402, 403

Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Fishing Piers	Pier/Platform walking surface is not compliant.	Provide compliant walking surface with recommended value at the pier/platform.		
Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Fishing Piers	Guardrail height is not compliant.	Provide compliant guardrail for the pier/platform.		ADA 1005.2.1, IBC 1003.1.12.1
Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3
Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Fishing Piers	Gangway is not compliant.	Provide a compliant gangway at the pier/platform.		
Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Fishing Piers	Gangway is not compliant.	Provide a compliant gangway at the pier/platform.		

Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Fishing Piers	Change in level height at top is not compliant.	Provide compliant gangway.		
Captain Harding - 8 Captain Hardings Lane West Dennis, MA 02670	Fishing Piers	Change in level height at bottom is not compliant.	Provide compliant gangway.		
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Parking	The bottom edge of the wall-mounted signage designating accessible parking is not at the required height.	Remount the wall-mounted signage designating the accessible parking space so that it is installed at the required height. The sign	$158.00	ADA 502, 502.6, MA 23.6
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Parking	The bottom edge of the wall-mounted signage designating accessible parking is not at the required height.	Remount the wall-mounted signage designating the accessible parking space so that it is installed at the required height. The sign	$158.00	ADA 502, 502.6, MA 23.6

Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$3,500.00	ADA 404, 404.2.3, MA 26.5
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$8,000.00	ADA 404, 404.2.4, MA 26.6
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$8,000.00	ADA 404, 404.2.4, MA 26.6
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$1,600.00	ADA 309.4, 404.2.7
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6

Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	The vertical clearance height of the open doorway is not compliant.	Provide a compliant open doorway at the location.	$5,600.00	ADA 307.4
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Counters	The height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	Provide a portion of counter at the compliant height.	$3,500.00	ADA 902, 904, MA 35.6, MA 7.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The shields extend greater than 24” in front of the urinal. The width between the shields is less than required.	Modify or replace the urinal shields in the restroom to provide the required clearance between the shields for the urinal	$1,800.00	ADA 305.7, 605, 605.3
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3

Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	Rear grab bar interferes with the tank/flushometer.	Readjust the rear grab bar so that it does not interfere with the tank/flushometer.	$231.00	ADA 609.3

Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 603, 609.4
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2

Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet	$277.00	ADA 603, 604.7, MA 30.7.6
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Assembly Areas	Stairs connect the front of the stage in the theater/auditorium/performing arts center to the audience seating area, the stage is not accessible from a back entrance/ramp/hallway.	Provide a vertical platform lift or other means of vertical access between the level floor seating area and the stage. It is imperative as an ADA mandate to provide	$8,210.00	ADA 219, 221, 706, 802, MA 14.6

Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Break/Conference Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Break/Conference Room	Sink counter height does not meet the standards.	Provide compliant sink.	$1,800.00	ADA 606.3
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Break/Conference Room	The pipes are not wrapped for the sink.	Insulate or otherwise configure the water supply and drain pipes under the sink to protect against contact. Make certain there are no	$149.00	ADA 606.5
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Break/Conference Room	The cabinet door hardware is not accessible.	Provide compliant hardware for the cabinet door.	$1,000.00	ADA 205, 228, 308, 309
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Break/Conference Room	The toe kick for the sink in break/conference room is not removed.	Remove the toe kick for the sink.	$612.00	ADA 305, 306, 606.2
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Break/Conference Room	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Break/Conference Room	Supply lines are not wrapped for the break/conference room sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Carleton Hall - 1006 Old Bass River Road Dennis, MA 02638	Break/Conference Room	Appliance Reach Height in the break/conference room is not compliant.	Make sure that the specified appliance reach height is compliant.	$1,200.00	ADA 205, 308, 309
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the	Re-stripe any existing parking spaces marked accessible and create additional accessible	$370.00	ADA 208, 208.2, MA 23.2

Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1

Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Chapin Beach - 90 Chapin Beach Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Chase Avenue - 5 Chase Avenue Dennis Port, MA 02639	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Chase Avenue - 5 Chase Avenue Dennis Port, MA 02639	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Chase Garden Park / Conservation Area - Chapin Beach Road Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Chase Garden Park / Conservation Area - Chapin Beach Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3

Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	The accessible parking space outline is faded, damaged, missing or otherwise not viewable.	Re-stripe the existing parking space marked as accessible to define the width of the space.	$350.00	ADA 502, 502.2, MA 23.4.5
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking space.	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle that may be shared.	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502

Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	The accessible parking space outline is faded, damaged, missing or otherwise not viewable.	Re-stripe the existing parking space marked as accessible to define the width of the space.	$350.00	ADA 502, 502.2, MA 23.4.5
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking space.	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle that may be shared.	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1

Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2

Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6

Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2

Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2

Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Reach Ranges	The clear floor space width is not compliant.	Provide compliant clear floor space.	$500.00	ADA 304, 305.3
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Reach Ranges	The clear floor space length is not compliant.	Provide compliant clear floor space.	$500.00	ADA 304, 305.3
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Benches	No clear floor space provided at the bench.	Provide compliant clear floor space for the bench at one end.	$1,840.00	ADA 305, 903.2
Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903

Cold Storage Beach - 66 Salt Works Road South Dennis, MA 02660	Benches	No clear floor space provided at the bench.	Provide compliant clear floor space for the bench at one end.	$1,840.00	ADA 305, 903.2
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6

Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3

Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	$1,300.00	ADA 402, 405.3, 406.1, MA 21.3
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	$1,440.00	ADA 406
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	$240.00	ADA 406, 406.4, MA 21.6

Corporation Beach - 250 Corporation Road Dennis, MA 02638	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Stairs	There are no handrails provided on the stairway.	Provide compliant handrails.	$1,528.00	ADA 504, 504.6 , 505.2, MA 27.4
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Counters	The height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	Provide a portion of counter at the compliant height.	$3,500.00	ADA 902, 904, MA 35.6, MA 7.2

Corporation Beach - 250 Corporation Road Dennis, MA 02638	Signage	Highest line of tactile characters are not at a compliant height.	Provide compliant signage at the location.	$158.00	ADA 703.4.1
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Restrooms	The height of the counter surface is greater than allowed.	Relocate or replace the lavatory to provide a maximum counter surface height of no greater than recommended.	$1,286.00	ADA 213, 606, 606.3, MA 30.9.2
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1

Corporation Beach - 250 Corporation Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Outdoor Sports Areas	There are not enough accessible seats at the location with respect to the total number of seats available.	Provide compliant accessible seating at the location.	$600.00	ADA 221.2 , 802.1
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Play Area	The play area is not located on an accessible route.	Provide a compliant accessible route to the play area.	$1,440.00	ADA 1008, 1008.2, 240, 402.1
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Play Area	The play area provides no accessible point of access.	Provide compliant access to the play area.	$2,400.00	ADA 1008, 1008.2, 240
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240

Corporation Beach - 250 Corporation Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Picnic Areas	There is no accessible route to the picnic tables.	Provide an accessible route to the picnic tables.	$1,440.00	ADA 205, 226, 228, 308, 309, 402, 403
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Reach Ranges	The clear floor space slope is not compliant.	Provide compliant clear floor space.	$500.00	ADA 304
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Corporation Beach - 250 Corporation Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903

Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Path of Travel	The width of the path of travel is insufficient.	Widen the primary path of travel to provide the correct width.	$3,500.00	ADA 403.5.1, MA 20.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Path of Travel	There is a curb on the designated path of travel.	Provide a compliant curb ramp.	$2,500.00	ADA 206, 302, 303, 303.4, 402, 403.4, 406

Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The treads do not have a compliant depth.	Modify or replace the stairs to provide compliant treads.	$8,520.00	ADA 504, 504.2, MA 27.2
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4

Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The treads do not have a compliant depth.	Modify or replace the stairs to provide compliant treads.	$8,520.00	ADA 504, 504.2, MA 27.2
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2

Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Fishing Piers	Pier/Platform walking surface is not compliant.	Provide compliant walking surface with recommended value at the pier/platform.		
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Fishing Piers	There is not enough turning space at the pier/platform.	Provide a compliant pier/platform with recommended turning space.		
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Fishing Piers	Guardrail height is not compliant.	Provide compliant guardrail for the pier/platform.		ADA 1005.2.1, IBC 1003.1.12.1
Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3

Cove Road (South Dennis) - 159 Cove Road South Dennis, MA 02660	Fishing Piers	Walking surface gap space width is is not compliant.	Provide compliant walking surface for the pier/platform.		
Cove Road (West Dennis) - 170 Cove Road West Dennis, MA 02670	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
Cove Road (West Dennis) - 170 Cove Road West Dennis, MA 02670	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Cove Road (West Dennis) - 170 Cove Road West Dennis, MA 02670	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Cross Blueberry Patch - 57 Fieldstone Drive Dennis, MA 02638	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
Cross Blueberry Patch - 57 Fieldstone Drive Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Cross Blueberry Patch - 57 Fieldstone Drive Dennis, MA 02638	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1

Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-accessible. The parking lot can	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Exhibits	Exhibit display is not compliant.	Provide a compliant exhibit display.	$640.00	

Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	The leading edge of the object protrudes into path of travel greater than allowed.	Modify, relocate, or lower the item so that the leading edge protrudes less than recommended value.	ADA 1017.9 , 307.2
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail has a tread obstacle.	Remove the tread obstacle.	ADA 1017.5.2
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail has a tread obstacle.	Remove the tread obstacle.	ADA 1017.5.2
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail has a tread obstacle.	Remove the tread obstacle.	ADA 1017.5.2
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail signage does not indicate length of trail.	Provide compliant signage for the trail that includes length of trail.	ADA 1017.11, F247.4.1
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail signage does not indicate length of trail.	Provide compliant signage for the trail that includes length of trail.	ADA 1017.11, F247.4.1
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail signage does not indicate length of trail.	Provide compliant signage for the trail that includes length of trail.	ADA 1017.11, F247.4.1

Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail slope is not compliant.	Readjust the trail surface slope to the recommended value.	ADA 1017.7.1
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	The leading edge of the object protrudes into path of travel greater than allowed.	Modify, relocate, or lower the item so that the leading edge protrudes less than recommended value.	ADA 1017.9 , 307.2
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail has a tread obstacle.	Remove the tread obstacle.	ADA 1017.5.2

Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	There is no compliant signage.	Provide compliant signage with characters and numbers that are properly sized for viewing distance.	ADA 1017.11, F247.4.1
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail signage does not indicate length of trail.	Provide compliant signage for the trail that includes length of trail.	ADA 1017.11, F247.4.1
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	The vertical clearance height is less than required.	Provide the required vertical clearance height.	ADA 307.4
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2

Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail slope is not compliant.	Readjust the trail surface slope to the recommended value.	ADA 1017.7.1
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3

Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.		ADA 1017.7.2
Crowes Pasture Conservation Area - South Street South Dennis, MA 02660	Trails	The vertical clearance height is less than required.	Provide the required vertical clearance height.		ADA 307.4
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The accessible parking space outline is faded, damaged, missing or otherwise not viewable.	Re-stripe the existing parking space marked as accessible to define the width of the space.	$350.00	ADA 502, 502.2, MA 23.4.5
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The accessible parking space outline is faded, damaged, missing or otherwise not viewable.	Re-stripe the existing parking space marked as accessible to define the width of the space.	$350.00	ADA 502, 502.2, MA 23.4.5
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The accessible parking space outline is faded, damaged, missing or otherwise not viewable.	Re-stripe the existing parking space marked as accessible to define the width of the space.	$350.00	ADA 502, 502.2, MA 23.4.5

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Passenger Loading Zones	There are curbs between the access aisle and the vehicle pull-up space.	Remove curbs or install compliant curb ramp to provide accessible path of travel from the vehicle pull-up space and the access aisle.	$150.00	ADA 502, 503, 503.4, MA 23.7

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Passenger Loading Zones	There is no required striped access aisle adjacent to the passenger loading zone.	Create an access aisle to meet the required minimum width and length adjacent and parallel to the vehicle pull-up space. The access aisle striping for the passenger	$650.00	ADA 502, 503, 503.3, MA 23.7
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Passenger Loading Zones	Passenger loading zone has no sign.	Mark the passenger loading zone with ISA symbol of accessibility.	$220.00	ADA 503.3.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	$1,300.00	ADA 405.2, 406, 406.1, MA 21.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	$255.00	ADA 406.2, MA 21.4
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Platform Lifts	Lift device is not red or orange or does not have use instructions.	Make sure that the lowering device is red or orange and has use instructions.	$300.00	ADA 302, 410, ASME A18.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Platform Lifts	Power operated door does not remain open for at least 20 seconds.	Provide a compliant power operated door for the platform lift.		
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Counters	The height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	Provide a portion of counter at the compliant height.	$3,500.00	ADA 902, 904, MA 35.6, MA 7.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Counters	The height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	Provide a portion of counter at the compliant height.	$3,500.00	ADA 902, 904, MA 35.6, MA 7.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Counters	The height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	Provide a portion of counter at the compliant height.	$3,500.00	ADA 902, 904, MA 35.6, MA 7.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is less than the required clear floor space provided in front of the urinal in the restroom to allow an accessible forward approach.	Provide the required minimum clear floor space in front of the urinal designated to be accessible in the restroom, for a forward approach.	$1,707.00	ADA 305.3, 605, 605.3, MA 6.4.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The clear opening width of the doorway to the compartment is less than required.	Widen the doorway to provide a compliant clear opening width when the door is open 90 degrees.	$4,000.00	ADA 404, 404.2.3, 604.8, MA 30.6.1, MA 30.6.2

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The door to the compartment swings inward into the minimum required compartment area.	Modify the swing of the door so that it does not swing into the minimum required compartment area.	$269.00	ADA 304.4, 603, 604.8, MA 30.6.1, MA 30.6.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The clear opening width of the doorway to the compartment is less than required.	Widen the doorway to provide a compliant clear opening width when the door is open 90 degrees.	$4,000.00	ADA 404, 404.2.3, 604.8, MA 30.6.1, MA 30.6.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The door to the compartment swings inward into the minimum required compartment area.	Modify the swing of the door so that it does not swing into the minimum required compartment area.	$269.00	ADA 304.4, 603, 604.8, MA 30.6.1, MA 30.6.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Drinking Fountains	The distance from the front edge of the unit (including bumpers) to the spout location, is greater than the allowed maximum distance.	Make sure that the distance from the front of the fountain to the flow of the water is not greater than the allowed maximum distance.	$2,500.00	ADA 211, 602, 602.5, MA 36.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Drinking Fountains	The water flow trajectory is not parallel to the front of the drinking fountain.	Provide a water flow trajectory that is parallel to the front of the drinking fountain.	$2,875.00	ADA 602.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Drinking Fountains	The distance from the front edge of the unit (including bumpers) to the spout location, is greater than the allowed maximum distance.	Make sure that the distance from the front of the fountain to the flow of the water is not greater than the allowed maximum distance.	$2,500.00	ADA 211, 602, 602.5, MA 36.3
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Drinking Fountains	The water flow trajectory is not parallel to the front of the drinking fountain.	Provide a water flow trajectory that is parallel to the front of the drinking fountain.	$2,875.00	ADA 602.6

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Food Service	There is less than the required percentage of accessible tables/seating provided.	Provide the minimum required percentage of the total seating capacity with accessible seating.	$5,000.00	ADA 206, 226.1, 305, MA 35.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Food Service	The knee space at the table is less than required.	Modify or replace one or more of the tables in the food service area to meet the required minimum accessible seating.	$2,500.00	ADA 226, 306, 306.2.3, 902, 902.2, MA 35.5
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Food Service	The knee space at the table is less than required.	Modify or replace one or more of the tables in the food service area to meet the required minimum accessible seating.	$2,500.00	ADA 226, 306, 306.2.3, 902, 902.2, MA 35.5
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Food Service	The counter/tableware/condiment counter area is not at the required height.	Provide a tableware/condiment counter at the required height.	$2,500.00	ADA 902, 904.5, MA 35.6
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Emergency Warning Systems	There are no visual warning devices at the facility.	Install visual warning devices integrated with the facility's alarm system in all common areas such as hallways, classrooms and general use rooms, and in	$2,200.00	ADA 215, 702, MA 40.1
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Break/Conferenc e Room	The table height in the break/conference room is not compliant.	Provide compliant table in the break/conference room.	$2,200.00	ADA 205, 228, 308, 309
Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902

Dennis Pines Golf Course - 50 Golf Course Road South Dennis, MA 02660	Picnic Areas	The width of the clear floor space at the table is not compliant.	Provide compliant clear floor space at the table.	$1,260.00	ADA 305.3, 902.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Parking	There is no device at the head of the general parking spaces to prevent vehicles from encroaching into walkways.	Install a wheel stop at the head of the general parking spaces.	$148.00	ADA 502, 502.7, MA 23.4.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Parking	There is no device at the head of the accessible parking space to prevent vehicles from encroaching into accessible aisles or walkways.	Install a wheel stop at the head of the accessible parking space.	$250.00	ADA 502, 502.7, MA 23.4.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Parking	There is no device at the head of the accessible parking space to prevent vehicles from encroaching into accessible aisles or walkways.	Install a wheel stop at the head of the accessible parking space.	$250.00	ADA 502, 502.7, MA 23.4.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Parking	There is no device at the head of the accessible parking space to prevent vehicles from encroaching into accessible aisles or walkways.	Install a wheel stop at the head of the accessible parking space.	$250.00	ADA 502, 502.7, MA 23.4.2

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	$1,300.00	ADA 405.2, 406.1, MA 21.3
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Elevators	There is no signage at the Elevator indicating the Evacuation Plan.	Provide compliant signage indicating Evacuation plan and routes.	$207.00	ADA 302, 407
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Elevators	The space between the elevator car and the floor is not compliant.	Decrease the width of the space between the elevator car and the floor to a compliant value.	$1,840.00	ADA 302, 407
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$50.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$50.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$100.00	ADA 404, 404.2.10

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$5,842.00	ADA 404, 404.2.4, MA 26.6

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	Highest line of tactile characters are not at a compliant height.	Provide compliant signage at the location.	$158.00	ADA 703.4.1

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	Highest line of tactile characters are not at a compliant height.	Provide compliant signage at the location.	$158.00	ADA 703.4.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The distance from the rear wall to the side grab bar is greater than allowed.	Remount the side grab bar so it meets the distance requirements from the back wall.	$267.00	ADA 603, 604.5.1, 609, MA 30.8.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The entrance door swings into the turning space within the restroom.	Reverse the door swing, or modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$8,200.00	ADA 304, 305.3, 603.2, 603.2.3
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	There is no signage with the International Symbol of Accessibility.	Install signage that includes the International Symbol of Accessibility (ISA Symbol).	$158.00	ADA 216, 216.8, 703, 703.7, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	There is not a minimum of 56 inches of clearance around the water closet measured perpendicular from the rear wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches (1420 mm) minimum measured	$1,707.00	ADA 603, 604.3.1

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The entrance door swings into the turning space within the restroom.	Reverse the door swing, or modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$8,200.00	ADA 304, 305.3, 603.2, 603.2.3
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	There is no signage with the International Symbol of Accessibility.	Install signage that includes the International Symbol of Accessibility (ISA Symbol).	$158.00	ADA 216, 216.8, 703, 703.7, MA 41.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	Pedestal sink does not allow a forward approach.	Provide compliant sink.	$962.00	ADA 213, 306.1, 606, 606.2

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The distance from the rear wall to the side grab bar is greater than allowed.	Remount the side grab bar so it meets the distance requirements from the back wall.	$267.00	ADA 603, 604.5.1, 609, MA 30.8.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The distance from the rear wall to the side grab bar is greater than allowed.	Remount the side grab bar so it meets the distance requirements from the back wall.	$267.00	ADA 603, 604.5.1, 609, MA 30.8.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The height of the counter surface is greater than allowed.	Relocate or replace the lavatory to provide a maximum counter surface height of no greater than recommended.	$1,286.00	ADA 213, 606, 606.3, MA 30.9.2

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	There is not enough toe clearance at the restroom lavatory.	Provide minimum required toe clearance.	$289.00	ADA 213, 306.2.1, 606, 606.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The height of the counter surface is greater than allowed.	Relocate or replace the lavatory to provide a maximum counter surface height of no greater than recommended.	$1,286.00	ADA 213, 606, 606.3, MA 30.9.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The distance from the rear wall to the side grab bar is greater than allowed.	Remount the side grab bar so it meets the distance requirements from the back wall.	$267.00	ADA 603, 604.5.1, 609, MA 30.8.1
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Drinking Fountains	There is insufficient clear floor space in front of the drinking fountain.	Provide the required clear floor space that is on a primary path of travel.	$660.00	ADA 211, 305, 305.3, 306, 602, 602.2, MA 6.4
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Locker Rooms	No accessible lockers were found.	At least one locker or 5% of the lockers should be accessible.	$1,840.00	ADA 222, 225.2.1 , 803, 811, F222.1, MA 19.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Locker Rooms	There are no accessible benches in the locker room.	Install compliant benches in the locker room.	$500.00	ADA 222, 803, 803.4, MA 33.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Locker Rooms	There are no accessible benches in the locker room.	Install compliant benches in the locker room.	$500.00	ADA 222, 803, 803.4, MA 33.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Locker Rooms	No accessible lockers were found.	At least one locker or 5% of the lockers should be accessible.	$1,840.00	ADA 222, 225.2.1 , 803, 811, F222.1, MA 19.2

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Break/Conference Room	The table knee depth does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 306.3.3, 308, 309
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Break/Conference Room	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Break/Conference Room	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Break/Conference Room	The side reach height of the controls on the vending machine is greater than the allowed maximum height.	Provide a compliant vending machine.		ADA 308
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Break/Conference Room	The side reach height of the controls on the vending machine is greater than the allowed maximum height.	Provide a compliant vending machine.		ADA 308
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Break/Conference Room	The table knee depth does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 306.3.3, 308, 309
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 606.3

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Sinks	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Sinks	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 606.2

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Lockers	No accessible lockers were found.	At least one locker or 5% of the lockers should be accessible.	$1,840.00	ADA 225.2.1 , 811
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Accessible Showers	There are thresholds or splash curbs with a height greater than allowed.	Remove at least a 36-inch wide portion of the splash curbs to provide access to the recommended accessible shower. Shower compartments that are 30	$950.00	ADA 608, MA 31.7.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Accessible Showers	The controls on the showers hand held mount are not accessible.	Provide accessible controls on the hand held mount.	$540.00	ADA 213, 608, 608.6
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Accessible Showers	There are thresholds or splash curbs with a height greater than allowed.	Remove at least a 36-inch wide portion of the splash curbs to provide access to the recommended accessible shower. Shower compartments that are 30	$950.00	ADA 608, MA 31.7.8
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Accessible Showers	The folding seat in the accessible shower is not mounted at a compliant height above the finished floor.	Remount the folding seat to a compliant height above the finished floor.	$1,500.00	ADA 608, 610.3, MA 31.7.4
Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Accessible Showers	The controls on the showers hand held mount are not accessible.	Provide accessible controls on the hand held mount.	$540.00	ADA 213, 608, 608.6

Dennis Police Station - 90 Bob Crowell Road South Dennis, MA 02660	Reach Ranges	The side reach height of the controls on the vending machine is greater than the allowed maximum height.	Contact the owner of the vending machines to obtain accessible vending machines.		ADA 308, 309
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$300.00	ADA 303, 403.4, MA 20.10
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Path of Travel	Walking surface has an opening that is not compliant.	Make sure that the walking surface opening does not allow passage of a sphere more than ½ inch in diameter.	$185.00	ADA 302.3
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$474.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no informational signage.	Install informational signage to each accessible element or room or location.	$158.00	ADA 216.3 , 703.5, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above finish floor	$291.00	ADA 213, 603, 603.3, MA 30.18
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side	$267.00	ADA 604.5.2

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 604.5.1, MA 30.20
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The distance from the center line of the toilet to the nearest side wall in the compartment designated to be accessible in the restroom is greater	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side	$267.00	ADA 604.5.2

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side	$267.00	ADA 604.5.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Drinking Fountains	There is less than the required minimum knee clearance height.	Provide a fountain with the required knee and toe clearances.	$2,500.00	ADA 211, 306, 602, 602.2, MA 36.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Drinking Fountains	The drinking fountain protrudes more than 4 inches outside of the alcove.	Provide an alcove that will contain the entire depth of the drinking fountain.	$640.00	ADA 305, 307.2, 602.1 , MA 6.4.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Libraries	The knee clearance height of the table is not compliant.	Provide a compliant table.	$500.00	ADA 226, 306, 902, 902.2
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Libraries	The space between book shelves is less than required value.	Increase the space between shelves to the recommended value.	$2,160.00	ADA 403
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Libraries	The knee clearance height at the table for use primarily by children is not compliant.	Provide a compliant table for use primarily by children.	$174.00	ADA 226, 306, 902
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Libraries	There is less than 19 inches of knee depth provided at the library table.	Modify the table so that it provides at least 27 inches of knee clearance space with 30 inches horizontal width and 19 inches	$174.00	ADA 226, 306, 902
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Break/Conferenc e Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Break/Conferenc e Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Break/Conferenc e Room	Sink counter height does not meet the standards.	Provide compliant sink.	$1,800.00	ADA 606.3

Dennis Public Library - 5 Hall Street Dennis, MA 02638	Break/Conference Room	Appliance Reach Height in the break/conference room is not compliant.	Make sure that the specified appliance reach height is compliant.	$1,200.00	ADA 205, 308, 309
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Break/Conference Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Break/Conference Room	Sink counter height does not meet the standards.	Provide compliant sink.	$1,800.00	ADA 606.3
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Break/Conference Room	Supply lines are not wrapped for the break/conference room sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Break/Conference Room	The table knee depth does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 306.3.3, 308, 309
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Break/Conference Room	Appliance Reach Height in the break/conference room is not compliant.	Make sure that the specified appliance reach height is compliant.	$1,200.00	ADA 205, 308, 309
Dennis Public Library - 5 Hall Street Dennis, MA 02638	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	There is no designated "van accessible" parking space provided in the parking lot.	Provide a compliant van accessible space.	$370.00	ADA 208, 208.2.4, 502.7, MA 23.2

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	There is no designated "van accessible" parking space provided in the parking lot.	Provide a compliant van accessible space.	$370.00	ADA 208, 208.2.4, 502.7, MA 23.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	There is no device at the head of the accessible parking space to prevent vehicles from encroaching into accessible aisles or walkways.	Install a wheel stop at the head of the accessible parking space.	$250.00	ADA 502, 502.7, MA 23.4.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	There is no device at the head of the accessible parking space to prevent vehicles from encroaching into accessible aisles or walkways.	Install a wheel stop at the head of the accessible parking space.	$250.00	ADA 502, 502.7, MA 23.4.2

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	The designated accessible parking space does not provide accessible signage at the head of the space.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, MA 23.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	There is no device at the head of the accessible parking space to prevent vehicles from encroaching into accessible aisles or walkways.	Install a wheel stop at the head of the accessible parking space.	$250.00	ADA 502, 502.7, MA 23.4.2

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Passenger Loading Zones	The slope of the surface for the access aisle at the passenger loading zone is greater than required.	Resurface the passenger loading zone to provide a level surface or one that does not exceed the maximum slope in any direction.	$2,900.00	ADA 502, 503, 503.4, MA 23.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Passenger Loading Zones	Passenger loading zone has no sign.	Mark the passenger loading zone with ISA symbol of accessibility.	$220.00	ADA 503.3.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Path of Travel	The vertical clearance height is less than required.	Provide recommended vertical clearance.	$108.00	ADA 307, 307.4, MA 20.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Path of Travel	Section of surface is broken or spalled.	Provide a compliant surface for the broken/spalled section.	$1,260.00	ADA 302, 403.2

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Ramps	There is a change in elevation greater than allowed on the primary path of travel of the ramp that is not beveled.	Bevel the area or resurface the area to provide a smooth and level path of travel.	$1,840.00	ADA 302, 303, 303.3, 405.7.1, MA 20.10
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Ramps	The slope of the landing is greater than required.	Modify the landing to create a slope in any direction not exceeding the required maximum value.	$2,872.00	ADA 402, 405.7.1, MA 20.9
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4, MA 24.5.9
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Ramps	There is not enough distance between the rails(Adult and Children).	Provide compliant rails for the ramp.	$61.18	

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Ramps	The ends of the handrails end abruptly.	The handrails shall provide extensions that are parallel to the floor or ground surface extending the required distance beyond the top and bottom of the ramp and	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4, MA 24.5.9
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Ramps	There is not enough distance between the rails(Adult and Children).	Provide compliant rails for the ramp.	$61.18	
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Elevators	There is no signage at the Elevator indicating the Evacuation Plan.	Provide compliant signage indicating Evacuation plan and routes.	$207.00	ADA 302, 407
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Elevators	An emergency communication system is provided, though the controls and emergency equipment are not identified by accessible symbols.	Contact a certified elevator provider to perform all renovation required.	$800.00	ADA 407, 407.4.7.1.3, MA 28.10
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Elevators	An emergency communication system is provided, though it is located in a closed compartment with non-accessible hardware.	Contact a certified elevator provider to perform all renovation required.	$4,500.00	ADA 309.4, 407, 407.4.6 , MA 39.5

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Elevators	Controls are not compliant.	Provide compliant controls.	$339.00	ADA 407
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Elevators	Controls are not compliant.	Provide compliant controls.	$339.00	ADA 407
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Elevators	Main floor is not indicated with a star.	Make sure that main floor is indicated with a star.	$180.00	ADA 407, MA 28.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	Stair run vertical clearance height is not compliant.	Provide compliant vertical clearance for the stair run.		ADA 307.4
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The surface texture of the wall adjacent to the handrail is sharp and abrasive.	Modify the surface texture on the wall adjacent to the handrail so that the surface is smooth.	$2,320.00	ADA 504.6 , 505, 505.8, MA 27.4.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The surface texture of the wall adjacent to the handrail is sharp and abrasive.	Modify the surface texture on the wall adjacent to the handrail so that the surface is smooth.	$2,320.00	ADA 504.6 , 505, 505.8, MA 27.4.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The distance between the handrail and the wall on the stairway is less than required.	Remount the handrails on the stairway so that the distance from the handrail to the adjacent wall is compliant.	$1,916.00	ADA 504, 504.6 , 505.5, MA 27.4.7

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The distance between the handrail and the wall on the stairway is less than required.	Remount the handrails on the stairway so that the distance from the handrail to the adjacent wall is compliant.	$1,916.00	ADA 504, 504.6 , 505.5, MA 27.4.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The control switch for automatic door is within the arc of the door opening.	Provide a compliant automatic door.	$4,000.00	ADA 404, 404.3.5, ANSI/BHMA A156, ANSI/BHMA A156
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$1,600.00	ADA 309.4, 404.2.7

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$1,600.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$1,600.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The vertical clearance height of the open doorway is not compliant.	Provide a compliant open doorway at the location.	$5,600.00	ADA 307.4
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The height of the urinal flush control in the restroom is greater than the required maximum height.	Lower the flush control valve on the urinal to a height not greater than the required maximum height.	$227.00	ADA 308.2, 309.3, 605, 605.4, MA 30.10.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is no back grab bar at the toilet compartment.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 604.8.1.5, MA 30.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The length of the side grab bar is less than required.	Replace the side grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is no back grab bar at the toilet compartment.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 604.8.1.5, MA 30.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The length of the side grab bar is less than required.	Replace the side grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side and 24 inches of extension on the	$267.00	ADA 604.5.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The height of the counter surface is greater than allowed.	Relocate or replace the lavatory to provide a maximum counter surface height of no greater than recommended.	$1,286.00	ADA 213, 606, 606.3, MA 30.9.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is no back grab bar at the toilet compartment.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 604.8.1.5, MA 30.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The height of the urinal flush control in the restroom is greater than the required maximum height.	Lower the flush control valve on the urinal to a height not greater than the required maximum height.	$227.00	ADA 308.2, 309.3, 605, 605.4, MA 30.10.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Drinking Fountains	There is less than the required minimum knee clearance height.	Provide a fountain with the required knee and toe clearances.	$2,500.00	ADA 211, 306, 602, 602.2, MA 36.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Drinking Fountains	The spout outlet height is greater than required.	Provide a spout outlet that does not exceed the required height.	$627.00	ADA 211, 602, 602.4, MA 36.4
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	The table knee clearance does not meet required standards.	Provide compliant tables.	$500.00	ADA 305, 306, 902.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	The table knee clearance does not meet required standards.	Provide compliant tables.	$500.00	ADA 305, 306, 902.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	The table knee depth does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 306.3.3, 308, 309

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	Sink counter height does not meet the standards.	Provide compliant sink.	$1,800.00	ADA 606.3
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	The pipes are not wrapped for the sink.	Insulate or otherwise configure the water supply and drain pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under	$149.00	ADA 606.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	The cabinet door hardware is not accessible.	Provide compliant hardware for the cabinet door.	$1,000.00	ADA 205, 228, 308, 309
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	The toe kick for the sink in break/conference room is not removed.	Remove the toe kick for the sink.	$612.00	ADA 305, 306, 606.2
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	Supply lines are not wrapped for the break/conference room sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	The table knee width does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 308, 309

Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	The table knee depth does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 306.3.3, 308, 309
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Break/Conference Room	The table knee width does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 308, 309
Dennis Senior Center - 1045 Route 134 South Dennis, MA 02660	Reach Ranges	The knee height is not compliant.	Adjust knee height to the recommended value.	$500.00	ADA 226, 304, 306, 902
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle parked in the space.	$158.00	ADA 502, 502.6, MA 23.6

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle parked in the space.	$158.00	ADA 502, 502.6, MA 23.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Path of Travel	There is a curb on the designated path of travel.	Provide a compliant curb ramp.	$2,500.00	ADA 206, 302, 303, 303.4, 402, 403.4, 406
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed for a vertical rise.	Modify or replace the threshold to provide the recommended height.	$257.00	ADA 404, 404.2.5, MA 26.10
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed for a vertical rise.	Modify or replace the threshold to provide the recommended height.	$257.00	ADA 404, 404.2.5, MA 26.10
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition.	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition.	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition.	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition.	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed for a vertical rise.	Modify or replace the threshold to provide the recommended height.	$257.00	ADA 404, 404.2.5, MA 26.10
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door.	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The entrance door swings into the turning space within the restroom.	Reverse the door swing, or modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$8,200.00	ADA 304, 305.3, 603.2, 603.2.3
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be accessible in the restroom.	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow continuous paper flow and shall	$277.00	ADA 603, 604.7, MA 30.7.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be accessible in the restroom.	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow continuous paper flow and shall	$277.00	ADA 603, 604.7, MA 30.7.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow continuous paper flow and shall	$277.00	ADA 603, 604.7, MA 30.7.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	Clear floor space of at least 18"x18" is not centered at the signage and/or is within the swing of the door.	Provide at least 18"x18" of clear floor space centered at the signage. Make sure it is not located within the door swing.		ADA 703.4.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	There is not a minimum of 60 inches of clearance around the water closet measured perpendicular from the side wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches (1420 mm) minimum measured perpendicular from the rear wall.	$1,707.00	ADA 502.4, 603, 604.3.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 603.3
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	There is not enough toe clearance at the restroom lavatory.	Provide minimum required toe clearance.	$289.00	ADA 213, 306.2.1, 606, 606.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Drinking Fountains	There is less than the required minimum knee clearance height.	Provide a fountain with the required knee and toe clearances.	$2,500.00	ADA 211, 306, 602, 602.2, MA 36.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Drinking Fountains	There is less than the required minimum knee clearance height.	Provide a fountain with the required knee and toe clearances.	$2,500.00	ADA 211, 306, 602, 602.2, MA 36.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Locker Rooms	No accessible lockers were found.	At least one locker or 5% of the lockers should be accessible.	$1,840.00	ADA 222, 225.2.1 , 803, 811, F222.1, MA 19.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Locker Rooms	The bench is not fixed to the wall along the longer dimension.	Install a compliant bench in the locker room. Provide sufficient clear floor space alongside the the bench to allow a person using a wheelchair to transfer on to the bench.	$500.00	ADA 222, 803, 803.4, 903.4, MA 33.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Locker Rooms	The width of the bench is not compliant.	Install a compliant bench in the locker room. Provide sufficient clear floor space alongside the the bench to allow a person using a wheelchair to transfer on to the bench.	$500.00	ADA 222, 803, 803.4, 903.3, MA 33.6

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Locker Rooms	No accessible lockers were found.	At least one locker or 5% of the lockers should be accessible.	$1,840.00	ADA 222, 225.2.1 , 803, 811, F222.1, MA 19.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Locker Rooms	The bench is not fixed to the wall along the longer dimension.	Install a compliant bench in the locker room. Provide sufficient clear floor space alongside the the bench to allow a person using a wheelchair to transfer on to the bench.	$500.00	ADA 222, 803, 803.4, 903.4, MA 33.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Locker Rooms	The width of the bench is not compliant.	Install a compliant bench in the locker room. Provide sufficient clear floor space alongside the the bench to allow a person using a wheelchair to transfer on to the bench.	$500.00	ADA 222, 803, 803.4, 903.3, MA 33.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The table knee depth does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 306.3.3, 308, 309
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The side reach height of the controls on the vending machine is greater than the allowed maximum height.	Provide a compliant vending machine.		ADA 308
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The controls of the vending machine require tight grasping, pinching, or twisting of the wrist.	Replace controls of vending machine with those that allow operation with one hand and does not require tight grasping, pinching, or twisting of the wrist.		ADA 305

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	Sink counter height does not meet the standards.	Provide compliant sink.	$1,800.00	ADA 606.3
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The pipes are not wrapped for the sink.	Insulate or otherwise configure the water supply and drain pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	Supply lines are not wrapped for the break/conference room sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The table knee depth does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 306.3.3, 308, 309

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	Appliance Reach Height in the break/conference room is not compliant.	Make sure that the specified appliance reach height is compliant.	$1,200.00	ADA 205, 308, 309
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	Sink counter height does not meet the standards.	Provide compliant sink.	$1,800.00	ADA 606.3
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The pipes are not wrapped for the sink.	Insulate or otherwise configure the water supply and drain pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	Supply lines are not wrapped for the break/conference room sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The table knee clearance does not meet required standards.	Provide compliant tables.	$500.00	ADA 305, 306, 902.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The table knee width does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 308, 309
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The aisle width between tables is not compliant.	Provide compliant aisle width between tables.		ADA 205, 228, 308, 309
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Break/Conference Room	The table knee clearance does not meet required standards.	Provide compliant tables.	$500.00	ADA 305, 306, 902.2
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	There is not enough transfer space available at the shower.	Provide compliant transfer space for the accessible shower.	$1,840.00	ADA 608.2.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	The grab bars in the accessible shower are not mounted at a compliant height.	Remount the grab bars in the accessible shower to a compliant height and location.	$78.00	ADA 608, MA 31.7.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	Shower seat length is not compliant.	Provide a compliant seat that extends the full length of the shower.	$1,068.00	ADA 608, MA 31.7.4
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	The distance between the folding seat and the adjacent wall is greater than 1 1/2 inches.	Remount the folding seat at a height of 18 inches above the finished floor. Make certain that the distance between the folding seat and wall upon which it is hung is no greater than 1 1/2 inches and	$1,500.00	ADA 608, MA 31.7.4
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	The folding seat in the accessible shower is not mounted at a compliant height above the finished floor.	Remount the folding seat to a compliant height above the finished floor.	$1,500.00	ADA 608, 610.3, MA 31.7.4
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	The water valve distance from seat wall is not compliant.	Provide a compliant water valve.	$1,500.00	ADA 213, 608, 608.6, MA 31.7.3

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	The hand-held sprayer unit is not mounted at the required height above the finished floor.	Provide a compliant hand-held sprayer unit with a hose.	$385.00	ADA 213, 608, MA 31.7.7
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	The controls on the showers hand held mount are not accessible.	Provide accessible controls on the hand held mount.	$540.00	ADA 213, 608, 608.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	There is not enough transfer space available at the shower.	Provide compliant transfer space for the accessible shower.	$1,840.00	ADA 608.2.1
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	The grab bars in the accessible shower are not mounted at a compliant height.	Remount the grab bars in the accessible shower to a compliant height and location.	$78.00	ADA 608, MA 31.7.5
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	Shower seat length is not compliant.	Provide a compliant seat that extends the full length of the shower.	$1,068.00	ADA 608, MA 31.7.4
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	The distance between the folding seat and the adjacent wall is greater than 1 1/2 inches.	Remount the folding seat at a height of 18 inches above the finished floor. Make certain that the distance between the folding seat and wall upon which it is hung is no greater than 1 1/2 inches and	$1,500.00	ADA 608, MA 31.7.4

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	The folding seat in the accessible shower is not mounted at a compliant height above the finished floor.	Remount the folding seat to a compliant height above the finished floor.	$1,500.00	ADA 608, 610.3, MA 31.7.4
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	The water valve distance from seat wall is not compliant.	Provide a compliant water valve.	$1,500.00	ADA 213, 608, 608.6, MA 31.7.3
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	The hand-held sprayer unit is not mounted at the required height above the finished floor.	Provide a compliant hand-held sprayer unit with a hose.	$385.00	ADA 213, 608, MA 31.7.7
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Accessible Showers	The controls on the showers hand held mount are not accessible.	Provide accessible controls on the hand held mount.	$540.00	ADA 213, 608, 608.6
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Reach Ranges	The clear floor space slope is not compliant.	Provide compliant clear floor space.	$500.00	ADA 304
DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Reach Ranges	The clear floor space slope is not compliant.	Provide compliant clear floor space.	$500.00	ADA 304

DPW Headquarters & Operations - 120 Theophilus Smith Road South Dennis, MA 02660	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking space.	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle that may be shared.	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3

East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking space.	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle that may be shared.	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502

East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Ramps	The width of the ramp is less than required.	Widen the run of the ramp so that it has minimum required width.	$9,515.00	ADA 405, 405.5, MA 24.3
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Ramps	The slope of the ramp is greater than the allowed slope.	Modify the run of the ramp to provide the required slope and cross slope.	$3,600.00	ADA 405, 405.2, MA 24.2

East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Ramps	There are no handrails.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.2, MA 24.5
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Ramps	The slope of the landing is greater than required.	Modify the landing to create a slope in any direction not exceeding the required maximum value.	$2,872.00	ADA 402, 405.7.1, MA 20.9
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Ramps	There is a change in elevation greater than allowed on the primary path of travel of the ramp that is not beveled.	Bevel the area or resurface the area to provide a smooth and level path of travel.	$1,840.00	ADA 302, 303, 303.3, 405.7.1, MA 20.10
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3

East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1

East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1

East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8

East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side and 24 inches of extension on the	$267.00	ADA 604.5.2
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Emergency Warning Systems	There are no visual warning devices in this area of the facility.	Install visual warning devices integrated with the facility's alarm system in all common areas such as hallways, general use rooms, and in accessible restrooms and	$2,200.00	ADA 215, 702, 702.1, MA 40.3
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Emergency Warning Systems	There are no visual warning devices in this area of the facility.	Install visual warning devices integrated with the facility's alarm system in all common areas such as hallways, general use rooms, and in accessible restrooms and	$2,200.00	ADA 215, 702, 702.1, MA 40.3
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Fishing Piers	Pier/Platform walking surface is not compliant.	Provide compliant walking surface with recommended value at the pier/platform.		

East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3
East Sesuit Harbor - 80 Cold Storage Road South Dennis, MA 02660	Fishing Piers	Gangway is not compliant.	Provide a compliant gangway at the pier/platform.		
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it	$158.00	ADA 502, 502.6, MA 23.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Passenger Loading Zones	The access aisle adjacent to the passenger loading zone is located on a raised sidewalk.	Remove the striping on the sidewalk and create an access aisle to meet the required minimum width and length adjacent and parallel to the vehicle pull-up	$400.00	ADA 502, 503.4, MA 23.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Passenger Loading Zones	There is less than the minimum required length in the access aisle at the passenger loading zone.	Create an access aisle to meet the required minimum width and length adjacent and parallel to the vehicle pull-up space. The access	$650.00	ADA 502, 503, 503.3.2, MA 23.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Passenger Loading Zones	There is less than the minimum required width in the access aisle at the passenger loading zone.	Create an access aisle to meet the required minimum width and length adjacent and parallel to the vehicle pull-up space. The access	$650.00	ADA 502, 503, 503.3.1, MA 23.7

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Passenger Loading Zones	The slope of the surface for the access aisle at the passenger loading zone is greater than required.	Resurface the passenger loading zone to provide a level surface or one that does not exceed the maximum slope in any direction.	$2,900.00	ADA 502, 503, 503.4, MA 23.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Passenger Loading Zones	Passenger loading zone has no sign.	Mark the passenger loading zone with ISA symbol of accessibility.	$220.00	ADA 503.3.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Passenger Loading Zones	The passenger loading zone exceeds 100 feet of continuous length.	Provide a compliant passenger loading zone for every 100 feet (30m) of continuous passenger loading zone provided.	$2,800.00	ADA 209.2.1, 503
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	The guardrail height is not compliant.	Provide compliant guardrails.	$2,176.00	IBC 1003.2.12.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There is no edge protection at the drop off.	Install edge protection on the walking surface at the required minimum height.	$2,176.00	ADA 303.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$450.00	ADA 303, 403.4, MA 20.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The slope of the ramp is greater than the allowed slope.	Modify the run of the ramp to provide the required slope and cross slope.	$3,600.00	ADA 405, 405.2, MA 24.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The length of the bottom landing does not meet the required minimum length.	Modify or replace the bottom landing to provide the required minimum length and width.	$2,872.00	ADA 405, 405.7.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The slope of the landing is greater than required.	Modify the landing to create a slope in any direction not exceeding the required maximum value.	$2,872.00	ADA 402, 405.7.1, MA 20.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The length of the top landing does not meet the required minimum length.	Modify or replace the top landing to provide the required minimum length and width.	$2,872.00	ADA 405.7, 405.7.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	There is a change in elevation greater than allowed on the primary path of travel of the ramp that is not beveled.	Bevel the area or resurface the area to provide a smooth and level path of travel.	$1,840.00	ADA 302, 303, 405.7.1, MA 20.10

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The slope of the landing is greater than required.	Modify the landing to create a slope in any direction not exceeding the required maximum value.	$2,872.00	ADA 402, 405.7.1, MA 20.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The slope of the landing is greater than required.	Modify the landing to create a slope in any direction not exceeding the required maximum value.	$2,872.00	ADA 402, 405.7.1, MA 20.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The slope of the landing is greater than required.	Modify the landing to create a slope in any direction not exceeding the required maximum value.	$2,872.00	ADA 402, 405.7.1, MA 20.9

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The length of the ramp exceeds the maximum distance allowed for its slope (rise).	Provide an intermediate landing on the ramp with a rise for each run of the ramp not exceeding 30 inches in height.	$3,168.00	ADA 405, 405.6, MA 24.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Elevators	There is no signage at the Elevator indicating the Evacuation Plan.	Provide compliant signage indicating Evacuation plan and routes.	$207.00	ADA 302, 407
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Elevators	The elevator provides a center opening door to the elevator car. The width of the elevator car is less than required.	Contact a certified elevator provider to perform all renovation required.		ADA 407, 407.4.1, MA 28.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Elevators	The reopening device for the elevator door does not remain open for the required amount of time.	Contact a certified elevator provider to perform all renovation required.	$800.00	ADA 407, 407.3.3.3, MA 28.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Elevators	There is no signage at the Elevator indicating the Evacuation Plan.	Provide compliant signage indicating Evacuation plan and routes.	$207.00	ADA 302, 407
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Elevators	The reopening device for the elevator door does not remain open for the required amount of time.	Contact a certified elevator provider to perform all renovation required.	$800.00	ADA 407, 407.3.3.3, MA 28.6

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Elevators	Controls are not compliant.	Provide compliant controls.	$339.00	ADA 407
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Elevators	The highest tactile character height above the finish floor is not compliant.	Provide compliant jamb marking for the elevator.		ADA 703.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Platform Lifts	There is no light in the car.	Provide a light in the car.	$800.00	ADA 302, 410, ASME A18.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Platform Lifts	Lift cannot be lowered in case of power loss.	Make sure that the lift can be lowered in the event of power loss.		ADA 302, 410, ASME A18.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Platform Lifts	Lift device is not red or orange or does not have use instructions.	Make sure that the lowering device is red or orange and has use instructions.	$300.00	ADA 302, 410, ASME A18.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Platform Lifts	Platform is not located in a pit.	Please make sure that the platform is located in a pit.	$4,200.00	ADA 205, 228, 308, 309, 410, ASME A18.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Platform Lifts	The slope of the landing is not compliant.	Provide a compliant level landing at the platform lift.	$1,840.00	ADA 302, 410, ASME A18.1 , MA 28.12
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Platform Lifts	There is not enough latch side clearance from the pull side of the platform lift door.	Make sure there is enough latch side clearance from the pull side of the platform lift door.	$2,921.00	ADA 206, 302, 404, 410, ASME A18.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The width of the stairway does not meet the minimum required width.	Install a stairway with a minimum width as required.	$4,816.00	ADA 210, 504, MA 20.3

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The width of the stairway does not meet the minimum required width.	Install a stairway with a minimum width as required.	$4,816.00	ADA 210, 504, MA 20.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no handrails provided on the stairway.	Provide compliant handrails.	$1,528.00	ADA 504, 504.6 , 505.2, MA 27.4
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed for a vertical rise.	Modify or replace the threshold to provide the recommended height.	$257.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$5,842.00	ADA 404, 404.2.4, 404.2.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$50.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed for a vertical rise.	Modify or replace the threshold to provide the recommended height.	$257.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$5,842.00	ADA 404, 404.2.4, 404.2.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$8,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$50.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$50.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	Door hardware broken or missing.	Provide compliant accessible door hardware.	$340.00	ADA 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$50.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$50.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$1,600.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$8,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no informational signage.	Install informational signage to each accessible element or room or location.	$158.00	ADA 216.3 , 703.5, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no informational signage.	Install informational signage to each accessible element or room or location.	$158.00	ADA 216.3 , 703.5, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no informational signage.	Install informational signage to each accessible element or room or location.	$158.00	ADA 216.3 , 703.5, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$316.00	ADA 703.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	Clear floor space of at least 18"x18" is not centered at the signage and/or is within the swing of the door.	Provide at least 18"x18" of clear floor space centered at the signage. Make sure it is not located within the door swing.		ADA 703.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The lavatory is in an enclosed cabinet, thereby preventing an accessible forward approach.	Lavatories in restrooms must provide clear floor space in front of the lavatory for an accessible forward approach and shall provide the minimum required primary age group knee and toe	$420.00	ADA 213, 606, 606.2, MA 30.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not enough toe clearance at the restroom lavatory.	Provide minimum required toe clearance.	$289.00	ADA 213, 306.2.1, 606, 606.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not enough toe clearance at the restroom lavatory.	Provide minimum required toe clearance.	$289.00	ADA 213, 306.2.1, 606, 606.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the	$277.00	ADA 603, 604.9.6, MA 30.14.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the	$277.00	ADA 603, 604.9.6, MA 30.14.5

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not a minimum of 60 inches of clearance around the water closet measured perpendicular from the side wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches	$1,707.00	ADA 502.4, 603, 604.3.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet	$277.00	ADA 603, 604.7, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance between the wall and the gripping surface of the grab bar does not meet requirements.	Remount the grab bar so the space between the wall and gripping surface meets requirements. Grab bars must be able to support a	$250.00	ADA 505, 604.9.3, 609.3, MA 30.8.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance between the wall and the gripping surface of the grab bar does not meet requirements.	Remount the grab bar so the space between the wall and gripping surface meets requirements. Grab bars must be able to support a	$250.00	ADA 505, 604.9.3, 609.3, MA 30.8.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The width between urinal shields in the restroom is less than required.	Modify or replace the urinal shields in the restroom to provide the required shield-width clearance.	$230.00	ADA 305.3, 605, 605.3, MA 30.10.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side	$267.00	ADA 604.5.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the	$277.00	ADA 603, 604.9.6, MA 30.14.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The lavatory is in an enclosed cabinet, thereby preventing an accessible forward approach.	Lavatories in restrooms must provide clear floor space in front of the lavatory for an accessible forward approach and shall provide the minimum required primary age group knee and toe	$420.00	ADA 213, 606, 606.2, MA 30.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not enough toe clearance at the restroom lavatory.	Provide minimum required toe clearance.	$289.00	ADA 213, 306.2.1, 606, 606.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side	$267.00	ADA 604.5.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The diameter of the gripping surface of the grab bars is not within the compliant range.	Replace the grab bars with grab bars that provide a compliant gripping surface diameter. Alternate shapes of grab bars are allowed as long as they allow an	$267.00	ADA 505, 604.5, 609.2, MA 30.8.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment swings inward into the minimum required compartment area.	Modify the swing of the door so that it does not swing into the minimum required compartment area.	$269.00	ADA 304.4, 603, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The clear opening width of the doorway to the compartment is less than required.	Widen the doorway to provide a compliant clear opening width when the door is open 90 degrees.	$4,000.00	ADA 404, 404.2.3, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the rear wall to the side grab bar is greater than allowed.	Remount the side grab bar so it meets the distance requirements from the back wall.	$267.00	ADA 603, 604.5.1, 609, MA 30.8.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the	$277.00	ADA 603, 604.9.6, MA 30.14.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the toilet seat in the restroom is greater than the allowed maximum height for use by the primary age group.	Adjust or modify the height of the toilet seat in the restroom to the required height for use by the primary age group.	$1,707.00	ADA 603, 604.9.3, MA 30.14.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The entrance door swings into the turning space within the restroom.	Reverse the door swing, or modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to	$8,200.00	ADA 304, 305.3, 603.2, 603.2.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The length of the side grab bar is less than required.	Replace the side grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side	$267.00	ADA 604.5.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic	$127.00	ADA 603, 604.6, MA 30.7.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic	$127.00	ADA 603, 604.6, MA 30.7.5

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The length of the side grab bar is less than required.	Replace the side grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side	$267.00	ADA 604.5.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the	$277.00	ADA 603, 604.9.6, MA 30.14.5

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The knee clearance space under the lavatory designated to be accessible in the restroom is less than the required minimum for the primary	Reinstall or replace the lavatory designated to be accessible with an accessible lavatory that provides the required knee	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not enough toe clearance at the restroom lavatory.	Provide minimum required toe clearance.	$289.00	ADA 213, 306.2.1, 606, 606.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish	$291.00	ADA 213, 603, 603.3, MA 30.18

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	There is not enough toe clearance at the restroom lavatory.	Provide minimum required toe clearance.	$289.00	ADA 213, 306.2.1, 606, 606.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The drinking fountain protrudes more than 4 inches outside of the alcove.	Provide an alcove that will contain the entire depth of the drinking fountain.	$640.00	ADA 305, 307.2, 602.1 , MA 6.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	An unstable floor mat is provided within the drinking fountain clear floor space.	Provide a compliant floor mat.	$126.00	ADA 302, 305.2, 602.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	An unstable floor mat is provided within the drinking fountain clear floor space.	Provide a compliant floor mat.	$126.00	ADA 302, 305.2, 602.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The water flow trajectory is not parallel to the front of the drinking fountain.	Provide a water flow trajectory that is parallel to the front of the drinking fountain.	$2,875.00	ADA 602.6
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The toe clearance is less than required.	Provide a fountain with the required knee and toe clearances.	$2,500.00	ADA 211, 305, 306, 306.2, 602, 602.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	There is less than the required minimum knee clearance height.	Provide a fountain with the required knee and toe clearances.	$2,500.00	ADA 211, 306, 602, 602.2, MA 36.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The spout outlet height is greater than required.	Provide a spout outlet that does not exceed the required height.	$627.00	ADA 211, 602, 602.4, MA 36.4
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The spout height for standing persons is not compliant.	Provide a compliant spout outlet height for standing persons.		ADA 602.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	An unstable floor mat is provided within the drinking fountain clear floor space.	Provide a compliant floor mat.	$126.00	ADA 302, 305.2, 602.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of	$2,500.00	ADA 211, 602, 602.6, MA 36.3

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Libraries	There is less than 19 inches of knee depth provided at the library table.	Modify the table so that it provides at least 27 inches of knee clearance space with 30 inches horizontal width and 19 inches	$174.00	ADA 226, 306, 902
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Food Service	There is less than the required percentage of accessible tables/seating provided.	Provide the minimum required percentage of the total seating capacity with accessible seating.	$2,500.00	ADA 206, 226.1, 305, MA 35.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Food Service	Counter is a protruding object.	Make sure that the counter is not a protruding object.	$250.00	ADA 307.2, 902
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Food Service	The width of the aisle at the food service line is less than required.	Widen the aisle at the food service line to provide required width, or a preferred clear width to allow passage around an individual using	$1,200.00	ADA 403, 904.2, MA 17.6.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Food Service	The height of the tray return is greater than the allowed maximum height for the primary age group.	Lower the tops of the tray return to the required accessible level for the primary age group.	$1,200.00	ADA 403, 902, 902.4.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Food Service	The knee space at the table is less than required for the primary age group.	Modify or replace one or more of the tables in the food service area to meet the required minimum accessible seating for the primary	$2,174.00	ADA 306, 306.3.5, 902.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Outdoor Sports Areas	There are not enough accessible seats at the location with respect to the total number of seats available.	Provide compliant accessible seating at the location.	$600.00	ADA 221.2 , 802.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	No bottom landing is provided at the ramp.	Provide a compliant bottom landing.	$1,260.00	ADA 1008.2, 405.7
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	There are no handrails provided for the ramp.	Provide compliant handrails for the ramp.	$61.18	ADA 1008.2.5.3, 505.2

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	The transfer platform height is not compliant.	Provide compliant platform with recommended value at the transfer point.	$320.00	ADA 1008, 1008.3.1.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	The transfer platform is not located on shortest route from the play areas accessible point of access.	The transfer platform shall be located on the shortest route from the play areas accessible point of access.	$320.00	ADA 1008, 1008.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	The point of operation height for the play equipment is not compliant.	Provide compliant play equipment.	$1,500.00	ADA 1008, 1008.4.2, 308.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	The play area is not located on an accessible route.	Provide a compliant accessible route to the play area.	$1,440.00	ADA 1008, 1008.2, 240, 402.1
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	The vertical clearance height on route to the transfer platform/play equipment is not compliant.	Provide compliant vertical clearance.	$1,840.00	ADA 1008, 1008.2, 307.4
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	The vertical clearance height on route to the transfer platform/play equipment is not compliant.	Provide compliant vertical clearance.	$1,840.00	ADA 1008, 1008.2, 307.4
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Break/Conference Room	The pipes are not wrapped for the sink.	Insulate or otherwise configure the water supply and drain pipes under the sink to protect against contact. Make certain there are no	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Break/Conference Room	The cabinet door hardware is not accessible.	Provide compliant hardware for the cabinet door.	$1,000.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Break/Conference Room	The toe kick for the sink in break/conference room is not removed.	Remove the toe kick for the sink.	$612.00	ADA 305, 306, 606.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Break/Conference Room	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Break/Conference Room	Supply lines are not wrapped for the break/conference room sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Break/Conference Room	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$220.00	ADA 205, MA 39.5

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Break/Conference Room	The table knee depth does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 306.3.3, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 606.5

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 606.5

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5

Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Lockers	No accessible lockers were found.	At least one locker or 5% of the lockers should be accessible.	$1,840.00	ADA 225.2.1 , 811
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Ezra Baker School - 810 MA-28 West Dennis, MA 02670	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1

Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Path of Travel	Section of surface is broken or spalled.	Provide a compliant surface for the broken/spalled section.	$1,260.00	ADA 302, 403.2
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Signage	There is no informational signage.	Install informational signage to each accessible element or room or location.	$158.00	ADA 216.3 , 703.5, MA 41.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Signage	There is no informational signage.	Install informational signage to each accessible element or room or location.	$158.00	ADA 216.3 , 703.5, MA 41.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the counter surface is greater than allowed.	Relocate or replace the lavatory to provide a maximum counter surface height of no greater than recommended.	$1,286.00	ADA 213, 606, 606.3, MA 30.9.2
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	There is not a minimum of 56 inches of clearance around the water closet measured perpendicular from the rear wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches	$1,707.00	ADA 603, 604.3.1

Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Emergency Warning Systems	There are no visual warning devices at the facility.	Install visual warning devices integrated with the facility's alarm system in all common areas such as hallways, classrooms and	$2,200.00	ADA 215, 702, MA 40.1
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Break/Conferenc e Room	Sink counter height does not meet the standards.	Provide compliant sink.	$1,800.00	ADA 606.3
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Break/Conferenc e Room	The pipes are not wrapped for the sink.	Insulate or otherwise configure the water supply and drain pipes under the sink to protect against contact. Make certain there are no	$149.00	ADA 606.5

Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Break/Conference Room	The cabinet door hardware is not accessible.	Provide compliant hardware for the cabinet door.	$1,000.00	ADA 205, 228, 308, 309
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Break/Conference Room	The toe kick for the sink in break/conference room is not removed.	Remove the toe kick for the sink.	$612.00	ADA 305, 306, 606.2
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Break/Conference Room	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Break/Conference Room	Supply lines are not wrapped for the break/conference room sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Break/Conference Room	The table knee depth does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 306.3.3, 308, 309
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Break/Conference Room	Appliance Reach Height in the break/conference room is not compliant.	Make sure that the specified appliance reach height is compliant.	$1,200.00	ADA 205, 308, 309
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Break/Conference Room	Appliance Reach Height in the break/conference room is not compliant.	Make sure that the specified appliance reach height is compliant.	$1,200.00	ADA 205, 308, 309
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Fire Station #2 - 1015 Old Bass River Road Dennis, MA 02638	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Parking	The accessible parking space outline is faded, damaged, missing or otherwise not viewable.	Re-stripe the existing parking space marked as accessible to define the width of the space.	$350.00	ADA 502, 502.2, MA 23.4.5
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	$1,300.00	ADA 405.2, 406, 406.1, MA 21.3
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	$1,300.00	ADA 406, 406.3, MA 21.7

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	$240.00	ADA 406, 406.4, MA 21.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Elevators	There is no signage at the Elevator indicating the Evacuation Plan.	Provide compliant signage indicating Evacuation plan and routes.	$207.00	ADA 302, 407
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Elevators	An emergency two-way communication system provides voice only communication.	Contact a certified elevator provider to perform all renovation required.	$800.00	ADA 407, 407.4.9 , 708.2, MA 28.10
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no informational signage.	Install informational signage to each accessible element or room or location.	$158.00	ADA 216.3 , 703.5, MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The height of the counter surface is greater than allowed.	Relocate or replace the lavatory to provide a maximum counter surface height of no greater than recommended.	$1,286.00	ADA 213, 606, 606.3, MA 30.9.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Restrooms	The height of the counter surface is greater than allowed.	Relocate or replace the lavatory to provide a maximum counter surface height of no greater than recommended.	$1,286.00	ADA 213, 606, 606.3, MA 30.9.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Break/Conferenc e Room	The table knee clearance does not meet required standards.	Provide compliant tables.	$500.00	ADA 305, 306, 902.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Break/Conferenc e Room	The table knee depth does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 306.3.3, 308, 309
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 606.3
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2

Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Sinks	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 606.2
Fire Station Headquarters - 883 Route 28 South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	Trail has a tread obstacle.	Remove the tread obstacle.		
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	Trail has a tread obstacle.	Remove the tread obstacle.		

Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	There is no compliant signage.	Provide compliant signage with characters and numbers that are properly sized for viewing distance.	ADA 1017.11, F247.4.1
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	Trail slope is not compliant.	Readjust the trail surface slope to the recommended value.	ADA 1017.7.1
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	Trail slope is not compliant.	Readjust the trail surface slope to the recommended value.	ADA 1017.7.1
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	The condition of the trail cannot be inspected and trail compliance is not feasible due to terrain or other conditional exceptions like the Endangered Species Act, National Environmental Policy Act, National	Further study may need to be required.	ADA 1017.1 , 1019.1 , 1019.2
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	There is no compliant signage.	Provide compliant signage with characters and numbers that are properly sized for viewing distance.	ADA 1017.11, F247.4.1

Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	Trail slope is not compliant.	Readjust the trail surface slope to the recommended value.		ADA 1017.7.1
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	Trail has a tread obstacle.	Remove the tread obstacle.		ADA 1017.5.2
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	Trail has a tread obstacle.	Remove the tread obstacle.		
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	Trail surface is not firm and stable.	Provide a compliant surface that is firm and stable.		ADA 1017.2
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	The vertical clearance height is less than required.	Provide the required vertical clearance height.		ADA 307.4
Flax Pond Conservation Lands - 210 Setucket Road Dennis, MA 02638	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.		ADA 1017.7.2
Follins Park Boat Launch - 20 Follins Pond Road South Dennis, MA 02660	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2

Follins Park Boat Launch - 20 Follins Pond Road South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Francis Baker Park - 110 Main Street South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-accessible. The parking lot can provide parking spaces.	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Parking	The accessible parking space outline is faded, damaged, missing or otherwise not viewable.	Re-stripe the existing parking space marked as accessible to define the width of the space.	$350.00	ADA 502, 502.2, MA 23.4.5
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking space.	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle that may be shared.	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6

Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Parking	The designated accessible parking space in the parking lot does not provide an International Symbol of Accessibility symbol pavement marking.	Provide a compliant pavement marking at the designated accessible parking space.	$220.00	ADA 502, MA 23.6
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7

Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition.	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition.	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition.	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7

Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition.	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Picnic Areas	There is no accessible route to the picnic tables.	Provide an accessible route to the picnic tables.	$1,440.00	ADA 205, 226, 228, 308, 309, 402, 403
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903

Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Trails	The condition of the trail cannot be inspected and trail compliance is not feasible due to terrain or other conditional exceptions like the Endangered Species Act, National Environmental Policy Act, National	Further study may need to be required.		ADA 1017.1 , 1019.1 , 1019.2
Fresh Pond - Off Route 134 South Dennis & Route 157 South Dennis, MA 02660	Trails	Trail has no signage.	Provide compliant signage for the trail.		ADA 1017.11, F247.4.1
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it	$158.00	ADA 502, 502.6, MA 23.6

Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Path of Travel	The width of the path of travel is insufficient.	Widen the primary path of travel to provide the correct width.	$3,500.00	ADA 403.5.1, MA 20.3
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Doors	The vertical clearance height of the open doorway is not compliant.	Provide a compliant open doorway at the location.	$5,600.00	ADA 307.4
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Doors	The clear opening width of the doorway is not compliant.	Provide a compliant doorway at the location.	$1,800.00	ADA 404, 404.2.4.2
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1

Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The restroom is not accessible and cannot be easily altered. There is no sufficient clear floor space to accommodate an individual in a	Consult a design professional to modify the restroom for access compliance.	$14,000.00	ADA 213, 213.1 , 603, 603.1
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The clear opening width of the doorway to the compartment is less than required.	Widen the doorway to provide a compliant clear opening width when the door is open 90 degrees.	$4,000.00	ADA 404, 404.2.3, 604.8, MA 30.6.1, MA 30.6.2

Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic	$127.00	ADA 603, 604.6, MA 30.7.5
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	This restroom is not located on an accessible level or route. This restroom is provided for public use.	Modifications are necessary to make certain accessibility is provided. Relocate to an accessible level or provide an	$1,840.00	ADA 206.2.2, 213, 603, MA 30.2

Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	There is less than the required clear floor space provided in front of the urinal in the restroom to allow an accessible forward approach.	Provide the required minimum clear floor space in front of the urinal designated to be accessible in the restroom, for a forward	$1,707.00	ADA 305.3, 605, 605.3, MA 6.4.1
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The width between urinal shields in the restroom is less than required.	Modify or replace the urinal shields in the restroom to provide the required shield-width clearance.	$230.00	ADA 305.3, 605, 605.3, MA 30.10.2
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1

Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Reach Ranges	Element reach depth is not compliant.	Make sure that the element is within allowed reach range with recommended reach depth.	$550.00	ADA 308
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Glendon Beach - 155 Glendon Road Dennis Port, MA 02639	Benches	No clear floor space provided at the bench.	Provide compliant clear floor space for the bench at one end.	$1,840.00	ADA 305, 903.2
Harborview Beach - 46 Harbor Road Harbor Road South Dennis, MA 02660	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2

Harborview Beach - 46 Harbor Road Harbor Road South Dennis, MA 02660	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-accessible. The parking lot can	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Harborview Beach - 46 Harbor Road Harbor Road South Dennis, MA 02660	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Harborview Beach - 46 Harbor Road Harbor Road South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Harborview Beach - 46 Harbor Road Harbor Road South Dennis, MA 02660	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Path of Travel	The guardrail height is not compliant.	Provide compliant guardrails.	$1,088.00	IBC 1003.2.12.1
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Path of Travel	There is no edge protection at the drop off.	Install edge protection on the walking surface at the required minimum height.	$1,088.00	ADA 303.5

Highbank Road - 17 Highbank Road South Dennis, MA 02660	Path of Travel	Walking surface has an opening that is not compliant.	Make sure that the walking surface opening does not allow passage of a sphere more than ½ inch in diameter.	$185.00	ADA 302.3
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth,	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth,	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6

Highbank Road - 17 Highbank Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Fishing Piers	Guardrail height is not compliant.	Provide compliant guardrail for the pier/platform.		ADA 1005.2.1, IBC 1003.1.12.1
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3
Highbank Road - 17 Highbank Road South Dennis, MA 02660	Fishing Piers	Walking surface gap space width is is not compliant.	Provide compliant walking surface for the pier/platform.		
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	The location of the designated accessible parking space(s) is not located on the shortest accessible route of travel to the facility for which it serves.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	The location of the designated accessible parking space(s) is not located on the shortest accessible route of travel to the facility for which it serves.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking space.	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle that may be shared.	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking space.	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle that may be shared.	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Passenger Loading Zones	The slope of the surface for the access aisle at the passenger loading zone is greater than required.	Resurface the passenger loading zone to provide a level surface or one that does not exceed the maximum slope in any direction.	$2,900.00	ADA 502, 503, 503.4, MA 23.7

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Passenger Loading Zones	Passenger loading zone has no sign.	Mark the passenger loading zone with ISA symbol of accessibility.	$220.00	ADA 503.3.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Platform Lifts	Lift device is not red or orange or does not have use instructions.	Make sure that the lowering device is red or orange and has use instructions.	$300.00	ADA 302, 410, ASME A18.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Platform Lifts	The door width is not compliant.	Provide a compliant door for the lift.		ADA 410.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Platform Lifts	The door width is not compliant.	Provide a compliant door for the lift.		ADA 410.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Platform Lifts	Power operated door does not remain open for at least 20 seconds.	Provide a compliant power operated door for the platform lift.		

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Counters	The height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	Provide a portion of counter at the compliant height.	$3,500.00	ADA 902, 904, MA 35.6, MA 7.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The distance from the rear wall to the side grab bar is greater than allowed.	Remount the side grab bar so it meets the distance requirements from the back wall.	$267.00	ADA 603, 604.5.1, 609, MA 30.8.1

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$280.00	ADA 304, 309, 309.4, 404.2.7, 603
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The entrance door swings into the turning space within the restroom.	Reverse the door swing, or modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$8,200.00	ADA 304, 305.3, 603.2, 603.2.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$280.00	ADA 304, 309, 309.4, 404.2.7, 603
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The entrance door swings into the turning space within the restroom.	Reverse the door swing, or modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$8,200.00	ADA 304, 305.3, 603.2, 603.2.3
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Food Service	There is less than the required percentage of accessible tables/seating provided.	Provide the minimum required percentage of the total seating capacity with accessible seating.	$5,000.00	ADA 206, 226.1, 305, MA 35.1
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Food Service	The knee space at the table is less than required.	Modify or replace one or more of the tables in the food service area to meet the required minimum accessible seating.	$2,500.00	ADA 226, 306, 306.2.3, 902, 902.2, MA 35.5
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Food Service	The height of the top of the tables or dining counters in the food service area is not within the compliant range.	Modify or replace one or more of the tables in the food service area to meet the required minimum accessible seating.	$2,500.00	ADA 902, 902.3, MA 35.6

Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Food Service	The knee space at the table is less than required.	Modify or replace one or more of the tables in the food service area to meet the required minimum accessible seating.	$2,500.00	ADA 226, 306, 306.2.3, 902, 902.2, MA 35.5
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Food Service	The counter/tableware/condiment counter area is not at the required height.	Provide a tableware/condiment counter at the required height.	$2,500.00	ADA 902, 904.5, MA 35.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Food Service	The counter/tableware/condiment counter area is not at the required height.	Provide a tableware/condiment counter at the required height.	$2,500.00	ADA 902, 904.5, MA 35.6
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Picnic Areas	The width of the clear floor space at the table is not compliant.	Provide compliant clear floor space at the table.	$1,260.00	ADA 305.3, 902.2
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Reach Ranges	The knee height is not compliant.	Adjust knee height to the recommended value.	$500.00	ADA 226, 304, 306, 902
Highland Links Golf Course - 825 Old Bass River Road Dennis, MA 02638	Reach Ranges	The controls of the vending machine require tight grasping, pinching, or twisting of the wrist.	Replace controls of vending machine with those that allow operation with one hand and does not require tight grasping, pinching, or twisting of the wrist.	$550.00	ADA 308

Howes Street Beach - 60 Howes Street Dennis, MA 02638	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
Howes Street Beach - 60 Howes Street Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Howes Street Beach - 60 Howes Street Dennis, MA 02638	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Howes Street Beach - 60 Howes Street Dennis, MA 02638	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Howes Street Beach - 60 Howes Street Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Howes Street Beach - 60 Howes Street Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Indian Lands - 485 Main Street South Dennis, MA 02660	Parking	There is no device at the head of the general parking spaces to prevent vehicles from encroaching into walkways.	Install a wheel stop at the head of the general parking spaces.	$148.00	ADA 502, 502.7, MA 23.4.2
Indian Lands - 485 Main Street South Dennis, MA 02660	Parking	The accessible parking space outline is faded, damaged, missing or otherwise not viewable.	Re-stripe the existing parking space marked as accessible to define the width of the space.	$350.00	ADA 502, 502.2, MA 23.4.5

Indian Lands - 485 Main Street South Dennis, MA 02660	Parking	There is no device at the head of the accessible parking space to prevent vehicles from encroaching into accessible aisles or walkways.	Install a wheel stop at the head of the accessible parking space.	$250.00	ADA 502, 502.7, MA 23.4.2
Indian Lands - 485 Main Street South Dennis, MA 02660	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Indian Lands - 485 Main Street South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Indian Lands - 485 Main Street South Dennis, MA 02660	Parking	There is no device at the head of the accessible parking space to prevent vehicles from encroaching into accessible aisles or walkways.	Install a wheel stop at the head of the accessible parking space.	$250.00	ADA 502, 502.7, MA 23.4.2
Indian Lands - 485 Main Street South Dennis, MA 02660	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Indian Lands - 485 Main Street South Dennis, MA 02660	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	$1,300.00	ADA 405.3, 406.1, MA 21.3
Indian Lands - 485 Main Street South Dennis, MA 02660	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance	$1,260.00	ADA 402.2, 406.4, MA 21.6
Indian Lands - 485 Main Street South Dennis, MA 02660	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Indian Lands - 485 Main Street South Dennis, MA 02660	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1

Indian Lands - 485 Main Street South Dennis, MA 02660	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Indian Lands - 485 Main Street South Dennis, MA 02660	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	The leading edge of the object protrudes into path of travel greater than allowed.	Modify, relocate, or lower the item so that the leading edge protrudes less than recommended value.		ADA 1017.9 , 307.2
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	Clear ground space around the constructed feature is not compliant.	Provide compliant clear ground space around the constructed feature.		ADA 1011.2.2
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	Trail has a tread obstacle.	Remove the tread obstacle.		ADA 1017.5.1
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	There is no compliant signage.	Provide compliant signage with characters and numbers that are properly sized for viewing distance.		ADA 1017.11, F247.4.1
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	There is no compliant signage.	Provide compliant signage with characters and numbers that are properly sized for viewing distance.		ADA 1017.11, F247.4.1
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	Trail surface is not firm and stable.	Provide a compliant surface that is firm and stable.		ADA 1017.2
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	Trail surface is not firm and stable.	Provide a compliant surface that is firm and stable.		ADA 1017.2

Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	Trail surface is not firm and stable.	Provide a compliant surface that is firm and stable.	ADA 1017.2
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	Trail surface is not firm and stable.	Provide a compliant surface that is firm and stable.	ADA 1017.2
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	Trail surface is not firm and stable.	Provide a compliant surface that is firm and stable.	ADA 1017.2
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	Trail slope is not compliant.	Readjust the trail surface slope to the recommended value.	ADA 1017.7.1

Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	Trail surface is not firm and stable.	Provide a compliant surface that is firm and stable.		ADA 1017.2
Indian Lands - 485 Main Street South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.		ADA 1017.7.2
Inman Beach - 51 Chase Avenue Dennis Port, MA 02639	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
Inman Beach - 51 Chase Avenue Dennis Port, MA 02639	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Inman Beach - 51 Chase Avenue Dennis Port, MA 02639	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Inman Beach - 51 Chase Avenue Dennis Port, MA 02639	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Inman Beach - 51 Chase Avenue Dennis Port, MA 02639	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Inman Beach - 51 Chase Avenue Dennis Port, MA 02639	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Stairs	The width of the stairway does not meet the minimum required width.	Install a stairway with a minimum width as required.	$4,816.00	ADA 210, 504, MA 20.3
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Stairs	Stair run vertical clearance height is not compliant.	Provide compliant vertical clearance for the stair run.		ADA 307.4
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Stairs	The treads do not have a compliant depth.	Modify or replace the stairs to provide compliant treads.	$8,520.00	ADA 504, 504.2, MA 27.2
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	Door hardware broken or missing.	Provide compliant accessible door hardware.	$340.00	ADA 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door.	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	Door hardware broken or missing.	Provide compliant accessible door hardware.	$340.00	ADA 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The vertical clearance height of the open doorway is not compliant.	Provide a compliant open doorway at the location.	$5,600.00	ADA 307.4
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	There is not a minimum of 56 inches of clearance around the water closet measured perpendicular from the rear wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches (1420 mm) minimum measured	$1,707.00	ADA 603, 604.3.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$280.00	ADA 304, 309, 309.4, 404.2.7, 603
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3

Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	There is not enough toe clearance at the restroom lavatory.	Provide minimum required toe clearance.	$289.00	ADA 213, 306.2.1, 606, 606.2
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Jericho Barn & House Museum - 90 Old Main Street West Dennis, MA 02670	Restrooms	The restroom is not accessible and cannot be easily altered. There is no sufficient clear floor space to accommodate an individual in a wheelchair.	Consult a design professional to modify the restroom for access compliance.	$14,000.00	ADA 213, 213.1 , 603, 603.1

Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1

Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$8,000.00	ADA 404, 404.2.4, MA 26.6
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$8,000.00	ADA 404, MA 26.6
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$4,000.00	ADA 404, 404.2.10
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7

Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$5,842.00	ADA 404, 404.2.4, MA 26.6
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Signage	There is no informational signage.	Install informational signage to each accessible element or room or location.	$158.00	ADA 216.3 , 703.5, MA 41.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Signage	There is no informational signage.	Install informational signage to each accessible element or room or location.	$158.00	ADA 216.3 , 703.5, MA 41.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Signage	There is no informational signage.	Install informational signage to each accessible element or room or location.	$158.00	ADA 216.3 , 703.5, MA 41.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet	$277.00	ADA 603, 604.7, MA 30.7.6
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3

Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the urinal flush control in the restroom is greater than the required maximum height.	Lower the flush control valve on the urinal to a height not greater than the required maximum height.	$227.00	ADA 308.2, 309.3, 605, 605.4, MA 30.10.3
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The width between urinal shields in the restroom is less than required.	Modify or replace the urinal shields in the restroom to provide the required shield-width clearance.	$230.00	ADA 305.3, 605, 605.3, MA 30.10.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5

Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet	$277.00	ADA 603, 604.7, MA 30.7.6
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5

Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Outdoor Sports Areas	There are not enough accessible seats at the location with respect to the total number of seats available.	Provide compliant accessible seating at the location.	$600.00	ADA 221.2 , 802.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Outdoor Sports Areas	There are not enough accessible seats at the location with respect to the total number of seats available.	Provide compliant accessible seating at the location.	$600.00	ADA 221.2 , 802.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Outdoor Sports Areas	There are not enough accessible seats at the location with respect to the total number of seats available.	Provide compliant accessible seating at the location.	$600.00	ADA 221.2 , 802.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Outdoor Sports Areas	There are not enough accessible seats at the location with respect to the total number of seats available.	Provide compliant accessible seating at the location.	$600.00	ADA 221.2 , 802.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The play area is not located on an accessible route.	Provide a compliant accessible route to the play area.	$1,440.00	ADA 1008, 1008.2, 240, 402.1

Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The transfer platform height is not compliant.	Provide compliant platform with recommended value at the transfer point.	$320.00	ADA 1008, 1008.3.1.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The play area is not located on an accessible route.	Provide a compliant accessible route to the play area.	$1,440.00	ADA 1008, 1008.2, 240, 402.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The transfer platform height is not compliant.	Provide compliant platform with recommended value at the transfer point.	$320.00	ADA 1008, 1008.3.1.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240

Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The play area is not located on an accessible route.	Provide a compliant accessible route to the play area.	$1,440.00	ADA 1008, 1008.2, 240, 402.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	The transfer platform height is not compliant.	Provide compliant platform with recommended value at the transfer point.	$320.00	ADA 1008, 1008.3.1.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Play Area	At least one means of support for transferring to the transfer platform is not provided at the steps.	Provide at least one means of support for transferring to assist when transferring.	$1,500.00	ADA 1008, 1008.3.1.4
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Picnic Areas	There is no accessible route to the picnic tables.	Provide an accessible route to the picnic tables.	$1,440.00	ADA 205, 226, 228, 308, 309, 402, 403
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902

Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903

Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Exhibits	Exhibit display is not compliant.	Provide a compliant exhibit display.	$640.00	
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Exhibits	Exhibit display is not compliant.	Provide a compliant exhibit display.	$640.00	
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Exhibits	Exhibit display is not compliant.	Provide a compliant exhibit display.	$640.00	
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Exhibits	Exhibit display is not compliant.	Provide a compliant exhibit display.	$640.00	
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Exhibits	Exhibit display is not compliant.	Provide a compliant exhibit display.	$640.00	
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Exhibits	Exhibit display is not compliant.	Provide a compliant exhibit display.	$640.00	
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Exhibits	Exhibit display is not compliant.	Provide a compliant exhibit display.	$640.00	

Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Trails	The clear ground space is not on an accessible route.	Make sure that clear ground space is on an accessible route.		ADA 1011.2.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Trails	Trail signage does not indicate length of trail.	Provide compliant signage for the trail that includes length of trail.		ADA 1017.11, F247.4.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Trails	Clear ground space around the constructed feature is not compliant.	Provide compliant clear ground space around the constructed feature.		ADA 1011.2.2
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Trails	Trail signage does not indicate length of trail.	Provide compliant signage for the trail that includes length of trail.		ADA 1017.11, F247.4.1
Johnny Kelley / Pavilion - 180 Old Bass River Road Dennis, MA 02638	Trails	Trail signage does not indicate length of trail.	Provide compliant signage for the trail that includes length of trail.		ADA 1017.11, F247.4.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-accessible. The parking lot can	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	The accessible parking space outline is faded, damaged, missing or otherwise not viewable.	Re-stripe the existing parking space marked as accessible to define the width of the space.	$350.00	ADA 502, 502.2, MA 23.4.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking space.	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle that may be shared.	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	The designated accessible parking space in the parking lot does not provide an International Symbol of Accessibility symbol pavement marking.	Provide a compliant pavement marking at the designated accessible parking space.	$220.00	ADA 502, MA 23.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	The accessible parking space outline is faded, damaged, missing or otherwise not viewable.	Re-stripe the existing parking space marked as accessible to define the width of the space.	$350.00	ADA 502, 502.2, MA 23.4.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	The path of travel from the accessible parking space is not on the primary route used by the general public and does not lead to the primary entrance of the facility from the parking lot.	Remove and relocate the designated accessible parking spaces. Accessible paved parking spaces shall be located on the shortest accessible route of travel	$1,379.00	ADA 208, 208.3, 502, MA 23.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking space.	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle that may be shared.	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	The designated accessible parking space in the parking lot does not provide an International Symbol of Accessibility symbol pavement marking.	Provide a compliant pavement marking at the designated accessible parking space.	$220.00	ADA 502, MA 23.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	The width of the path of travel is insufficient.	Widen the primary path of travel to provide the correct width.	$3,500.00	ADA 403.5.1, MA 20.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Path of Travel	There is a step or curb on the path of travel preventing access.	Provide a ramp or other means of vertical access.	$3,500.00	ADA 303, 403.4, MA 20.1

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	There are no handrails provided on the stairway.	Provide compliant handrails.	$1,528.00	ADA 504, 504.6 , 505.2, MA 27.4
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The width of the stairway does not meet the minimum required width.	Install a stairway with a minimum width as required.	$4,816.00	ADA 210, 504, MA 20.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The treads do not have a compliant depth.	Modify or replace the stairs to provide compliant treads.	$8,520.00	ADA 504, 504.2, MA 27.2

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	There are no handrails provided on the stairway.	Provide compliant handrails.	$1,528.00	ADA 504, 504.6 , 505.2, MA 27.4
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The width of the stairway does not meet the minimum required width.	Install a stairway with a minimum width as required.	$4,816.00	ADA 210, 504, MA 20.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The treads do not have a compliant depth.	Modify or replace the stairs to provide compliant treads.	$8,520.00	ADA 504, 504.2, MA 27.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	There are no handrails provided on the stairway.	Provide compliant handrails.	$1,528.00	ADA 504, 504.6 , 505.2, MA 27.4
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The width of the stairway does not meet the minimum required width.	Install a stairway with a minimum width as required.	$4,816.00	ADA 210, 504, MA 20.3

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	Stair run vertical clearance height is not compliant.	Provide compliant vertical clearance for the stair run.		ADA 307.4
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The treads do not have a compliant depth.	Modify or replace the stairs to provide compliant treads.	$8,520.00	ADA 504, 504.2, MA 27.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The distance between the handrail and the wall on the stairway is less than required.	Remount the handrails on the stairway so that the distance from the handrail to the adjacent wall is compliant.	$1,916.00	ADA 504, 504.6 , 505.5, MA 27.4.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The width of the stairway does not meet the minimum required width.	Install a stairway with a minimum width as required.	$4,816.00	ADA 210, 504, MA 20.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	The width of the stairway does not meet the minimum required width.	Install a stairway with a minimum width as required.	$4,816.00	ADA 210, 504, MA 20.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Stairs	There are no handrails provided on the stairway.	Provide compliant handrails.	$1,528.00	ADA 504, 504.6 , 505.2, MA 27.4
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door.	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door.	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the open doorway is not compliant.	Provide a compliant open doorway at the location.	$5,600.00	ADA 307.4
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the open doorway is not compliant.	Provide a compliant open doorway at the location.	$5,600.00	ADA 307.4
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the doorway is not compliant.	Provide a compliant doorway at the location.	$1,800.00	ADA 404, 404.2.4.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is signage suspended or projected overhead. The size of the lettering is less than required or cannot be viewed at a practical distance.	Install accessible signage with lettering sized according to viewing distance.	$158.00	ADA 216, 703, 703.2.5, 703.5.5, MA 41.4
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	Signage contains the word Handicap.	Provide compliant signage. Remove the word Handicap.	$158.00	ADA 216, 703, MA 41.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side and 24 inches of extension on the	$267.00	ADA 604.5.2
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Exhibits	Exhibit display is not compliant.	Provide a compliant exhibit display.	$640.00	

Josiah Dennis Manse & Old West School Museum - 61 Whig Street Dennis, MA 02638	Exhibits	Exhibit display is not compliant.	Provide a compliant exhibit display.	$640.00	
Mayflower Beach / Horsefoot - 62 Horsefoot Path Dennis, MA 02638	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
Mayflower Beach / Horsefoot - 62 Horsefoot Path Dennis, MA 02638	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Mayflower Beach / Horsefoot - 62 Horsefoot Path Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Mayflower Beach / Horsefoot - 62 Horsefoot Path Dennis, MA 02638	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Mayflower Beach / Horsefoot - 62 Horsefoot Path Dennis, MA 02638	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Path of Travel	The guardrail height is not compliant.	Provide compliant guardrails.	$1,088.00	IBC 1003.2.12.1
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1

Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	The treads do not have a compliant depth.	Modify or replace the stairs to provide compliant treads.	$8,520.00	ADA 504, 504.2, MA 27.2
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2

Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Play Area	The play area is not located on an accessible route.	Provide a compliant accessible route to the play area.	$1,440.00	ADA 1008, 1008.2, 240, 402.1
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Play Area	The play area provides no accessible point of access.	Provide compliant access to the play area.	$2,400.00	ADA 1008, 1008.2, 240
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Play Area	The transfer platform height is not compliant.	Provide compliant platform with recommended value at the transfer point.	$320.00	ADA 1008, 1008.3.1.2

Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Play Area	Transfer platform depth is not compliant.	Provide compliant platform with recommended value at the transfer point.	$320.00	ADA 1008, 1008.3.1.1
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Play Area	Transfer platform width is not compliant.	Provide compliant platform with recommended value at the transfer point.	$320.00	ADA 1008, 1008.3.1.1
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Play Area	The tread depth of the steps is not compliant.	Provide steps with compliant tread depth.	$34.75	ADA 1008, 1008.3.2.1
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Play Area	The width of the steps is not compliant.	Provide steps with a compliant width.	$280.00	ADA 1008, 1008.3.2.1
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Play Area	The height of the steps is not compliant.	Provide steps with a compliant riser height.	$280.00	ADA 1008, 1008.3.2.2
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Play Area	The vertical clearance height on route to the transfer platform/play equipment is not compliant.	Provide compliant vertical clearance.	$1,840.00	ADA 1008, 1008.2, 307.4
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Picnic Areas	There is no accessible route to the picnic tables.	Provide an accessible route to the picnic tables.	$1,440.00	ADA 205, 226, 228, 308, 309, 402, 403
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903

Mike Stacy Park - 21 Hall Street Dennis Port, MA 02639	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Passenger Loading Zones	There is less than the minimum required length in the access aisle at the passenger loading zone.	Create an access aisle to meet the required minimum width and length adjacent and parallel to the vehicle pull-up space. The access aisle striping for the passenger	$650.00	ADA 502, 503, 503.3.2, MA 23.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Passenger Loading Zones	The slope of the surface for the access aisle at the passenger loading zone is greater than required.	Resurface the passenger loading zone to provide a level surface or one that does not exceed the maximum slope in any direction.	$2,900.00	ADA 502, 503, 503.4, MA 23.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Passenger Loading Zones	Passenger loading zone has no sign.	Mark the passenger loading zone with ISA symbol of accessibility.	$220.00	ADA 503.3.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Passenger Loading Zones	The passenger loading zone exceeds 100 feet of continuous length.	Provide a compliant passenger loading zone for every 100 feet (30m) of continuous passenger loading zone provided.	$2,800.00	ADA 209.2.1, 503
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	There is a curb on the designated path of travel.	Provide a compliant curb ramp.	$2,500.00	ADA 206, 302, 303, 303.4, 402, 403.4, 406
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	The vertical clearance height is less than required.	Provide recommended vertical clearance.	$108.00	ADA 307, 307.4, MA 20.7

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	Section of surface is broken or spalled.	Provide a compliant surface for the broken/spalled section.	$1,260.00	ADA 302, 403.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	The vertical clearance height is less than required.	Provide recommended vertical clearance.	$108.00	ADA 307, 307.4, MA 20.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	The vertical clearance height is less than required.	Provide recommended vertical clearance.	$108.00	ADA 307, 307.4, MA 20.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Path of Travel	The vertical clearance height is less than required.	Provide recommended vertical clearance.	$108.00	ADA 307, 307.4, MA 20.7

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The length of the ramp exceeds the maximum distance allowed for its slope (rise).	Provide an intermediate landing on the ramp with a rise for each run of the ramp not exceeding 30 inches in height.	$3,168.00	ADA 405, 405.6, MA 24.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The length of the top landing does not meet the required minimum length.	Modify or replace the top landing to provide the required minimum length and width.	$2,872.00	ADA 405.7, 405.7.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The ends of the handrails end abruptly.	The handrails shall provide extensions that are parallel to the floor or ground surface extending the required distance beyond the top and bottom of the ramp and	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4, MA 24.5.9

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The length of the top landing does not meet the required minimum length.	Modify or replace the top landing to provide the required minimum length and width.	$2,872.00	ADA 405.7, 405.7.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The ends of the handrails end abruptly.	The handrails shall provide extensions that are parallel to the floor or ground surface extending the required distance beyond the top and bottom of the ramp and	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4, MA 24.5.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The ramp changes direction at this landing. The width of the landing is less than the required minimum width.	Modify or replace the landing to meet the minimum required width and length.	$3,168.00	ADA 405, 504.7.4, MA 24.4.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Elevators	There is no signage at the Elevator indicating the Evacuation Plan.	Provide compliant signage indicating Evacuation plan and routes.	$207.00	ADA 302, 407
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Elevators	The reopening device for the elevator door does not remain open for the required amount of time.	Contact a certified elevator provider to perform all renovation required.	$800.00	ADA 407, 407.3.3.3, MA 28.6

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Elevators	The hall direction lanterns do not function.	Contact a certified elevator provider to perform all renovation required.	$900.00	ADA 407, 407.2.2, MA 28.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Elevators	The hall direction lanterns do not provide a single audible signal for the up direction and a double audible signal for the down direction .	Contact a certified elevator provider to perform all renovation required.	$500.00	ADA 407, 407.2.2.3, MA 28.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Elevators	The hall direction lanterns do not register and extinguish to show each call.	Contact a certified elevator provider to perform all renovation required.	$500.00	ADA 407, 407.2.2.1, MA 28.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Elevators	The hall direction lanterns do not provide a single audible signal for the up direction and a double audible signal for the down direction .	Contact a certified elevator provider to perform all renovation required.	$500.00	ADA 407, 407.2.2.3, MA 28.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Elevators	The hall direction lanterns do not register and extinguish to show each call.	Contact a certified elevator provider to perform all renovation required.	$500.00	ADA 407, 407.2.2.1, MA 28.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Elevators	Main floor is not indicated with a star.	Make sure that main floor is indicated with a star.	$180.00	ADA 407, MA 28.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The width of the stairway does not meet the minimum required width.	Install a stairway with a minimum width as required.	$4,816.00	ADA 210, 504, MA 20.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The vertical clearance height of the open doorway is not compliant.	Provide a compliant open doorway at the location.	$5,600.00	ADA 307.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed for a vertical rise.	Modify or replace the threshold to provide the recommended height.	$257.00	ADA 404, 404.2.5, MA 26.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$100.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Counters	The height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	Provide a portion of counter at the compliant height.	$3,500.00	ADA 902, 904, MA 35.6, MA 7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no informational signage.	Install informational signage to each accessible element or room or location.	$158.00	ADA 216.3 , 703.5, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The length of the side grab bar is less than required.	Replace the side grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the primary age group.	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side and 24 inches of extension on the	$267.00	ADA 604.5.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 213, 604, 604.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for use by the primary age group.	$1,143.00	ADA 603, 604.9.1, MA 30.14.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The latch side approach to the compartment designated to be accessible in the restroom is not wide enough.	Provide a latch-side approach to the compartment designated to be accessible with a clear, unobstructed access width.	$4,000.00	ADA 603, 604.8.1.2, MA 30.6.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The clear opening width of the doorway to the compartment is less than required.	Widen the doorway to provide a compliant clear opening width when the door is open 90 degrees.	$4,000.00	ADA 404, 404.2.3, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment swings inward into the minimum required compartment area.	Modify the swing of the door so that it does not swing into the minimum required compartment area.	$269.00	ADA 304.4, 603, 604.8, MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish floor.	$291.00	ADA 213, 603, 603.3, MA 30.18
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory designated to be accessible in the restroom is less than the required minimum for the primary age group.	Reinstall or replace the lavatory designated to be accessible with an accessible lavatory that provides the required knee clearance for the primary age	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not a minimum of 56 inches of clearance around the water closet measured perpendicular from the rear wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches (1420 mm) minimum measured	$1,707.00	ADA 603, 604.3.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not a minimum of 56 inches of clearance around the water closet measured perpendicular from the rear wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches (1420 mm) minimum measured	$1,707.00	ADA 603, 604.3.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not a minimum of 56 inches of clearance around the water closet measured perpendicular from the rear wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches (1420 mm) minimum measured	$1,707.00	ADA 603, 604.3.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The length of the side grab bar is less than required.	Replace the side grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the primary age group.	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side and 24 inches of extension on the	$267.00	ADA 604.5.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 213, 604, 604.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The latch side approach to the compartment designated to be accessible in the restroom is not wide enough.	Provide a latch-side approach to the compartment designated to be accessible with a clear, unobstructed access width.	$4,000.00	ADA 603, 604.8.1.2, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side and 24 inches of extension on the	$267.00	ADA 604.5.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The entrance door swings into the turning space within the restroom.	Reverse the door swing, or modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$8,200.00	ADA 304, 305.3, 603.2, 603.2.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the urinal rim in the restroom is greater than the allowed maximum height for use by the primary age group.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than the allowed maximum height for use by the primary age group.	$1,397.00	ADA 605, 605.2, MA 30.17.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the urinal flush control in the restroom is greater than the allowed maximum height for use by the primary age group.	Lower the flush control valve on the urinal designated to be accessible in the restroom to a height no greater than the allowed maximum height for use by the	$227.00	ADA 308.2, 309.3, 605, 605.4

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The width between urinal shields in the restroom is less than required.	Modify or replace the urinal shields in the restroom to provide the required shield-width clearance.	$230.00	ADA 305.3, 605, 605.3, MA 30.10.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish floor.	$291.00	ADA 213, 603, 603.3, MA 30.18
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The latch side approach to the compartment designated to be accessible in the restroom is not wide enough.	Provide a latch-side approach to the compartment designated to be accessible with a clear, unobstructed access width.	$4,000.00	ADA 603, 604.8.1.2, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The clear opening width of the doorway to the compartment is less than required.	Widen the doorway to provide a compliant clear opening width when the door is open 90 degrees.	$4,000.00	ADA 404, 404.2.3, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The entrance door swings into the turning space within the restroom.	Reverse the door swing, or modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$8,200.00	ADA 304, 305.3, 603.2, 603.2.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish floor.	$291.00	ADA 213, 603, 603.3, MA 30.18
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish floor.	$291.00	ADA 213, 603, 603.3, MA 30.18
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The lavatory is in an enclosed cabinet, thereby preventing an accessible forward approach.	Lavatories in restrooms must provide clear floor space in front of the lavatory for an accessible forward approach and shall provide the minimum required primary age group knee and toe	$420.00	ADA 213, 606, 606.2, MA 30.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish floor.	$291.00	ADA 213, 603, 603.3, MA 30.18
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory designated to be accessible in the restroom is less than the required minimum for the primary age group.	Reinstall or replace the lavatory designated to be accessible with an accessible lavatory that provides the required knee clearance for the primary age	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The latch side approach to the compartment designated to be accessible in the restroom is not wide enough.	Provide a latch-side approach to the compartment designated to be accessible with a clear, unobstructed access width.	$4,000.00	ADA 603, 604.8.1.2, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side and 24 inches of extension on the	$267.00	ADA 604.5.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The width between urinal shields in the restroom is less than required.	Modify or replace the urinal shields in the restroom to provide the required shield-width clearance.	$230.00	ADA 305.3, 605, 605.3, MA 30.10.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There are grab bars missing from the toilet compartment.	Install the required grab bars in the toilet compartment.	$231.00	ADA 604.5, 604.9.4, 609, MA 30.15.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The clear opening width of the doorway to the compartment is less than required.	Widen the doorway to provide a compliant clear opening width when the door is open 90 degrees.	$4,000.00	ADA 404, 404.2.3, 604.8, MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment swings inward into the minimum required compartment area.	Modify the swing of the door so that it does not swing into the minimum required compartment area.	$269.00	ADA 304.4, 603, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not a minimum of 60 inches of clearance around the water closet measured perpendicular from the side wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches (1420 mm) minimum measured	$1,707.00	ADA 502.4, 603, 604.3.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side and 24 inches of extension on the	$267.00	ADA 604.5.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the primary age group.	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 213, 604, 604.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side and 24 inches of extension on the	$267.00	ADA 604.5.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front edge of the toilet seat.	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the toilet seat. Toilet paper dispensers	$277.00	ADA 603, 604.9.6, MA 30.14.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat in the restroom is greater than the allowed maximum height for use by the primary age group.	Adjust or modify the height of the toilet seat in the restroom to the required height for use by the primary age group.	$1,707.00	ADA 603, 604.9.3, MA 30.14.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish floor.	$291.00	ADA 213, 603, 603.3, MA 30.18
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the primary age group.	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 213, 604, 604.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front edge of the toilet seat.	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the toilet seat. Toilet paper dispensers	$277.00	ADA 603, 604.9.6, MA 30.14.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat in the restroom is greater than the allowed maximum height for use by the primary age group.	Adjust or modify the height of the toilet seat in the restroom to the required height for use by the primary age group.	$1,707.00	ADA 603, 604.9.3, MA 30.14.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish floor.	$291.00	ADA 213, 603, 603.3, MA 30.18
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The width between urinal shields in the restroom is less than required.	Modify or replace the urinal shields in the restroom to provide the required shield-width clearance.	$230.00	ADA 305.3, 605, 605.3, MA 30.10.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish floor.	$291.00	ADA 213, 603, 603.3, MA 30.18
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the primary age group.	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 213, 604, 604.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat in the restroom is greater than the allowed maximum height for use by the primary age group.	Adjust or modify the height of the toilet seat in the restroom to the required height for use by the primary age group.	$1,707.00	ADA 603, 604.9.3, MA 30.14.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for use by the primary age group.	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The faucet controls on the lavatory require tight grasping, pinching, or twisting of the wrist and are not accessible.	Install accessible faucet controls. Lever-operated, push-type, touch-type or electronically controlled mechanisms are acceptable elements. If self-closing valves are	$392.00	ADA 213, 309.4, 606, MA 30.9.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the urinal rim in the restroom is greater than the allowed maximum height for use by the primary age group.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than the allowed maximum height for use by the primary age group.	$1,397.00	ADA 605, 605.2, MA 30.17.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the urinal flush control in the restroom is greater than the allowed maximum height for use by the primary age group.	Lower the flush control valve on the urinal designated to be accessible in the restroom to a height no greater than the allowed maximum height for use by the	$227.00	ADA 308.2, 309.3, 605, 605.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The width between urinal shields in the restroom is less than required.	Modify or replace the urinal shields in the restroom to provide the required shield-width clearance.	$230.00	ADA 305.3, 605, 605.3, MA 30.10.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish floor.	$291.00	ADA 213, 603, 603.3, MA 30.18
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory designated to be accessible in the restroom is less than the required minimum for the primary age group.	Reinstall or replace the lavatory designated to be accessible with an accessible lavatory that provides the required knee clearance for the primary age	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the primary age group.	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 213, 604, 604.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front edge of the toilet seat.	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the toilet seat. Toilet paper dispensers	$277.00	ADA 603, 604.9.6, MA 30.14.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat in the restroom is greater than the allowed maximum height for use by the primary age group.	Adjust or modify the height of the toilet seat in the restroom to the required height for use by the primary age group.	$1,707.00	ADA 603, 604.9.3, MA 30.14.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for use by the primary age group.	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish floor.	$291.00	ADA 213, 603, 603.3, MA 30.18
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toe clearance for the toilet compartment does not meet the required minimum height.	In compartments provided primarily for children, the front partition and at least one side partition shall provide compliant toe clearance.	$4,000.00	ADA 603, 604.8.1.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment swings inward into the minimum required compartment area.	Modify the swing of the door so that it does not swing into the minimum required compartment area.	$269.00	ADA 304.4, 603, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the primary age group.	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 213, 604, 604.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front edge of the toilet seat.	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the toilet seat. Toilet paper dispensers	$277.00	ADA 603, 604.9.6, MA 30.14.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat in the restroom is greater than the allowed maximum height for use by the primary age group.	Adjust or modify the height of the toilet seat in the restroom to the required height for use by the primary age group.	$1,707.00	ADA 603, 604.9.3, MA 30.14.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the primary age group.	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 213, 604, 604.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front edge of the toilet seat.	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the toilet seat. Toilet paper dispensers	$277.00	ADA 603, 604.9.6, MA 30.14.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat in the restroom is greater than the allowed maximum height for use by the primary age group.	Adjust or modify the height of the toilet seat in the restroom to the required height for use by the primary age group.	$1,707.00	ADA 603, 604.9.3, MA 30.14.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for use by the primary age group.	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The faucet controls on the lavatory require tight grasping, pinching, or twisting of the wrist and are not accessible.	Install accessible faucet controls. Lever-operated, push-type, touch-type or electronically controlled mechanisms are acceptable elements. If self-closing valves are	$392.00	ADA 213, 309.4, 606, MA 30.9.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$277.00	ADA 205, 309, 309.4, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toe clearance for the toilet compartment does not meet the required minimum height.	In compartments provided primarily for children, the front partition and at least one side partition shall provide compliant toe clearance.	$4,000.00	ADA 603, 604.8.1.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the primary age group.	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 213, 604, 604.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat in the restroom is greater than the allowed maximum height for use by the primary age group.	Adjust or modify the height of the toilet seat in the restroom to the required height for use by the primary age group.	$1,707.00	ADA 603, 604.9.3, MA 30.14.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center line of the toilet to the nearest side wall in the restroom is not at the required distance.	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for use by the primary age group.	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the urinal rim in the restroom is greater than the allowed maximum height for use by the primary age group.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than the allowed maximum height for use by the primary age group.	$1,397.00	ADA 605, 605.2, MA 30.17.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The width between urinal shields in the restroom is less than required.	Modify or replace the urinal shields in the restroom to provide the required shield-width clearance.	$230.00	ADA 305.3, 605, 605.3, MA 30.10.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish floor.	$291.00	ADA 213, 603, 603.3, MA 30.18
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above the finish floor.	$291.00	ADA 213, 603, 603.3, MA 30.18

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for the primary age group.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for the primary age group.	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The clear opening width of the doorway to the compartment is less than required.	Widen the doorway to provide a compliant clear opening width when the door is open 90 degrees.	$4,000.00	ADA 404, 404.2.3, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The door to the compartment swings inward into the minimum required compartment area.	Modify the swing of the door so that it does not swing into the minimum required compartment area.	$269.00	ADA 304.4, 603, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The drinking fountain is a protruding object.	Make sure that the fountain is not a protruding object.	$550.00	ADA 211, 305, 306, 307.2, 602
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of the drinking fountain.	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The drinking fountain is a protruding object.	Make sure that the fountain is not a protruding object.	$550.00	ADA 211, 305, 306, 307.2, 602
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of the drinking fountain.	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The drinking fountain is a protruding object.	Make sure that the fountain is not a protruding object.	$550.00	ADA 211, 305, 306, 307.2, 602
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of the drinking fountain.	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The drinking fountain is a protruding object.	Make sure that the fountain is not a protruding object.	$550.00	ADA 211, 305, 306, 307.2, 602
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of the drinking fountain.	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The spout outlet height is greater than required.	Provide a spout outlet that does not exceed the required height.	$627.00	ADA 211, 602, 602.4, MA 36.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of the drinking fountain.	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The drinking fountain is a protruding object.	Make sure that the fountain is not a protruding object.	$550.00	ADA 211, 305, 306, 307.2, 602
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Drinking Fountains	The spout height is greater than the required maximum height for the primary age group.	The height of the spout outlet shall not exceed the maximum height for the primary age group.	$627.00	ADA 211, 305, 306, 602, 602.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Libraries	The height of the checkout counter is greater than 30 inches for use primarily by children.	Make sure a portion of the counter is within compliant height ranges to accommodate age group requirements for children.	$545.00	ADA 227, 902.4.2, 904
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Libraries	The knee clearance height at the table for use primarily by children is not compliant.	Provide a compliant table for use primarily by children.	$174.00	ADA 226, 306, 902
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Libraries	The space between book shelves is less than required value.	Increase the space between shelves to the recommended value.	$2,160.00	ADA 403
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Food Service	There is less than the required percentage of accessible tables/seating provided.	Provide the minimum required percentage of the total seating capacity with accessible seating.	$2,500.00	ADA 206, 226.1, 305, MA 35.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Food Service	The width of the aisle at the food service line is less than required.	Widen the aisle at the food service line to provide required width, or a preferred clear width to allow passage around an individual using a wheelchair.	$1,200.00	ADA 403, 904.2, MA 17.6.1

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Food Service	The height of the tray return is greater than the allowed maximum height for the primary age group.	Lower the tops of the tray return to the required accessible level for the primary age group.	$1,200.00	ADA 403, 902, 902.4.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Food Service	The knee space at the table is less than required for the primary age group.	Modify or replace one or more of the tables in the food service area to meet the required minimum accessible seating for the primary age group.	$2,174.00	ADA 306, 306.3, 902.4.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Food Service	The knee space at the table is less than required for the primary age group.	Modify or replace one or more of the tables in the food service area to meet the required minimum accessible seating for the primary age group.	$2,174.00	ADA 306, 306.3.5, 902.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Assembly Areas	There is no signage at the ticket counter indicating the availability of accessible seating.	Post signage at the ticket counter indicating the availability and location of accessible seating areas.	$207.00	ADA 221, MA 14.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Assembly Areas	Wheelchair Locations are not dispersed among other seating.	Disperse the Wheelchairs among other seating	$1,840.00	ADA 225, 802
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Assembly Areas	Wheelchair seating areas are not marked with the International Symbol of Accessibility to reserve them for wheelchair users.	Wheelchair seating areas should be marked with the International Symbol of Accessibility to reserve them for wheelchair users.	$50.00	ADA 216, 703, MA 41.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Assembly Areas	Wheelchair seating areas are not marked with the International Symbol of Accessibility to reserve them for wheelchair users.	Wheelchair seating areas should be marked with the International Symbol of Accessibility to reserve them for wheelchair users.	$50.00	ADA 216, 703, MA 41.7

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Assembly Areas	Ground and Floor Surfaces around wheelchair location are not clear.	Ground and Floor Surfaces around wheelchair location must be smooth and clear.	$1,260.00	ADA 225, 802
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Assembly Areas	Wheelchair seating areas are not marked with the International Symbol of Accessibility to reserve them for wheelchair users.	Wheelchair seating areas should be marked with the International Symbol of Accessibility to reserve them for wheelchair users.	$50.00	ADA 216, 703, MA 41.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Assembly Areas	Wheelchair seating areas are not marked with the International Symbol of Accessibility to reserve them for wheelchair users.	Wheelchair seating areas should be marked with the International Symbol of Accessibility to reserve them for wheelchair users.	$50.00	ADA 216, 703, MA 41.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Assembly Areas	Ground and Floor Surfaces around wheelchair location are not clear.	Ground and Floor Surfaces around wheelchair location must be smooth and clear.	$1,260.00	ADA 225, 802
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Assembly Areas	Wheelchair seating areas are not marked with the International Symbol of Accessibility to reserve them for wheelchair users.	Wheelchair seating areas should be marked with the International Symbol of Accessibility to reserve them for wheelchair users.	$50.00	ADA 216, 703, MA 41.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Assembly Areas	Wheelchair seating areas are not marked with the International Symbol of Accessibility to reserve them for wheelchair users.	Wheelchair seating areas should be marked with the International Symbol of Accessibility to reserve them for wheelchair users.	$50.00	ADA 216, 703, MA 41.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Assembly Areas	Wheelchair Location companion seat is not marked with ISA symbol.	Make sure that there is an ISA symbol at the companion seat.	$50.00	ADA 225, 802

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Assembly Areas	There are not enough accessible seats at the location with respect to the total number of seats available.	Provide compliant accessible seating at the location.	$600.00	ADA 221.2 , 802.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	There is no companion fixed seat provided next to each wheelchair seating area.	Provide at least one companion fixed seat next to each wheelchair seating area.	$1,840.00	ADA 225, 802, MA 14.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	The width of the wheelchair seating space, accessed from the front or rear, is not compliant.	Provide a compliant wheelchair seating space.	$1,840.00	ADA 225, 802, 802.1.2, MA 14.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	The slope of the surface for the wheelchair location is greater than allowed.	The ground or floor at wheelchair locations shall be level and shall be stable, firm and slip-resistant)	$1,840.00	ADA 402, MA 20.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	There is no companion fixed seat provided next to each wheelchair seating area.	Provide at least one companion fixed seat next to each wheelchair seating area.	$1,840.00	ADA 225, 802, MA 14.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	The width of the wheelchair seating space, accessed from the front or rear, is not compliant.	Provide a compliant wheelchair seating space.	$1,840.00	ADA 225, 802, 802.1.2, MA 14.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	The slope of the surface for the wheelchair location is greater than allowed.	The ground or floor at wheelchair locations shall be level and shall be stable, firm and slip-resistant)	$1,840.00	ADA 402, MA 20.9

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	There is no companion fixed seat provided next to each wheelchair seating area.	Provide at least one companion fixed seat next to each wheelchair seating area.	$1,840.00	ADA 225, 802, MA 14.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	The width of the wheelchair seating space, accessed from the front or rear, is not compliant.	Provide a compliant wheelchair seating space.	$1,840.00	ADA 225, 802, 802.1.2, MA 14.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	The slope of the surface for the wheelchair location is greater than allowed.	The ground or floor at wheelchair locations shall be level and shall be stable, firm and slip-resistant)	$1,840.00	ADA 402, MA 20.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	There is no companion fixed seat provided next to each wheelchair seating area.	Provide at least one companion fixed seat next to each wheelchair seating area.	$1,840.00	ADA 225, 802, MA 14.4.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	The width of the wheelchair seating space, accessed from the front or rear, is not compliant.	Provide a compliant wheelchair seating space.	$1,840.00	ADA 225, 802, 802.1.2, MA 14.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	The slope of the surface for the wheelchair location is greater than allowed.	The ground or floor at wheelchair locations shall be level and shall be stable, firm and slip-resistant)	$1,840.00	ADA 402, MA 20.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	There is no companion fixed seat provided next to each wheelchair seating area.	Provide at least one companion fixed seat next to each wheelchair seating area.	$1,840.00	ADA 225, 802, MA 14.4.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	The width of the wheelchair seating space, accessed from the front or rear, is not compliant.	Provide a compliant wheelchair seating space.	$1,840.00	ADA 225, 802, 802.1.2, MA 14.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	The slope of the surface for the wheelchair location is greater than allowed.	The ground or floor at wheelchair locations shall be level and shall be stable, firm and slip-resistant)	$1,840.00	ADA 402, MA 20.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	The width of the wheelchair seating space, accessed from the front or rear, is not compliant.	Provide a compliant wheelchair seating space.	$1,840.00	ADA 225, 802, 802.1.2, MA 14.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	The slope of the surface for the wheelchair location is greater than allowed.	The ground or floor at wheelchair locations shall be level and shall be stable, firm and slip-resistant)	$1,840.00	ADA 402, MA 20.9
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	There are not enough accessible seats at the location with respect to the total number of seats available.	Provide compliant accessible seating at the location.	$600.00	ADA 221.2 , 802.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Outdoor Sports Areas	There are not enough accessible seats at the location with respect to the total number of seats available.	Provide compliant accessible seating at the location.	$600.00	ADA 221.2 , 802.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Locker Rooms	No accessible lockers were found.	At least one locker or 5% of the lockers should be accessible.	$1,840.00	ADA 222, 225.2.1 , 803, 811, F222.1, MA 19.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Locker Rooms	The bench is not fixed to the wall along the longer dimension.	Install a compliant bench in the locker room. Provide sufficient clear floor space alongside the the bench to allow a person using a wheelchair to transfer on to the	$500.00	ADA 222, 803, 803.4, 903.4, MA 33.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Locker Rooms	The width of the bench is not compliant.	Install a compliant bench in the locker room. Provide sufficient clear floor space alongside the the bench to allow a person using a wheelchair to transfer on to the	$500.00	ADA 222, 803, 803.4, 903.3, MA 33.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Locker Rooms	No accessible lockers were found.	At least one locker or 5% of the lockers should be accessible.	$1,840.00	ADA 222, 225.2.1 , 803, 811, F222.1, MA 19.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Locker Rooms	The width of the bench is not compliant.	Install a compliant bench in the locker room. Provide sufficient clear floor space alongside the the bench to allow a person using a wheelchair to transfer on to the	$500.00	ADA 222, 803, 803.4, 903.3, MA 33.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Locker Rooms	The height of the bench is not compliant.	Install a compliant bench in the locker room. Provide sufficient clear floor space alongside the the bench to allow a person using a wheelchair to transfer on to the	$500.00	ADA 222, 803, 803.4, 903.5, MA 33.6
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Locker Rooms	There is no full-length mirror in the locker room.	Install a full-length mirror in each locker room.	$350.00	ADA 222, 803, MA 33.7
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Play Area	The width of the path of travel to the play area is not compliant.	Provide a compliant accessible route to the play area.	$500.00	ADA 1008, 1008.2, 1008.2.4, 240

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Play Area	There is a change in level to the play area surface.	Provide a smooth transition from the play area access point to the play area surface.	$150.00	ADA 1008, 1008.2, 240, 403.4
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Emergency Warning Systems	There are some visual warning devices, though visual warning devices are not located throughout the facility.	Install visual warning devices integrated with the facility's alarm system in all common areas such as hallways, classrooms and general use rooms, accessible	$2,200.00	ADA 215, 702, MA 40.1
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	The side reach height of the controls on the vending machine is greater than the allowed maximum height.	Provide a compliant vending machine.		ADA 308
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	The controls of the vending machine require tight grasping, pinching, or twisting of the wrist.	Replace controls of vending machine with those that allow operation with one hand and does not require tight grasping, pinching, or twisting of the wrist.		ADA 305
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	The side reach height of the controls on the vending machine is greater than the allowed maximum height.	Provide a compliant vending machine.		ADA 308
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	Sink counter height does not meet the standards.	Provide compliant sink.	$1,800.00	ADA 606.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	The pipes are not wrapped for the sink.	Insulate or otherwise configure the water supply and drain pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under	$149.00	ADA 606.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	The cabinet door hardware is not accessible.	Provide compliant hardware for the cabinet door.	$1,000.00	ADA 205, 228, 308, 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	The toe kick for the sink in break/conference room is not removed.	Remove the toe kick for the sink.	$612.00	ADA 305, 306, 606.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	Supply lines are not wrapped for the break/conference room sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$220.00	ADA 205, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	The table knee clearance does not meet required standards.	Provide compliant tables.	$500.00	ADA 305, 306, 902.2

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Break/Conference Room	The table knee depth does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 306.3.3, 308, 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 606.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The cabinet door hardware is not accessible.	Provide compliant hardware for cabinet door.	$190.00	ADA 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The cabinet door hardware is not accessible.	Provide compliant hardware for cabinet door.	$190.00	ADA 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The cabinet door hardware is not accessible.	Provide compliant hardware for cabinet door.	$190.00	ADA 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$980.00	ADA 309, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$980.00	ADA 309, MA 39.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 606.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The cabinet door hardware is not accessible.	Provide compliant hardware for cabinet door.	$190.00	ADA 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 606.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The cabinet door hardware is not accessible.	Provide compliant hardware for cabinet door.	$190.00	ADA 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 606.3
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The cabinet door hardware is not accessible.	Provide compliant hardware for cabinet door.	$190.00	ADA 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$980.00	ADA 309, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$980.00	ADA 309, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The cabinet door hardware is not accessible.	Provide compliant hardware for cabinet door.	$190.00	ADA 309

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the primary age group.	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the primary age group.	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$980.00	ADA 309, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The cabinet door hardware is not accessible.	Provide compliant hardware for cabinet door.	$190.00	ADA 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the primary age group.	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the primary age group.	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$980.00	ADA 309, MA 39.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The cabinet door hardware is not accessible.	Provide compliant hardware for cabinet door.	$190.00	ADA 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the primary age group.	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the primary age group.	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of the wrist. The force required to	$980.00	ADA 309, MA 39.5

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Picnic Areas	There is no accessible route to the picnic tables.	Provide an accessible route to the picnic tables.	$1,440.00	ADA 205, 226, 228, 308, 309, 402, 403
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Lockers	No accessible lockers were found.	At least one locker or 5% of the lockers should be accessible.	$1,840.00	ADA 225.2.1 , 811
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Lockers	No accessible lockers were found.	At least one locker or 5% of the lockers should be accessible.	$1,840.00	ADA 225.2.1 , 811
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Accessible Showers	There are not enough accessible showers with respect to the total number of showers available.	Provide the required amount of compliant accessible showers.	$4,500.00	ADA 213, 213.3.6, 608
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Accessible Showers	There are not enough accessible showers with respect to the total number of showers available.	Provide the required amount of compliant accessible showers.	$4,500.00	ADA 213, 213.3.6, 608
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Reach Ranges	The clear floor space width is not compliant.	Provide compliant clear floor space.	$500.00	ADA 304, 305.3

Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Nathaniel Wixon School - 901 Route 134 South Dennis, MA 02660	Medical Rooms	This room provides insufficient space for maneuvering.	Rearrange furnishings in room or remodel room to provide greater maneuvering space.		
Old Fish House Road - 79 Old Fish House Road South Dennis, MA 02660	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
Old Fish House Road - 79 Old Fish House Road South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Old Fish House Road - 79 Old Fish House Road South Dennis, MA 02660	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903

Old Main - 29 Old Main Street West Dennis, MA 02670	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
Old Main - 29 Old Main Street West Dennis, MA 02670	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Path of Travel	The surface of the primary accessible path of travel is rough and uneven, providing a hazardous surface for individuals with mobility impairments	Resurface the path of travel to provide a smooth, firm, stable and slip-resistant surface.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10

Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth,	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3

Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth,	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2

Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The faucet controls on the lavatory require tight grasping, pinching, or twisting of the wrist and are not accessible.	Install accessible faucet controls. Lever-operated, push-type, touch-type or electronically controlled mechanisms are acceptable	$392.00	ADA 213, 309.4, 606, MA 30.9.6
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The height of the counter surface is greater than allowed.	Relocate or replace the lavatory to provide a maximum counter surface height of no greater than recommended.	$1,286.00	ADA 213, 606, 606.3, MA 30.9.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The faucet controls on the lavatory require tight grasping, pinching, or twisting of the wrist and are not accessible.	Install accessible faucet controls. Lever-operated, push-type, touch-type or electronically controlled mechanisms are acceptable	$392.00	ADA 213, 309.4, 606, MA 30.9.6
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The height of the counter surface is greater than allowed.	Relocate or replace the lavatory to provide a maximum counter surface height of no greater than recommended.	$1,286.00	ADA 213, 606, 606.3, MA 30.9.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5

Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet	$277.00	ADA 603, 604.7, MA 30.7.6
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2

Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous	$277.00	ADA 603, 609.3, MA 30.7.6
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Play Area	The play area is not located on an accessible route.	Provide a compliant accessible route to the play area.	$1,440.00	ADA 1008, 1008.2, 240, 402.1
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Play Area	The play area provides no accessible point of access.	Provide compliant access to the play area.	$2,400.00	ADA 1008, 1008.2, 240

Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$100.00	ADA 308, 309
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Trails	The condition of the trail cannot be inspected and trail compliance is not feasible due to terrain or other conditional exceptions like the Endangered Species Act, National Environmental Policy Act, National	Further study may need to be required.		ADA 1017.1 , 1019.1 , 1019.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Trails	Trail has a tread obstacle.	Remove the tread obstacle.		ADA 1017.5.2
Princess Beach - 178 Scargo Hill Road Dennis, MA 02638	Trails	There is no compliant signage.	Provide compliant signage with characters and numbers that are properly sized for viewing distance.		ADA 1017.11, F247.4.1
Quivet Creek/Bound Brook - 750 Airline Road Brewster, MA 02631	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2

Quivet Creek/Bound Brook - 750 Airline Road Brewster, MA 02631	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-accessible. The parking lot can provide parking spaces.	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Quivet Creek/Bound Brook - 750 Airline Road Brewster, MA 02631	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to accessible building entrances at	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Quivet Creek/Bound Brook - 750 Airline Road Brewster, MA 02631	Stairs	There are no handrails provided on the stairway.	Provide compliant handrails.	$1,528.00	ADA 504, 504.6 , 505.2, MA 27.4
Quivet Creek/Bound Brook - 750 Airline Road Brewster, MA 02631	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2
Quivet Creek/Bound Brook - 750 Airline Road Brewster, MA 02631	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Quivet Creek/Bound Brook - 750 Airline Road Brewster, MA 02631	Trails	The leading edge of the object protrudes into path of travel greater than allowed.	Modify, relocate, or lower the item so that the leading edge protrudes less than recommended value.		ADA 1017.9 , 307.2

Quivet Creek/Bound Brook - 750 Airline Road Brewster, MA 02631	Trails	The clear ground space is not on an accessible route.	Make sure that clear ground space is on an accessible route.		ADA 1011.2.1
Quivet Creek/Bound Brook - 750 Airline Road Brewster, MA 02631	Trails	There is no compliant signage.	Provide compliant signage with characters and numbers that are properly sized for viewing distance.		ADA 1017.11, F247.4.1
Quivet Creek/Bound Brook - 750 Airline Road Brewster, MA 02631	Trails	Trail slope is not compliant.	Readjust the trail surface slope to the recommended value.		ADA 1017.7.1
Quivet Creek/Bound Brook - 750 Airline Road Brewster, MA 02631	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.		ADA 1017.7.2
Quivet Creek/Bound Brook - 750 Airline Road Brewster, MA 02631	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.		ADA 1017.7.2
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Passenger Loading Zones	There are curbs between the access aisle and the vehicle pull-up space.	Remove curbs or install compliant curb ramp to provide accessible path of travel from the vehicle pull-up space and the access aisle.	$150.00	ADA 502, 503, 503.4, MA 23.7

Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Passenger Loading Zones	There is no required striped access aisle adjacent to the passenger loading zone.	Create an access aisle to meet the required minimum width and length adjacent and parallel to the vehicle pull-up space. The access	$650.00	ADA 502, 503, 503.3, MA 23.7
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Passenger Loading Zones	Passenger loading zone has no sign.	Mark the passenger loading zone with ISA symbol of accessibility.	$220.00	ADA 503.3.3
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2

Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Raycroft Beach - 395 Old Warf Road Dennis Port, MA 02639	Benches	Clear floor space slope is not compliant for the bench.	Provide compliant clear floor space at the bench.	$1,840.00	ADA 305, 903.2
Scargo Beach - Dr Lord's Road South Dennis, MA 02638	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Scargo Beach - Dr Lord's Road South Dennis, MA 02638	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502

Scargo Beach - Dr Lord's Road South Dennis, MA 02638	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
Scargo Beach - Dr Lord's Road South Dennis, MA 02638	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Scargo Beach - Dr Lord's Road South Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Scargo Beach - Dr Lord's Road South Dennis, MA 02638	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Scargo Lake - Boat Launch Between 955 & 965 Route 6A Dennis, MA 02638	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
Scargo Lake - Boat Launch Between 955 & 965 Route 6A Dennis, MA 02638	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Scargo Lake - Boat Launch Between 955 & 965 Route 6A Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Scargo Lake - Boat Launch Between 955 & 965 Route 6A Dennis, MA 02638	Fishing Piers	Pier/Platform walking surface is not compliant.	Provide compliant walking surface with recommended value at the pier/platform.		
Scargo Lake - Boat Launch Between 955 & 965 Route 6A Dennis, MA 02638	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Passenger Loading Zones	The slope of the surface for the access aisle at the passenger loading zone is greater than required.	Resurface the passenger loading zone to provide a level surface or one that does not exceed the maximum slope in any direction.	$2,900.00	ADA 502, 503, 503.4, MA 23.7

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Passenger Loading Zones	Passenger loading zone has no sign.	Mark the passenger loading zone with ISA symbol of accessibility.	$220.00	ADA 503.3.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The treads do not have a compliant depth.	Modify or replace the stairs to provide compliant treads.	$8,520.00	ADA 504, 504.2, MA 27.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The treads do not have a compliant depth.	Modify or replace the stairs to provide compliant treads.	$8,520.00	ADA 504, 504.2, MA 27.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth, uninterrupted gripping surface.	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth, uninterrupted gripping surface.	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth, uninterrupted gripping surface.	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth, uninterrupted gripping surface.	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth, uninterrupted gripping surface.	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth, uninterrupted gripping surface.	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The treads do not have a compliant depth.	Modify or replace the stairs to provide compliant treads.	$8,520.00	ADA 504, 504.2, MA 27.2

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The treads do not have a compliant depth.	Modify or replace the stairs to provide compliant treads.	$8,520.00	ADA 504, 504.2, MA 27.2

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The projection of the nosing on the stairway is greater than required.	Modify the nosing on the stairway so that the nosing is curved or beveled and do not project more than required over the tread below.	$3,888.00	ADA 504, 504.5, MA 27.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth, uninterrupted gripping surface.	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth, uninterrupted gripping surface.	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5

Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Reach Ranges	The clear floor space slope is not compliant.	Provide compliant clear floor space.	$500.00	ADA 304
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Sea Street Beach (South) - 5 Sea Street Dennis Port, MA 02639	Benches	No clear floor space provided at the bench.	Provide compliant clear floor space for the bench at one end.	$1,840.00	ADA 305, 903.2
Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3

Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Parking	The accessible parking space outline is faded, damaged, missing or otherwise not viewable.	Re-stripe the existing parking space marked as accessible to define the width of the space.	$350.00	ADA 502, 502.2, MA 23.4.5
Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6

Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Reach Ranges	Element reach depth is not compliant.	Make sure that the element is within allowed reach range with recommended reach depth.	$550.00	ADA 308
Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Reach Ranges	The clear floor space slope is not compliant.	Provide compliant clear floor space.	$500.00	ADA 304
Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Sea Street Beach Access (North) - Sea Street South Dennis, MA 02660	Benches	No clear floor space provided at the bench.	Provide compliant clear floor space for the bench at one end.	$1,840.00	ADA 305, 903.2
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Parking	There is no device at the head of the general parking spaces to prevent vehicles from encroaching into walkways.	Install a wheel stop at the head of the general parking spaces.	$148.00	ADA 502, 502.7, MA 23.4.2
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502

Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Parking	The accessible parking space outline is faded, damaged, missing or otherwise not viewable.	Re-stripe the existing parking space marked as accessible to define the width of the space.	$350.00	ADA 502, 502.2, MA 23.4.5
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Parking	The access aisle markings are faded, damaged, or otherwise not viewable.	Re-stripe the access aisle so as to discourage parking.	$250.00	ADA 502.3, 502.3.3
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Passenger Loading Zones	There is no required striped access aisle adjacent to the passenger loading zone.	Create an access aisle to meet the required minimum width and length adjacent and parallel to the vehicle pull-up space. The access aisle striping for the passenger	$650.00	ADA 502, 503, 503.3, MA 23.7
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Passenger Loading Zones	Passenger loading zone has no sign.	Mark the passenger loading zone with ISA symbol of accessibility.	$220.00	ADA 503.3.3

Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	The width of the path of travel is insufficient.	Widen the primary path of travel to provide the correct width.	$3,500.00	ADA 403.5.1, MA 20.3
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	Walking surface has an opening that is not compliant.	Make sure that the walking surface opening does not allow passage of a sphere more than ½ inch in diameter.	$185.00	ADA 302.3
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$300.00	ADA 303, 403.4, MA 20.10
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9

Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	The surface of the primary accessible path of travel is rough and uneven, providing a hazardous surface for individuals with mobility impairments and the general public.	Resurface the path of travel to provide a smooth, firm, stable and slip-resistant surface.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10

Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Doors	There is no level landing at this door.	Provide a level landing.	$3,000.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$560.00	ADA 404, 404.2.7
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$4,000.00	ADA 404, 404.2.10
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Play Area	The width of the path of travel to the play area is not compliant.	Provide a compliant accessible route to the play area.	$500.00	ADA 1008, 1008.2, 1008.2.4, 240

Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Play Area	The average depth of the surface material for the play area is not compliant.	Provide compliant surface material at the play area.	$11.00	ADA 1008.2.6
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Play Area	There is no transfer platform provided for the elevated play equipment.	Provide a compliant transfer platform to the elevated play equipment.	$3,360.00	ADA 1008, 1008.3.1
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Play Area	The width of the path of travel to the play area is not compliant.	Provide a compliant accessible route to the play area.	$500.00	ADA 1008, 1008.2, 1008.2.4, 240
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Play Area	The average depth of the surface material for the play area is not compliant.	Provide compliant surface material at the play area.	$11.00	ADA 1008.2.6
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Play Area	The transfer platform height is not compliant.	Provide compliant platform with recommended value at the transfer point.	$320.00	ADA 1008, 1008.3.1.2
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Play Area	The transfer platform is not located on shortest route from the play areas accessible point of access.	The transfer platform shall be located on the shortest route from the play areas accessible point of access.	$320.00	ADA 1008, 1008.2
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Play Area	The tread depth of the steps is not compliant.	Provide steps with compliant tread depth.	$34.75	ADA 1008, 1008.3.2.1

Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Play Area	All risers are not closed.	All risers shall be closed.	$320.00	ADA 1008
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Picnic Areas	There is no accessible route to the picnic tables.	Provide an accessible route to the picnic tables.	$1,440.00	ADA 205, 226, 228, 308, 309, 402, 403
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Picnic Areas	The length of the clear floor space at the table is not compliant.	Provide compliant clear floor space at the table.	$1,260.00	ADA 305.3, 902.2
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Reach Ranges	Element reach depth is not compliant.	Make sure that the element is within allowed reach range with recommended reach depth.	$550.00	ADA 308
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309

Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Reach Ranges	The knee height is not compliant.	Adjust knee height to the recommended value.	$2,000.00	ADA 226, 304, 306, 902
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Benches	Clear floor space slope is not compliant for the bench.	Provide compliant clear floor space at the bench.	$1,840.00	ADA 305, 903.2
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Viewing Area	The viewing area does not have an unobstructed view above 32".	Make sure that there is at least 32" of unobstructed view from floor.		ADA 1015
Sea View Park & Beach - 475 Lower County Road Dennis Port, MA 02639	Viewing Area	The guardrail height is not compliant.	Provide a compliant guardrail.	$243.80	ADA 1015
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6

Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	The vertical clearance height is less than required.	Provide recommended vertical clearance.	$108.00	ADA 307, 307.4, MA 20.7
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to accessible building entrances at	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6

Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition.	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition.	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Play Area	The width of the path of travel to the play area is not compliant.	Provide a compliant accessible route to the play area.	$500.00	ADA 1008, 1008.2, 1008.2.4, 240
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Play Area	The transfer platform height is not compliant.	Provide compliant platform with recommended value at the transfer point.	$320.00	ADA 1008, 1008.3.1.2

Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Play Area	Transfer platform depth is not compliant.	Provide compliant platform with recommended value at the transfer point.	$320.00	ADA 1008, 1008.3.1.1
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Play Area	Transfer platform width is not compliant.	Provide compliant platform with recommended value at the transfer point.	$320.00	ADA 1008, 1008.3.1.1
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Play Area	The tread depth of the steps is not compliant.	Provide steps with compliant tread depth.	$34.75	ADA 1008, 1008.3.2.1
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Play Area	The width of the steps is not compliant.	Provide steps with a compliant width.	$280.00	ADA 1008, 1008.3.2.1
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Play Area	The height of the steps is not compliant.	Provide steps with a compliant riser height.	$280.00	ADA 1008, 1008.3.2.2
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Play Area	The point of operation height for the play equipment is not compliant.	Provide compliant play equipment.	$1,500.00	ADA 1008, 1008.4.2, 308.1

Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Play Area	The width of the path of travel to the play area is not compliant.	Provide a compliant accessible route to the play area.	$500.00	ADA 1008, 1008.2, 1008.2.4, 240
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Play Area	The tread depth of the steps is not compliant.	Provide steps with compliant tread depth.	$34.75	ADA 1008, 1008.3.2.1
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Play Area	The height of the steps is not compliant.	Provide steps with a compliant riser height.	$280.00	ADA 1008, 1008.3.2.2
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Picnic Areas	There is no accessible route to the picnic tables.	Provide an accessible route to the picnic tables.	$1,440.00	ADA 205, 226, 228, 308, 309, 402, 403
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Reach Ranges	The knee height is not compliant.	Adjust knee height to the recommended value.	$500.00	ADA 226, 304, 306, 902

Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Sea View Playland Equipment - 475 Lower County Road Dennis Port, MA 02639	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking space.	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle that may be shared.	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502

Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	There is an accessible parking space designated in the parking lot. There is no access aisle located at the parking space.	Provide a compliant access aisle at the parking space. Parking spaces shall each provide an access aisle that may be shared.	$370.00	ADA 502, 502.3, 502.3.4, MA 23.4.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6

Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Ramps	There is no top landing on the ramp.	Modify or replace the ramp so that it has a top landing.	$3,168.00	ADA 405, 405.7, MA 24.4
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4

Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4, MA 24.5.9
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4, MA 24.5.9
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Stairs	The width of the stairway does not meet the minimum required width.	Install a stairway with a minimum width as required.	$8,572.00	ADA 210, 504, MA 20.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4

Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7

Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door.	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7

Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Counters	The height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	Provide a portion of counter at the compliant height.	$3,500.00	ADA 902, 904, MA 35.6, MA 7.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The shields extend greater than 24” in front of the urinal. The width between the shields is less than required.	Modify or replace the urinal shields in the restroom to provide the required clearance between the shields for the urinal	$1,800.00	ADA 305.7, 605, 605.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The faucet controls on the lavatory require tight grasping, pinching, or twisting of the wrist and are not accessible.	Install accessible faucet controls. Lever-operated, push-type, touch-type or electronically controlled mechanisms are acceptable	$392.00	ADA 213, 309.4, 606, MA 30.9.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3

Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The approach is to the latch side of the compartment door, clearance between the door side of the compartment and any obstruction	Provide clearance between the door side of the compartment and any obstruction that meets the minimum required clearance.	$4,000.00	ADA 404.2, 603, 604.8.1.2, MA 30.6.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2

Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet	$277.00	ADA 603, 604.7, MA 30.7.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2

Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The distance between the wall and the gripping surface of the grab bar does not meet requirements.	Remount the grab bar so the space between the wall and gripping surface meets requirements. Grab bars must be able to support a	$250.00	ADA 505, 604.9.3, 609.3, MA 30.8.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic	$127.00	ADA 603, 604.6, MA 30.7.5
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11

Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Accessible Showers	There are not enough accessible showers with respect to the total number of showers available.	Provide the required amount of compliant accessible showers.	$4,500.00	ADA 213, 213.3.6, 608
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Fishing Piers	Change in level height at bottom is not compliant.	Provide compliant gangway.		
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Fishing Piers	Change in level height at bottom is not compliant.	Provide compliant gangway.		

Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Fishing Piers	Pier/Platform walking surface is not compliant.	Provide compliant walking surface with recommended value at the pier/platform.		
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Fishing Piers	Walking surface gap space width is is not compliant.	Provide compliant walking surface for the pier/platform.		
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Fishing Piers	Change in level height at bottom is not compliant.	Provide compliant gangway.		
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3
Sesuit Harbor - 351 Sesuit Neck Road South Dennis, MA 02660	Fishing Piers	Walking surface gap space width is is not compliant.	Provide compliant walking surface for the pier/platform.		
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1

Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to accessible building entrances at	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition.	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Picnic Areas	There is no accessible route to the picnic tables.	Provide an accessible route to the picnic tables.	$1,440.00	ADA 205, 226, 228, 308, 309, 402, 403

Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Exhibits	Display is not on an accessible route.	All exhibit displays shall be on an accessible route.		
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	Trail has a tread obstacle.	Remove the tread obstacle.		
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	Trail has a tread obstacle.	Remove the tread obstacle.		ADA 1017.5.2
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	Trail signage does not indicate length of trail.	Provide compliant signage for the trail that includes length of trail.		ADA 1017.11, F247.4.1

Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	Trail signage does not indicate length of trail.	Provide compliant signage for the trail that includes length of trail.	ADA 1017.11, F247.4.1
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	There is no compliant signage.	Provide compliant signage with characters and numbers that are properly sized for viewing distance.	ADA 1017.11, F247.4.1
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	Trail slope is not compliant.	Readjust the trail surface slope to the recommended value.	ADA 1017.7.1

Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.	ADA 1017.7.2
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.	ADA 1017.3
Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	Trail slope is not compliant.	Readjust the trail surface slope to the recommended value.	ADA 1017.7.1

Shoop Community Gardens - 1791 Main Street Route 6A South Dennis, MA 02660	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.		ADA 1017.7.2
South Village Beach - 21 & 27 South Village Road West Dennis, MA 02670	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
South Village Beach - 21 & 27 South Village Road West Dennis, MA 02670	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
South Village Beach - 21 & 27 South Village Road West Dennis, MA 02670	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
South Village Beach - 21 & 27 South Village Road West Dennis, MA 02670	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
South Village Beach - 21 & 27 South Village Road West Dennis, MA 02670	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
South Village Beach - 21 & 27 South Village Road West Dennis, MA 02670	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304

Swan Pond Overlook - 435 Center Street Dennis Port, MA 02639	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
Swan Pond Overlook - 435 Center Street Dennis Port, MA 02639	Path of Travel	The path of travel is grass, dirt, or gravel, preventing access to individuals with mobility impairments.	Provide an accessible route.	$1,840.00	ADA 302, 303, 403.2, MA 29.1
Swan Pond Overlook - 435 Center Street Dennis Port, MA 02639	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Swan Pond Overlook - 435 Center Street Dennis Port, MA 02639	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
Taunton Avenue Beach / Dr Bottero Road - 152 Taunton Avenue Dennis, MA 02638	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Taunton Avenue Beach / Dr Bottero Road - 152 Taunton Avenue Dennis, MA 02638	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
the Plashes - 70 Toms Path Dennis Port, MA 02639	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2

the Plashes - 70 Toms Path Dennis Port, MA 02639	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
the Plashes - 70 Toms Path Dennis Port, MA 02639	Trails	The leading edge of the object protrudes into path of travel greater than allowed.	Modify, relocate, or lower the item so that the leading edge protrudes less than recommended value.		ADA 1017.9 , 307.2
the Plashes - 70 Toms Path Dennis Port, MA 02639	Trails	Trail has a tread obstacle.	Remove the tread obstacle.		ADA 1017.5.2
the Plashes - 70 Toms Path Dennis Port, MA 02639	Trails	There is no compliant signage.	Provide compliant signage with characters and numbers that are properly sized for viewing distance.		ADA 1017.11, F247.4.1
the Plashes - 70 Toms Path Dennis Port, MA 02639	Trails	There is no compliant signage.	Provide compliant signage with characters and numbers that are properly sized for viewing distance.		ADA 1017.11, F247.4.1
the Plashes - 70 Toms Path Dennis Port, MA 02639	Trails	Trail tread width is not compliant.	Provide a compliant trail tread width at the specified segment.		ADA 1017.3
the Plashes - 70 Toms Path Dennis Port, MA 02639	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.		ADA 1017.7.2
the Plashes - 70 Toms Path Dennis Port, MA 02639	Trails	The cross slope of the trail is not compliant.	Provide a compliant cross slope on the trail.		ADA 1017.7.2

Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	There is no device at the head of the general parking spaces to prevent vehicles from encroaching into walkways.	Install a wheel stop at the head of the general parking spaces.	$148.00	ADA 502, 502.7, MA 23.4.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	There is no device at the head of the accessible parking space to prevent vehicles from encroaching into accessible aisles or walkways.	Install a wheel stop at the head of the accessible parking space.	$250.00	ADA 502, 502.7, MA 23.4.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3

Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	There is no device at the head of the accessible parking space to prevent vehicles from encroaching into accessible aisles or walkways.	Install a wheel stop at the head of the accessible parking space.	$250.00	ADA 502, 502.7, MA 23.4.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	There is no additional signage marked "van accessible" at the van accessible parking space.	Van accessible parking spaces shall provide additional signage that states "van accessible" .	$250.00	ADA 502, 502.6, MA 23.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Town Hall - 685 Route 134 South Dennis, MA 02660	Path of Travel	The vertical clearance height is less than required.	Provide recommended vertical clearance.	$108.00	ADA 307, 307.4, MA 20.7

Town Hall - 685 Route 134 South Dennis, MA 02660	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
Town Hall - 685 Route 134 South Dennis, MA 02660	Ramps	The length of the bottom landing does not meet the required minimum length.	Modify or replace the bottom landing to provide the required minimum length and width.	$2,872.00	ADA 405, 405.7.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
Town Hall - 685 Route 134 South Dennis, MA 02660	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
Town Hall - 685 Route 134 South Dennis, MA 02660	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8

Town Hall - 685 Route 134 South Dennis, MA 02660	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Elevators	There is no signage at the Elevator indicating the Evacuation Plan.	Provide compliant signage indicating Evacuation plan and routes.	$207.00	ADA 302, 407
Town Hall - 685 Route 134 South Dennis, MA 02660	Platform Lifts	Platform Lift Signage contains the word Handicap.	Provide compliant signage. Remove the word Handicap.	$158.00	ADA 302, 410, ASME A18.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	Stair run vertical clearance height is not compliant.	Provide compliant vertical clearance for the stair run.		ADA 307.4
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	There are no handrails provided on the stairway.	Provide compliant handrails.	$1,528.00	ADA 504, 504.6 , 505.2, MA 27.4
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3

Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door.	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the push side of the door.	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6

Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed for a vertical rise.	Modify or replace the threshold to provide the recommended height.	$257.00	ADA 404, 404.2.5, MA 26.10
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed for a vertical rise.	Modify or replace the threshold to provide the recommended height.	$257.00	ADA 404, 404.2.5, MA 26.10
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6

Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902
Town Hall - 685 Route 134 South Dennis, MA 02660	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902
Town Hall - 685 Route 134 South Dennis, MA 02660	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902
Town Hall - 685 Route 134 South Dennis, MA 02660	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902
Town Hall - 685 Route 134 South Dennis, MA 02660	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902
Town Hall - 685 Route 134 South Dennis, MA 02660	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902

Town Hall - 685 Route 134 South Dennis, MA 02660	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1

Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$316.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	Signage contains the word Handicap.	Provide compliant signage. Remove the word Handicap.	$158.00	ADA 216, 703, MA 41.5

Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	Signage contains the word Handicap.	Provide compliant signage. Remove the word Handicap.	$158.00	ADA 216, 703, MA 41.5
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	Lowest line of tactile characters are not at a compliant height.	Provide compliant signage.	$158.00	ADA 703.4.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	Highest line of tactile characters are not at a compliant height.	Provide compliant signage at the location.	$158.00	ADA 703.4.1

Town Hall - 685 Route 134 South Dennis, MA 02660	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1

Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance from the rear wall to the side grab bar is greater than allowed.	Remount the side grab bar so it meets the distance requirements from the back wall.	$267.00	ADA 603, 604.5.1, 609, MA 30.8.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side	$267.00	ADA 604.5.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The length of the side grab bar is less than required.	Replace the side grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8

Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance between the wall and the gripping surface of the grab bar does not meet requirements.	Remount the grab bar so the space between the wall and gripping surface meets requirements. Grab bars must be able to support a	$250.00	ADA 505, 604.9.3, 609.3, MA 30.8.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side	$267.00	ADA 604.5.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet	$277.00	ADA 603, 604.7, MA 30.7.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic	$127.00	ADA 603, 604.6, MA 30.7.5

Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The length of the side grab bar is less than required.	Replace the side grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance between the wall and the gripping surface of the grab bar does not meet requirements.	Remount the grab bar so the space between the wall and gripping surface meets requirements. Grab bars must be able to support a	$250.00	ADA 505, 604.9.3, 609.3, MA 30.8.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The length of the rear grab bar is less than required.	Replace the rear grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.2, 609, MA 30.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side	$267.00	ADA 604.5.2

Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet	$277.00	ADA 603, 604.7, MA 30.7.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1

Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The height of the counter surface is greater than allowed.	Relocate or replace the lavatory to provide a maximum counter surface height of no greater than recommended.	$1,286.00	ADA 213, 606, 606.3, MA 30.9.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not a minimum of 60 inches of clearance around the water closet measured perpendicular from the side wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches	$1,707.00	ADA 502.4, 603, 604.3.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic	$127.00	ADA 603, 604.6, MA 30.7.5

Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not a minimum of 56 inches of clearance around the water closet measured perpendicular from the rear wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches	$1,707.00	ADA 603, 604.3.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not a minimum of 60 inches of clearance around the water closet measured perpendicular from the side wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches	$1,707.00	ADA 502.4, 603, 604.3.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic	$127.00	ADA 603, 604.6, MA 30.7.5

Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is no signage with the International Symbol of Accessibility.	Install signage that includes the International Symbol of Accessibility (ISA Symbol).	$158.00	ADA 216, 216.8, 703, 703.7, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is no signage with the International Symbol of Accessibility.	Install signage that includes the International Symbol of Accessibility (ISA Symbol).	$158.00	ADA 216, 216.8, 703, 703.7, MA 41.1

Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is no signage with the International Symbol of Accessibility.	Install signage that includes the International Symbol of Accessibility (ISA Symbol).	$158.00	ADA 216, 216.8, 703, 703.7, MA 41.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2

Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 603, 609, 609.4, MA 30.8.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 603, 609, 609.4, MA 30.8.1

Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is not a minimum of 60 inches of clearance around the water closet measured perpendicular from the side wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches	$1,707.00	ADA 502.4, 603, 604.3.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
Town Hall - 685 Route 134 South Dennis, MA 02660	Drinking Fountains	There is less than the required minimum knee clearance height.	Provide a fountain with the required knee and toe clearances.	$2,500.00	ADA 211, 306, 602, 602.2, MA 36.2

Town Hall - 685 Route 134 South Dennis, MA 02660	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Town Hall - 685 Route 134 South Dennis, MA 02660	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Town Hall - 685 Route 134 South Dennis, MA 02660	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Drinking Fountains	The provided drinking fountain is not a Hi-Low fountain.	Replace the drinking fountain with a compliant Hi-Low fountain.	$2,500.00	ADA 211.2, 305, 602
Town Hall - 685 Route 134 South Dennis, MA 02660	Drinking Fountains	The faucet controls require tight grasping or pinching of the wrist to operate.	Provide fountain controls with controls that do not require tight grasping or pinching of the wrist to operate.	$392.00	ADA 205, 211, 309, 309.4, 602, 602.3 , MA 36.5
Town Hall - 685 Route 134 South Dennis, MA 02660	Drinking Fountains	The toe clearance is less than required.	Provide a fountain with the required knee and toe clearances.	$2,500.00	ADA 211, 305, 306, 306.2, 602, 602.2
Town Hall - 685 Route 134 South Dennis, MA 02660	Drinking Fountains	There is less than the required minimum knee clearance height.	Provide a fountain with the required knee and toe clearances.	$2,500.00	ADA 211, 306, 602, 602.2, MA 36.2

Town Hall - 685 Route 134 South Dennis, MA 02660	Drinking Fountains	The spout outlet height is greater than required.	Provide a spout outlet that does not exceed the required height.	$627.00	ADA 211, 602, 602.4, MA 36.4
Town Hall - 685 Route 134 South Dennis, MA 02660	Drinking Fountains	The height of the water stream is less than required.	Insure that the spout directs the water flow to the required height and in a trajectory that is parallel or nearly parallel to the front of	$2,500.00	ADA 211, 602, 602.6, MA 36.3
Town Hall - 685 Route 134 South Dennis, MA 02660	Emergency Warning Systems	There are some visual warning devices, though visual warning devices are not located throughout the facility.	Install visual warning devices integrated with the facility's alarm system in all common areas such as hallways, classrooms and	$2,200.00	ADA 215, 702, MA 40.1
Town Hall - 685 Route 134 South Dennis, MA 02660	Break/Conferenc e Room	The table knee depth does not meet required standards.	Provide compliant tables.	$2,174.00	ADA 205, 228, 306.3.3, 308, 309
Town Hall - 685 Route 134 South Dennis, MA 02660	Break/Conferenc e Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
Town Hall - 685 Route 134 South Dennis, MA 02660	Break/Conferenc e Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
Town Hall - 685 Route 134 South Dennis, MA 02660	Accessible Showers	There are thresholds or splash curbs with a height greater than allowed.	Remove at least a 36-inch wide portion of the splash curbs to provide access to the recommended accessible shower.	$950.00	ADA 608, MA 31.7.8
Town Hall - 685 Route 134 South Dennis, MA 02660	Accessible Showers	The controls on the showers hand held mount are not accessible.	Provide accessible controls on the hand held mount.	$540.00	ADA 213, 608, 608.6
Town Hall - 685 Route 134 South Dennis, MA 02660	Accessible Showers	The water valve distance from seat wall is not compliant.	Provide a compliant water valve.	$1,500.00	ADA 213, 608, 608.6, MA 31.7.3

Town Hall - 685 Route 134 South Dennis, MA 02660	Reach Ranges	The knee height is not compliant.	Adjust knee height to the recommended value.	$500.00	ADA 226, 304, 306, 902
Uncle Barney's Road - 33 Uncle Barney's Road West Dennis, MA 02670	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one parking space as "van-accessible".	$370.00	ADA 208, 208.2, MA 23.2
Uncle Barney's Road - 33 Uncle Barney's Road West Dennis, MA 02670	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Uncle Barney's Road - 33 Uncle Barney's Road West Dennis, MA 02670	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Uncle Barney's Road - 33 Uncle Barney's Road West Dennis, MA 02670	Fishing Piers	Pier/Platform walking surface is not compliant.	Provide compliant walking surface with recommended value at the pier/platform.		
Uncle Barney's Road - 33 Uncle Barney's Road West Dennis, MA 02670	Fishing Piers	Pier/Platform walking surface is not compliant.	Provide compliant walking surface with recommended value at the pier/platform.		
Uncle Barney's Road - 33 Uncle Barney's Road West Dennis, MA 02670	Fishing Piers	Guardrail height is not compliant.	Provide compliant guardrail for the pier/platform.		ADA 1005.2.1, IBC 1003.1.12.1

Uncle Barney's Road - 33 Uncle Barney's Road West Dennis, MA 02670	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9

Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Stairs	The treads do not have a compliant depth.	Modify or replace the stairs to provide compliant treads.	$8,520.00	ADA 504, 504.2, MA 27.2
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4

Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Fishing Piers	Pier/Platform walking surface is not compliant.	Provide compliant walking surface with recommended value at the pier/platform.		
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Fishing Piers	Guardrail height is not compliant.	Provide compliant guardrail for the pier/platform.		ADA 1005.2.1, IBC 1003.1.12.1
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Fishing Piers	There is no edge protection provided for the fishing pier.	Provide compliant edge protection for the fishing pier.		ADA 1005.3
Uncle Freeman's Road - 27 Uncle Freeman's Road West Dennis, MA 02670	Fishing Piers	Railing height at the fishing station is not compliant.	Provide compliant railing height at the fishing station.		ADA 1005.2.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Path of Travel	The vertical clearance height is less than required.	Provide recommended vertical clearance.	$108.00	ADA 307, 307.4, MA 20.7

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Path of Travel	The vertical clearance height is less than required.	Provide recommended vertical clearance.	$108.00	ADA 307, 307.4, MA 20.7
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405.9.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The slope of the ramp is greater than the allowed slope.	Modify the run of the ramp to provide the required slope and cross slope.	$3,600.00	ADA 405, 405.2, MA 24.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The ramp changes direction at this landing. The length of the landing is less than the required minimum length.	Modify or replace the landing to meet the minimum required width and length.	$2,600.00	ADA 405.7, 405.7.4
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The gripping surface of the handrails are interrupted by posts, or by a lack of smooth connections.	Replace the handrails on each side to provide a smooth and continuous gripping surface. The gripping surface shall be smooth	$2,320.00	ADA 405, 405.8, 505.6, MA 24.5.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The gripping surface of the handrails are interrupted by posts, or by a lack of smooth connections.	Replace the handrails on each side to provide a smooth and continuous gripping surface. The gripping surface shall be smooth	$2,320.00	ADA 405, 405.8, 505.6, MA 24.5.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405.9.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The slope of the ramp is greater than the allowed slope.	Modify the run of the ramp to provide the required slope and cross slope.	$3,600.00	ADA 405, 405.2, MA 24.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The distance between the latch side of the door and the edge of the landing does not meet the required minimum distance.	Modify or replace the top landing on the ramp to provide a top landing with a level surface and provides the required minimum	$3,168.00	ADA 404, 405, MA 24.4.6

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The gripping surface of the handrails are interrupted by posts, or by a lack of smooth connections.	Replace the handrails on each side to provide a smooth and continuous gripping surface. The gripping surface shall be smooth	$2,320.00	ADA 405, 405.8, 505.6, MA 24.5.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The gripping surface of the handrails are interrupted by posts, or by a lack of smooth connections.	Replace the handrails on each side to provide a smooth and continuous gripping surface. The gripping surface shall be smooth	$2,320.00	ADA 405, 405.8, 505.6, MA 24.5.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405.9.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The slope of the ramp is greater than the allowed slope.	Modify the run of the ramp to provide the required slope and cross slope.	$3,600.00	ADA 405, 405.2, MA 24.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	There is a change in elevation greater than allowed on the primary path of travel of the ramp that is not beveled.	Bevel the area or resurface the area to provide a smooth and level path of travel.	$1,840.00	ADA 303.3, 405.7.1, MA 20.10

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The ramp changes direction. The width of the landing does not meet the minimum required width.	Modify or replace the landing to provide the minimum required length and width.	$2,872.00	ADA 405, 504.7.4, MA 24.4.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The ramp changes direction at this landing. The length of the landing is less than the required minimum length.	Modify or replace the landing to meet the minimum required width and length.	$2,600.00	ADA 405.7, 405.7.4
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The slope of the landing is greater than required.	Modify the landing to create a slope in any direction not exceeding the required maximum value.	$2,872.00	ADA 402, 405.7.1, MA 20.9
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The surface texture of the wall adjacent to the handrail is sharp and abrasive.	Modify the surface texture on the wall adjacent to the handrail so that the surface is smooth.	$2,320.00	ADA 504.6 , 505, 505.8, MA 27.4.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The gripping surfaces of the handrails are sharp, abrasive and/or not smooth.	Modify or replace the handrails on the stairway so that the gripping surface is smooth and nonabrasive.	$1,528.00	ADA 504.6 , 505, 505.8, MA 27.4.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth,	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The surface texture of the wall adjacent to the handrail is sharp and abrasive.	Modify the surface texture on the wall adjacent to the handrail so that the surface is smooth.	$2,320.00	ADA 504.6 , 505, 505.8, MA 27.4.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The vertical clearance height of the open doorway is not compliant.	Provide a compliant open doorway at the location.	$5,600.00	ADA 307.4
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Doors	The bottom of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest	Install a panel or replace the door to provide a smooth, uninterrupted surface at the bottom of the door.	$2,000.00	ADA 404, 404.2.10
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the	$277.00	ADA 603, 604.9.6, MA 30.14.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The toilet paper dispenser does not allow a continuous paper flow.	Install a compliant toilet paper dispenser.		ADA 604.7
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the toilet seat in the restroom is greater than the allowed maximum height for the primary age group.	Adjust or modify the height of the toilet seat to meet the required height for the primary age group.	$1,707.00	ADA 603, 604.9, MA 30.14.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The distance from the center line of the toilet to the nearest side wall in the compartment designated to be accessible in the restroom is greater	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above finish floor	$291.00	ADA 213, 603, 603.3, MA 30.18
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The faucet controls on the lavatory require tight grasping, pinching, or twisting of the wrist and are not accessible.	Install accessible faucet controls. Lever-operated, push-type, touch-type or electronically controlled mechanisms are acceptable	$392.00	ADA 213, 309.4, 606, MA 30.9.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The bottom edge of the reflective surface of the mirror in the restroom is not at a compliant height for the primary age group.	Lower the mirror in the restroom so that the bottom edge of the reflective surface is no higher than recommended above finish floor	$291.00	ADA 213, 603, 603.3, MA 30.18
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the side grab bar in the compartment designated to be accessible in the restroom is greater than the allowed maximum height for	Remount the side grab bar in the compartment designated to be accessible in the restroom at to the required height for use by the	$78.00	ADA 604.9, 609, 609.4, MA 30.15.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct	$231.00	ADA 213, 604, 604.9
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The paper dispenser is located behind the front of toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat.	$78.00	ADA 304, 604.7
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The toilet paper dispenser does not allow a continuous paper flow.	Install a compliant toilet paper dispenser.		ADA 604.7
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the toilet seat in the restroom is greater than the allowed maximum height for the primary age group.	Adjust or modify the height of the toilet seat to meet the required height for the primary age group.	$1,707.00	ADA 603, 604.9, MA 30.14.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The distance from the center line of the toilet to the nearest side wall in the compartment designated to be accessible in the restroom is greater	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic	$127.00	ADA 603, 604.6, MA 30.7.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$280.00	ADA 304, 309, 309.4, 404.2.7, 603

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The faucet controls on the lavatory require tight grasping, pinching, or twisting of the wrist and are not accessible.	Install accessible faucet controls. Lever-operated, push-type, touch-type or electronically controlled mechanisms are acceptable	$392.00	ADA 213, 309.4, 606, MA 30.9.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The lavatory is in an enclosed cabinet, thereby preventing an accessible forward approach.	Lavatories in restrooms must provide clear floor space in front of the lavatory for an accessible forward approach and shall provide the minimum required primary age group knee and toe	$420.00	ADA 213, 606, 606.2, MA 30.9
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The knee clearance space under the lavatory designated to be accessible in the restroom is less than the required minimum for the primary	Reinstall or replace the lavatory designated to be accessible with an accessible lavatory that provides the required knee	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$280.00	ADA 304, 309, 309.4, 404.2.7, 603
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The faucet controls on the lavatory require tight grasping, pinching, or twisting of the wrist and are not accessible.	Install accessible faucet controls. Lever-operated, push-type, touch-type or electronically controlled mechanisms are acceptable	$392.00	ADA 213, 309.4, 606, MA 30.9.6
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The lavatory is in an enclosed cabinet, thereby preventing an accessible forward approach.	Lavatories in restrooms must provide clear floor space in front of the lavatory for an accessible forward approach and shall provide the minimum required primary age group knee and toe	$420.00	ADA 213, 606, 606.2, MA 30.9

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the counter surface of the lavatory designated to be accessible in the restroom is greater than the allowed maximum height for	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The knee clearance space under the lavatory designated to be accessible in the restroom is less than the required minimum for the primary	Reinstall or replace the lavatory designated to be accessible with an accessible lavatory that provides the required knee	$1,286.00	ADA 213, 606, 606.2, MA 30.16.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 213, 606, 606.5, MA 30.9.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the controls and operating mechanisms for the dispenser in the restroom are greater than the allowed maximum height for	Relocate the dispenser in the restroom to meet the required height for the primary age group.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 30.20

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$277.00	ADA 205, 309, 309.4, MA 39.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is not a minimum of 56 inches of clearance around the water closet measured perpendicular from the rear wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches	$1,707.00	ADA 603, 604.3.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There are grab bars missing from the toilet compartment.	Install the required grab bars in the toilet compartment.	$231.00	ADA 604.5, 604.9.4, 609, MA 30.15.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the	$277.00	ADA 603, 604.9.6, MA 30.14.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the toilet seat in the restroom is greater than the allowed maximum height for the primary age group.	Adjust or modify the height of the toilet seat to meet the required height for the primary age group.	$1,707.00	ADA 603, 604.9, MA 30.14.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The distance from the center line of the toilet to the nearest side wall in the compartment designated to be accessible in the restroom is greater	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is not a minimum of 56 inches of clearance around the water closet measured perpendicular from the rear wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches	$1,707.00	ADA 603, 604.3.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There are grab bars missing from the toilet compartment.	Install the required grab bars in the toilet compartment.	$231.00	ADA 604.5, 604.9.4, 609, MA 30.15.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 604.5.1, MA 30.20
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The location of the toilet paper dispenser in the restroom primarily used by children is not within recommended values of the front	Remount the toilet paper dispenser in the restroom so that it is within the recommended values from the front edge of the	$277.00	ADA 603, 604.9.6, MA 30.14.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The height of the toilet seat in the restroom is greater than the allowed maximum height for the primary age group.	Adjust or modify the height of the toilet seat to meet the required height for the primary age group.	$1,707.00	ADA 603, 604.9, MA 30.14.3
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The distance from the center line of the toilet to the nearest side wall in the compartment designated to be accessible in the restroom is greater	Relocate the toilet to provide a distance from the center line of the toilet to the nearest side that meets the required distance for	$1,143.00	ADA 603, 604.9.1, MA 30.14.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic	$127.00	ADA 603, 604.6, MA 30.7.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Play Area	The play area is not located on an accessible route.	Provide a compliant accessible route to the play area.	$1,440.00	ADA 1008, 1008.2, 240, 402.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Play Area	The play area provides no accessible point of access.	Provide compliant access to the play area.	$2,400.00	ADA 1008, 1008.2, 240
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Play Area	The transfer platform height is not compliant.	Provide compliant platform with recommended value at the transfer point.	$320.00	ADA 1008, 1008.3.1.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Play Area	The tread depth of the steps is not compliant.	Provide steps with compliant tread depth.	$34.75	ADA 1008, 1008.3.2.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Play Area	The height of the steps is not compliant.	Provide steps with a compliant riser height.	$280.00	ADA 1008, 1008.3.2.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Emergency Warning Systems	There are some visual warning devices, though visual warning devices are not located throughout the facility.	Install visual warning devices integrated with the facility's alarm system in all common areas such as hallways, classrooms and	$2,200.00	ADA 215, 702, MA 40.1
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 205, 228, 308, 309
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive	$149.00	ADA 606.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Sinks	The cabinet door hardware is not accessible.	Provide compliant hardware for cabinet door.	$190.00	ADA 309

V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Sinks	The toe kick for the sink is not removed.	Make sure there is no toe kick at the sink.	$420.00	ADA 305, 306, 606.2
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Sinks	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Sinks	The operable parts of the dispenser require tight grasping, pinching, or twisting of the wrist.	Replace dispenser with one that allows operation with one hand and does not require tight grasping, pinching, or twisting of	$980.00	ADA 309, MA 39.5
V.I.C. Hall - 185 Depot Street Dennis Port, MA 02639	Sinks	The height of the controls and operating mechanisms for the dispenser are greater than the allowed maximum height for the	Relocate the dispenser to meet the required height for the primary age group.	$180.00	ADA 205, 308, 309, 606, MA 30.20
Vets' Memorial - 100 Main Street West Dennis, MA 02670	Parking	There are not enough accessible parking spaces marked in the parking lot and therefore does not meet the minimum number required.	Re-stripe any existing parking spaces marked accessible and create additional accessible parking spaces. Designate one	$370.00	ADA 208, 208.2, MA 23.2
Vets' Memorial - 100 Main Street West Dennis, MA 02670	Parking	Parking is provided off-street to the public and/or employees at this location, though the parking lot surface is dirt or gravel and non-	Stripe parking spaces with an appropriate number of accessible parking spaces.	$1,611.00	ADA 206.1 , 208, 209, 302.1, 403.2, MA 23.4.4
Vets' Memorial - 100 Main Street West Dennis, MA 02670	Path of Travel	There is no edge protection at the drop off.	Install edge protection on the walking surface at the required minimum height.	$1,088.00	ADA 303.5
Vets' Memorial - 100 Main Street West Dennis, MA 02670	Path of Travel	The guardrail height is not compliant.	Provide compliant guardrails.	$1,088.00	IBC 1003.2.12.1

Vets' Memorial - 100 Main Street West Dennis, MA 02670	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10
Vets' Memorial - 100 Main Street West Dennis, MA 02670	Path of Travel	The leading edge of the wall-mounted item is more than 4 inches from the wall. The item is greater than 27 inches, and less than 80 inches from	Install side extensions, modify, relocate, or lower the item so that the leading edge protrudes less than 4 inches from the wall, is less	$640.00	ADA 307, 307.2, MA 20.6
Vets' Memorial - 100 Main Street West Dennis, MA 02670	Path of Travel	Walking surface has an opening that is not compliant.	Make sure that the walking surface opening does not allow passage of a sphere more than ½ inch in diameter.	$185.00	ADA 302.3
Vets' Memorial - 100 Main Street West Dennis, MA 02670	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
Vets' Memorial - 100 Main Street West Dennis, MA 02670	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
Vets' Memorial - 100 Main Street West Dennis, MA 02670	Benches	No clear floor space provided at the bench.	Provide compliant clear floor space for the bench at one end.	$1,840.00	ADA 305, 903.2
Vets' Memorial - 100 Main Street West Dennis, MA 02670	Viewing Area	The viewing area does not have an unobstructed view above 32".	Make sure that there is at least 32" of unobstructed view from floor.		ADA 1015
Vets' Memorial - 100 Main Street West Dennis, MA 02670	Viewing Area	The guardrail height is not compliant.	Provide a compliant guardrail.	$243.80	ADA 1015

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	There is no device at the head of the general parking spaces to prevent vehicles from encroaching into walkways.	Install a wheel stop at the head of the general parking spaces.	$148.00	ADA 502, 502.7, MA 23.4.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the wall-mounted signage designating accessible parking is not at the required height.	Remount the wall-mounted signage designating the accessible parking space so that it is installed at the required height. The sign shall be located so that it cannot	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$250.00	ADA 208, 502.2, MA 23.4.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The access aisle markings are faded, damaged, or otherwise not viewable.	Re-stripe the access aisle so as to discourage parking.	$250.00	ADA 502.3, 502.3.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	There is no vertically-mounted signage at the designated accessible parking space showing the International Symbol of Accessibility.	Provide a permanently posted reflectorized sign that includes an International Symbol of Accessibility symbol at the head of the parking space. The "van-	$250.00	ADA 502, 502.6, 703.7.2.1, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces.	$1,100.00	ADA 502.3

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The accessible parking space does not meet the minimum requirements for width.	Re-stripe the accessible parking space.	$350.00	ADA 502, 502.2, MA 23.4.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Passenger Loading Zones	There is no required striping in the access aisle adjacent to the passenger loading zone.	Stripe an access aisle to meet the required minimum width and length adjacent and parallel to the vehicle pull-up space. The access aisle striping for the passenger	$400.00	ADA 502, 503, 503.3.3, MA 23.7
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Passenger Loading Zones	There is less than the minimum required width in the access aisle at the passenger loading zone.	Create an access aisle to meet the required minimum width and length adjacent and parallel to the vehicle pull-up space. The access aisle striping for the passenger	$650.00	ADA 502, 503, 503.3.1, MA 23.7
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Passenger Loading Zones	Passenger loading zone has no sign.	Mark the passenger loading zone with ISA symbol of accessibility.	$220.00	ADA 503.3.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Path of Travel	Walking surface has an opening that is not compliant.	Make sure that the walking surface opening does not allow passage of a sphere more than ½ inch in diameter.	$185.00	ADA 302.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Path of Travel	The width of the path of travel is insufficient.	Widen the primary path of travel to provide the correct width.	$3,500.00	ADA 403.5.1, MA 20.3

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$450.00	ADA 303, 403.4, MA 20.10
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The slope of the ramp is greater than the allowed slope.	Modify the run of the ramp to provide the required slope and cross slope.	$3,600.00	ADA 405, 405.2, MA 24.2

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The slope of the landing is greater than required.	Modify the landing to create a slope in any direction not exceeding the required maximum value.	$2,872.00	ADA 402, 405.7.1, MA 20.9
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The ramp changes direction. The width of the landing does not meet the minimum required width.	Modify or replace the landing to provide the minimum required length and width.	$2,872.00	ADA 405, 504.7.4, MA 24.4.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The diameter of the handrail is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 405, 405.8, 505.7.1, MA 24.5.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The gripping surface of the handrails are interrupted by posts, or by a lack of smooth connections.	Replace the handrails on each side to provide a smooth and continuous gripping surface. The gripping surface shall be smooth and free from interruptions.	$2,320.00	ADA 405, 405.8, 505.6, MA 24.5.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The ends of the handrails end abruptly.	The handrails shall provide extensions that are parallel to the floor or ground surface extending the required distance beyond the top and bottom of the ramp and	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4, MA 24.5.9
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The diameter of the handrail is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 405, 405.8, 505.7.1, MA 24.5.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The ends of the handrails end abruptly.	The handrails shall provide extensions that are parallel to the floor or ground surface extending the required distance beyond the top and bottom of the ramp and	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4, MA 24.5.9
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	There are no handrails.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.2, MA 24.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The slope of the landing is greater than required.	Modify the landing to create a slope in any direction not exceeding the required maximum value.	$2,872.00	ADA 402, 405.7.1, MA 20.9
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	There is a change in elevation greater than allowed on the primary path of travel of the ramp that is not beveled.	Bevel the area or resurface the area to provide a smooth and level path of travel.	$1,840.00	ADA 302, 303, 303.3, 405.7.1, MA 20.10
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The slope of the landing is greater than required.	Modify the landing to create a slope in any direction not exceeding the required maximum value.	$2,872.00	ADA 402, 405.7.1, MA 20.9
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The ends of the handrails end abruptly.	The handrails shall provide extensions that are parallel to the floor or ground surface extending the required distance beyond the top and bottom of the ramp and	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4, MA 24.5.9

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The distance between the handrail and the adjacent wall is not compliant.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.5, MA 24.5.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the ramp.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 405.9.1, 505.10.1, MA 24.5.4, MA 24.5.9
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The ends of the handrails end abruptly.	The handrails shall provide extensions that are parallel to the floor or ground surface extending the required distance beyond the top and bottom of the ramp and	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4, MA 24.5.9
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	There is not enough extension beyond the top or bottom of the rail.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Ramps	The height of the handrails on the ramp is not within the required range above the surface of the ramp.	Modify or replace the handrails on the ramp to provide a gripping surface height within the required range above the ramp surface.	$3,918.00	ADA 405, 405.8, 505.4, MA 24.5.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$17,040.00	ADA 504, MA 27.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$960.00	ADA 504, 504.3, MA 27.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$4,640.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$3,832.00	ADA 504, 504.6 , 505.10, MA 27.4.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$1,600.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$1,600.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$4,640.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$3,832.00	ADA 504, 504.6 , 505.10, MA 27.4.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$1,600.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$1,600.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The gripping surfaces of the handrails are sharp, abrasive and/or not smooth.	Modify or replace the handrails on the stairway so that the gripping surface is smooth and nonabrasive.	$1,528.00	ADA 504.6 , 505, 505.8, MA 27.4.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth, uninterrupted gripping surface.	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$480.00	ADA 504, 504.3, MA 27.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth, uninterrupted gripping surface.	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The gripping surface of the handrail is interrupted.	Remount the handrails so they are not interrupted. Otherwise, replace the handrails with ones that provide a smooth, uninterrupted gripping surface.	$1,840.00	ADA 504, 504.6 , 505.6, MA 27.4.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$76,680.00	ADA 504, MA 27.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The risers on the stairway are open.	Close the riser openings on the stairway. Open risers are not permitted.	$4,320.00	ADA 504, 504.3, MA 27.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$20,880.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$17,244.00	ADA 504, 504.6 , 505.10, MA 27.4.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$7,200.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$7,200.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$12,825.00	ADA 504, 504.6 , 505.10.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$13,752.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$20,880.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$17,244.00	ADA 504, 504.6 , 505.10, MA 27.4.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension is not the required length beyond the top riser.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$7,200.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$7,200.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$12,825.00	ADA 504, 504.6 , 505.10.3

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$13,752.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The vertical clearance height of the open doorway is not compliant.	Provide a compliant open doorway at the location.	$5,600.00	ADA 307.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The vertical clearance height of the open doorway is not compliant.	Provide a compliant open doorway at the location.	$5,600.00	ADA 307.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The clear opening width of the doorway is not compliant.	Provide a compliant doorway at the location.	$1,800.00	ADA 404, 404.2.4.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The vertical clearance height of the open doorway is not compliant.	Provide a compliant open doorway at the location.	$5,600.00	ADA 307.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the push side of the door .	Provide the recommended clear floor space on the push side of the door.	$4,000.00	ADA 404, MA 26.6

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The door opening hardware is not accessible.	Provide accessible hardware on the door.	$800.00	ADA 309.4, 404.2.7
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The clear opening width of the door is less than required.	Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.	$1,750.00	ADA 404, 404.2.3, MA 26.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The vertical clearance height of the door is less than required.	Extend the height of the doorway to provide the required clearance height.	$2,000.00	ADA 307, 307.4, 404, 404.2.3, MA 20.7

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Doors	Door hardware broken or missing.	Provide compliant accessible door hardware.	$340.00	ADA 404.2.7
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Counters	The counter is a protruding object.	Adjust the counter so that it is no longer a protruding object.	$450.00	ADA 307.2, 902
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Signage	There is no directional signage.	Install directional signage to each accessible element or room.	$158.00	ADA 216, 216.3 , 703, 703.5, MA 41.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The shields extend greater than 24” in front of the urinal. The width between the shields is less than required.	Modify or replace the urinal shields in the restroom to provide the required clearance between the shields for the urinal designated as accessible.	$1,800.00	ADA 305.7, 605, 605.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The toilet paper dispenser interferes with the use of the grab bar.	Relocate the toilet paper dispenser so it does not interfere with the use of a grab bar. Toilet paper dispensers must allow continuous paper flow.	$277.00	ADA 603, 609.3, MA 30.7.6

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the side grab bar is not at the correct height.	Remount the grab bar so it is at the correct height.	$500.00	ADA 603, 609, 609.4, MA 30.8.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The grab bar on the rear wall is not at the correct height.	Remount the rear grab bar in the compartment designated to be accessible so the height of the gripping surface is at the correct height.	$231.00	ADA 603, 609, 609.4, MA 30.8.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The toilet paper dispenser is not mounted at the required height.	Remount the toilet paper dispenser in the compartment to the required height.	$277.00	ADA 603, 604.7, MA 30.7.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is no toilet paper dispenser provided on the narrow side wall.	Install a compliant toilet paper dispenser.	$277.00	ADA 603, 604.7, MA 30.7.6

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is not a minimum of 60 inches of clearance around the water closet measured perpendicular from the side wall.	Clearance around a water closet shall be 60 inches (1525 mm) minimum measured perpendicular from the side wall and 56 inches (1420 mm) minimum measured	$1,707.00	ADA 502.4, 603, 604.3.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There are no grab bars.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 609, MA 30.8
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is no required coat hook.	Install a coat hook at the recommended height.	$34.00	MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the toilet seat is not at the required height.	Adjust or modify the toilet so the seat height is at the required accessible height.	$1,707.00	ADA 603, 604.4, MA 30.7.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The distance between the wall and the gripping surface of the grab bar does not meet requirements.	Remount the grab bar so the space between the wall and gripping surface meets requirements. Grab bars must be able to support a point load of at least 250 pounds	$250.00	ADA 505, 604.9.3, 609.3, MA 30.8.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The restroom door does not provide a compliant privacy lock with occupancy indicator.	Install a compliant privacy lock with occupancy indicator to the door.	$804.00	ADA 213, 213.2.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.	Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.	$14,000.00	ADA 304, 304.3, 304.3.1, 603, 603.2.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The faucet controls on the lavatory require tight grasping, pinching, or twisting of the wrist and are not accessible.	Install accessible faucet controls. Lever-operated, push-type, touch-type or electronically controlled mechanisms are acceptable elements. If self-closing valves are	$392.00	ADA 213, 309.4, 606, MA 30.9.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is not enough toe clearance at the restroom lavatory.	Provide minimum required toe clearance.	$289.00	ADA 213, 306.2.1, 606, 606.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.	Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.	$289.00	ADA 309.4, 404, 404.2.7, 604.8, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,200.00	ADA 404, 404.2.4.1, 604.8.1.2, 604.8.2.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The distance between the wall and the gripping surface of the grab bar does not meet requirements.	Remount the grab bar so the space between the wall and gripping surface meets requirements. Grab bars must be able to support a point load of at least 250 pounds	$250.00	ADA 505, 604.9.3, 609.3, MA 30.8.3

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Rear grab bar interferes with the tank/flushometer.	Readjust the rear grab bar so that it does not interfere with the tank/flushometer.	$231.00	ADA 609.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Rear grab bar location is not compliant.	Remount the rear grab bar to provide a minimum of 12 inches of extension from the center line of the of the water closet on one side and 24 inches of extension on the	$267.00	ADA 604.5.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The location of the toilet paper dispenser is not within the required distance from the front edge of the toilet seat.	Remount the toilet paper dispenser so it is within the required distance from the front edge of the toilet seat. Toilet paper dispensers must allow	$277.00	ADA 603, 604.7, MA 30.7.6
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The bottom edge of the reflective surface of the mirror is not at the correct height.	Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.	$300.00	ADA 213, 603, 603.3, MA 30.11
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is not sufficient clear floor space provided to allow an accessible forward approach.	Relocate the lavatory to provide clear floor space.	$2,261.00	ADA 213, 305.3, 606, 606.2, MA 6.4.1

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	There is no signage indicating accessibility on the latch side of the entry door of the restroom.	Provide compliant signage on latch side of door.	$158.00	ADA 216, 216.8, 703, MA 41.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Restrooms	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$277.00	ADA 205, 308, 308.1, 309, 606, MA 6.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Play Area	The play area is not located on an accessible route.	Provide a compliant accessible route to the play area.	$1,440.00	ADA 1008, 1008.2, 240, 402.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface beneath the play components and	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Play Area	The play area provides no accessible point of access.	Provide compliant access to the play area.	$2,400.00	ADA 1008, 1008.2, 240

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface beneath the play components and	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Play Area	The controls cannot be operated with one hand and/or require tight pinching, grasping, or twisting of the wrist.	Provide controls that can be operated with one hand and do not require tight pinching, grasping or twisting of the wrist.	$277.00	ADA 1008, 309.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface beneath the play components and	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Play Area	The play area is not located on an accessible route.	Provide a compliant accessible route to the play area.	$1,440.00	ADA 1008, 1008.2, 240, 402.1
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface beneath the play components and	$500.00	ADA 1008, 1008.2, 1008.2.6, 240
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Play Area	The play area provides no accessible point of access.	Provide compliant access to the play area.	$2,400.00	ADA 1008, 1008.2, 240
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Play Area	The surface beneath the play area is non-accessible to individuals with mobility impairments.	The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface beneath the play components and	$500.00	ADA 1008, 1008.2, 1008.2.6, 240

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Sinks	Twist controls are present on the sink.	Provide compliant controls for the sink.	$392.00	ADA 205, 212, 228, 308, 309, 606.4
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Sinks	Sink counter height is not compliant.	Provide compliant sink.	$1,800.00	ADA 606.3
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Sinks	The pipes are not wrapped for the sink.	Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Sinks	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Sinks	Supply lines are not wrapped for the sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Sinks	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$180.00	ADA 205, 308, 309, 606, MA 6.5

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Picnic Areas	There is no accessible route to the picnic tables.	Provide an accessible route to the picnic tables.	$1,440.00	ADA 205, 226, 228, 308, 309, 402, 403
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Picnic Areas	At least 5% of the provided tables are not accessible.	Provide enough compliant Accessible Tables (At least 5% of the total Tables).	$500.00	ADA 205, 226.1, 228, 305, 306, 308, 309, 902
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Accessible Showers	There are not enough accessible showers with respect to the total number of showers available.	Provide the required amount of compliant accessible showers.	$4,500.00	ADA 213, 213.3.6, 608
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Accessible Showers	There are not enough accessible showers with respect to the total number of showers available.	Provide the required amount of compliant accessible showers.	$4,500.00	ADA 213, 213.3.6, 608
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Reach Ranges	Element reach depth is not compliant.	Make sure that the element is within allowed reach range with recommended reach depth.	$550.00	ADA 308
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Reach Ranges	Element reach depth is not compliant.	Make sure that the element is within allowed reach range with recommended reach depth.	$550.00	ADA 308

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Reach Ranges	The element is not located on the accessible route.	The element must be located on the accessible route.	$1,260.00	ADA 206, 304
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$50.00	ADA 308, 309
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Reach Ranges	The highest point of operation for the element is not compliant.	Make sure that the highest point of operation is within the recommended value.	$100.00	ADA 308, 309
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Reach Ranges	The side reach height of the controls on the vending machine is greater than the allowed maximum height.	Contact the owner of the vending machines to obtain accessible vending machines.		ADA 308, 309
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Benches	No clear floor space provided at the bench.	Provide compliant clear floor space for the bench at one end.	$1,840.00	ADA 305, 903.2
West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Benches	The bench is not on an accessible route.	Provide a compliant accessible route to the benches.	$1,840.00	ADA 205, 228, 305, 308, 309, 903

West Dennis Beach - 45 Lighthouse Road West Dennis, MA 02670	Benches	No clear floor space provided at the bench.	Provide compliant clear floor space for the bench at one end.	$1,840.00	ADA 305, 903.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	There is no designated "van accessible" parking space provided in the parking lot.	Provide a compliant van accessible space.	$370.00	ADA 208, 208.2.4, 502.7, MA 23.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	The access aisle does not meet the minimum required width.	Re-stripe the access aisle to meet the minimum required width and length for the space type.	$350.00	ADA 502, 502.3.1, MA 23.4.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	The bottom edge of the wall-mounted signage designating accessible parking is not at the required height.	Remount the wall-mounted signage designating the accessible parking space so that it is installed at the required height. The sign shall be located so that it cannot be obscured by a vehicle parked in	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	The access aisle exceeds maximum slope.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	The surface of the accessible parking space has a slope greater than allowed.	Pave the parking lot to provide a level surface.	$3,800.00	ADA 502, 502.4, MA 23.4.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	The location of the accessible parking spaces requires individuals with disabilities to travel behind parked cars other than their own.	Stripe an access aisle at the head of the accessible parking spaces, install a wheel stop at the head of the accessible parking spaces and at the general parking spaces. Wheel stops shall be used to	$1,100.00	ADA 502.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	The bottom edge of the post-mounted signage designating the accessible parking space is not at the required height.	Modify the height or replace the post-mounted signage designating the accessible parking space. The sign shall be located so that it cannot be obscured by a vehicle parked in the space.	$158.00	ADA 502, 502.6, MA 23.6

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	Parking space signage contains the word handicap.	Provide compliant signage. Remove the word handicap.	$300.00	ADA 502
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Parking	The bottom edge of the wall-mounted signage designating accessible parking is not at the required height.	Remount the wall-mounted signage designating the accessible parking space so that it is installed at the required height. The sign shall be located so that it cannot be obscured by a vehicle parked in	$158.00	ADA 502, 502.6, MA 23.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Path of Travel	There is no compliant accessible route from the public right of way to the accessible entrance of the facility.	Provide at least one accessible route from the public right of way to the accessible entrance of the facility. Make certain to post signage indicating the direction to accessible building entrances at	$1,840.00	ADA 206, 206.2, 402.1, MA 20.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Path of Travel	There are slopes greater than allowed maximum slope on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Path of Travel	There are cross slopes greater than allowed on the primary path of travel.	Provide a compliant path of travel.	$3,600.00	ADA 402, 403.3, MA 20.9
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Path of Travel	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	$150.00	ADA 303, 403.4, MA 20.10

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Path of Travel	Section of surface is broken or spalled.	Provide a compliant surface for the broken/spalled section.	$1,260.00	ADA 302, 403.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Ramps	The ramp run does not provide adequate edge protection to prevent individuals from slipping off the ramp.	Install compliant edge protection on each side of the ramp run.	$470.00	ADA 405, 405.9, MA 24.8
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Ramps	The slope of the ramp is greater than the allowed slope.	Modify the run of the ramp to provide the required slope and cross slope.	$3,600.00	ADA 405, 405.2, MA 24.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Ramps	There is only one handrail provided.	Provide compliant handrails on each side.	$2,200.00	ADA 405, 405.8, 505.2, MA 24.5
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Ramps	There is a change in elevation greater than allowed on the primary path of travel of the ramp that is not beveled.	Bevel the area or resurface the area to provide a smooth and level path of travel.	$1,840.00	ADA 303.3, 405.7.1, MA 20.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Ramps	The length of the top landing does not meet the required minimum length.	Modify or replace the top landing to provide the required minimum length and width.	$2,872.00	ADA 405.7, 405.7.3

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Ramps	The distance between the latch side of the door and the edge of the landing does not meet the required minimum distance.	Modify or replace the top landing on the ramp to provide a top landing with a level surface and provides the required minimum distance from the latch side of the door the edge of the landing.	$3,168.00	ADA 404, 405, MA 24.4.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Ramps	The handrail extension is not parallel to the floor or ground surface.	The handrails shall provide extensions that are parallel to the floor or ground surface extending beyond the top and bottom of the ramp and return smoothly to the post or wall.	$2,400.00	ADA 405, 405.8, 505.10.1, MA 24.5.4
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Elevators	Unable to inspect the elevator at the time of inspection due to a maintenance issue.	Follow up inspection is recommended.		ADA 206.6, 407
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	Stairway is marked as primary access. There is no other means of vertical access.	Provide a compliant means of vertical access.	$4,816.00	ADA 206.2, 210, 402.2, 504, MA 20.12.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The risers on the stairway are not a compliant height.	Modify or replace the stairs to provide compliant riser height.		ADA 504.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The height of the risers are not uniform.	Modify or replace the stairs to provide uniform riser height.	$8,520.00	ADA 504, MA 27.2

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The ends of the handrails are not rounded or returned smoothly to the wall or post.	Install handrail extensions that are rounded or returned smoothly to the wall post.	$1,916.00	ADA 504, 504.6 , 505.10, MA 27.4.8
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The distance between the handrail and the wall on the stairway is less than required.	Remount the handrails on the stairway so that the distance from the handrail to the adjacent wall is compliant.	$1,916.00	ADA 504, 504.6 , 505.5, MA 27.4.7
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	Stair run vertical clearance height is not compliant.	Provide compliant vertical clearance for the stair run.		ADA 307.4
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	There is no handrail provided on one side of the stairway.	Provide compliant handrails on the stairway.	$1,528.00	ADA 504, MA 27.4

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The diameter of the handrails is not within the required range.	Replace the handrails on each side to provide a smooth and continuous gripping surface diameter within the required range.	$2,320.00	ADA 504.6 , 505, 505.7.1, MA 27.4.4
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	There are no top handrail extensions provided on the stairway.	Install handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface at the top landing.	$1,425.00	ADA 504, 504.6 , 505.10.1, 505.10.2, MA 27.4.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The distance between the handrail and the wall on the stairway is less than required.	Remount the handrails on the stairway so that the distance from the handrail to the adjacent wall is compliant.	$1,916.00	ADA 504, 504.6 , 505.5, MA 27.4.7
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	There are no handrails provided on the stairway.	Provide compliant handrails.	$1,528.00	ADA 504, 504.6 , 505.2, MA 27.4

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	There are no bottom handrail extensions provided.	Install handrail extension to the bottom of the handrail that extends beyond the bottom riser at least one tread depth.	$1,425.00	ADA 504, 504.6 , 505.10.3, MA 27.4.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The distance between the handrail and the wall on the stairway is less than required.	Remount the handrails on the stairway so that the distance from the handrail to the adjacent wall is compliant.	$1,916.00	ADA 504, 504.6 , 505.5, MA 27.4.7

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The top handrail extension of the stairway is not parallel with the floor surface at the top landing.	Install a compliant handrail extension to the top of the handrail that extends beyond the top riser and is parallel to the floor surface of the landing.	$800.00	ADA 504, 504.6 , 505.10.2, MA 27.4.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The bottom handrail does not extend the depth of one stair tread beyond the bottom step.	Provide a compliant handrail extension.	$1,425.00	ADA 504, 504.6 , 505.10.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Stairs	The handrails are not mounted at the required height.	Provide handrails on the stairway at the required height.	$1,528.00	ADA 504, 504.6 , 505.4, MA 27.4.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The vertical clearance height of the open doorway is not compliant.	Provide a compliant open doorway at the location.	$5,600.00	ADA 307.4

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, 404.2.4.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	Door hardware is not mounted at the correct height.	Mount the door hardware at the recommended height.	$280.00	ADA 404, 404.2.7

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The door lock requires tight grasping, pinching, or twisting of the wrist to operate.	Provide a compliant door lock for the door that does not require tight grasping, pinching, or twisting of the wrist to operate.	$310.00	ADA 309.4, 404.2.7
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The door closing device limits the required headroom clearance.	Replace the door closing device with a device that fits above the door casing and does not protrude into the primary path of travel.	$250.00	ADA 404, 404.2.3, MA 20.7
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the push side of the door.	Provide the recommended latch side clearance on the push side of the door. Otherwise, install an automatic door opening device.	$2,921.00	ADA 404, 404.2.4, MA 26.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	An unstable floor mat is provided at the door landing.	Provide a compliant floor mat for the door.	$126.00	ADA 302.1, 403.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is not enough clear floor space provided at the pull side of the door.	Provide the recommended clear floor space on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$2,921.00	ADA 404, 404.2.4, MA 26.6

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The height of the threshold at the entrance door is greater than allowed.	Modify or replace the threshold to provide the recommended height.	$436.00	ADA 404, 404.2.5, MA 26.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	The door opening force for this door is greater than allowed.	Adjust the closer on the door to meet the door opening force requirements.	$25.00	ADA 404, 404.2.9, MA 26.8
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	Has a door stop.	Remove the door stop.	$50.00	ADA 404, 404.2.10
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is less than the required latch side clearance on the pull side of the door.	Provide required latch side clearance on the pull side of the door.	$4,000.00	ADA 404, 404.2.4, MA 26.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Doors	There is no level landing at this door.	Provide a level landing.	$1,500.00	ADA 302, 305, 404, 404.2.4.4, MA 26.6

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room signage.	Install accessible room signage.	$158.00	ADA 216.2, 216.6 , MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Signage	There is no room identification signage.	Install room identification signage.	$158.00	ADA 216, 216.2, 703, MA 41.1

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The height of the urinal rim in the restroom is greater than 17 inches above the finished floor.	Lower the urinal designated to be accessible in the restroom so that the rim height is not more than 17 inches above the finished floor.	$1,397.00	ADA 605, 605.2, MA 30.10.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The knee clearance space under the lavatory is less than the required minimum height.	Raise or replace the lavatory to provide the minimum required knee clearance.	$1,286.00	ADA 213, 306.3.1, 606, 606.2, MA 30.9.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The pipes under the lavatory do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.	$149.00	ADA 213, 606, 606.5, MA 30.9.5

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	Supply lines are not wrapped at the lavatory.	Wrap the supply lines around lavatory according to compliance.	$149.00	ADA 213, 606, 606.5, MA 30.9.5
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The approach is to the latch side of the compartment door, clearance between the door side of the compartment and any obstruction does not meet the minimum required clearance.	Provide clearance between the door side of the compartment and any obstruction that meets the minimum required clearance.	$4,000.00	ADA 404.2, 603, 604.8.1.2, MA 30.6.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	There is no back grab bar at the toilet compartment.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 604.8.1.5, MA 30.8
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be accessible in the restroom.	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The length of the side grab bar is less than required.	Replace the side grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The distance between the wall and the gripping surface of the grab bar does not meet requirements.	Remount the grab bar so the space between the wall and gripping surface meets requirements. Grab bars must be able to support a point load of at least 250 pounds and shall be less than the	$250.00	ADA 505, 604.9.3, 609.3, MA 30.8.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The approach is to the latch side of the compartment door, clearance between the door side of the compartment and any obstruction does not meet the minimum required clearance.	Provide clearance between the door side of the compartment and any obstruction that meets the minimum required clearance.	$4,000.00	ADA 404.2, 603, 604.8.1.2, MA 30.6.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	There is no back grab bar at the toilet compartment.	Install the required grab bars in the toilet compartment.	$267.00	ADA 603, 604.5, 604.8.1.5, MA 30.8
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	There is insufficient clear floor space in the compartment.	Modify or replace the compartment to provide adequate clear floor space.	$4,000.00	ADA 213, 603, 604, 604.8.1.1, MA 30.6.1

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The door to the compartment does not have an accessible handle on both sides.	Provide an accessible handle mounted on the door of the compartment near the latch.	$250.00	ADA 213, 404, 604, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The compartment door is located in front of the water closet.	Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.	$4,000.00	ADA 604.8.1.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	Door does not close automatically.	Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be accessible in the restroom.	$269.00	ADA 404, 604.8, 604.8.1.2, MA 30.6.1, MA 30.6.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The compartment door hardware is not at a compliant height.	Remove and relocate the door hardware.	$269.00	ADA 213, 404, 404.2.7, 604, 604.8, MA 30.6.1, MA 30.6.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The coat hook is not mounted at the correct height.	Mount the coat hook at the recommended height.	$50.00	ADA 308, 308.1, 603.4, MA 30.6.1, MA 30.6.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The length of the side grab bar is less than required.	Replace the side grab bar with a compliant grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The distance between the wall and the gripping surface of the grab bar does not meet requirements.	Remount the grab bar so the space between the wall and gripping surface meets requirements. Grab bars must be able to support a point load of at least 250 pounds and shall be less than the	$250.00	ADA 505, 604.9.3, 609.3, MA 30.8.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The distance from the back wall to the front of the grab bar is less than required.	Install or move the grab bar to create the required distance from the back wall to the front of the grab bar.	$267.00	ADA 603, 604.5.1, 609, MA 30.8
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The distance from the center of the toilet to the nearest side wall does not meet the required distance.	Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.	$2,500.00	ADA 603, 604.2, MA 30.7.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The flush control on the toilet is not on the wide (approach) side of the toilet.	Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.	$127.00	ADA 603, 604.6, MA 30.7.5
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	The toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	Locate the toilet in a space which provides the required clearances.	$2,500.00	ADA 603, 604.2, MA 30.7.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Restrooms	There is less than the required minimum space in front of the toilet.	Create the required minimum clear space in front of the toilet.	$3,500.00	ADA 603, MA 30.6.1, MA 30.7.1

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Assembly Areas	Stairs connect the front of the stage in the theater/auditorium/performing arts center to the audience seating area, the stage is not accessible from a back entrance/ramp/hallway.	Provide a vertical platform lift or other means of vertical access between the level floor seating area and the stage. It is imperative as an ADA mandate to provide access to the stage for individuals	$8,210.00	ADA 219, 221, 706, 802, MA 14.6
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Assembly Areas	There are not enough accessible seats at the location with respect to the total number of seats available.	Provide compliant accessible seating at the location.	$600.00	ADA 221.2 , 802.1
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Break/Conferenc e Room	Sink counter height does not meet the standards.	Provide compliant sink.	$1,800.00	ADA 606.3
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Break/Conferenc e Room	The pipes are not wrapped for the sink.	Insulate or otherwise configure the water supply and drain pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.	$149.00	ADA 606.5
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Break/Conferenc e Room	The toe kick for the sink in break/conference room is not removed.	Remove the toe kick for the sink.	$612.00	ADA 305, 306, 606.2
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Break/Conferenc e Room	There is not enough clear floor space at the sink.	Provide enough clear floor space at the location.	$900.00	ADA 205, 228, 308, 309

West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Break/Conference Room	Supply lines are not wrapped for the break/conference room sink.	Make sure that the supply lines are fully wrapped and insulated for the sink.	$149.00	ADA 606.5
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Break/Conference Room	The height of the controls and operating mechanisms for the dispenser is not at the correct height.	Relocate the dispenser to the correct height.	$110.00	ADA 308, 309, MA 6.5
West Dennis Graded School House - 67 School Street West Dennis, MA 02670	Break/Conference Room	Appliance Reach Height in the break/conference room is not compliant.	Make sure that the specified appliance reach height is compliant.	$1,200.00	ADA 205, 308, 309
				$7,627,126.56	